		· · · · ·
Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District 1</u> – (575) 393-6161	Energy, Minerals and Natural Resourc	es Revised August 1, 2011 WELL API NO.
1625 N: French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		20.015.02000
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	COLL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	1 1 2013 <sup>Santa Fe, NM 87505</sup>	6. State Oil & Gas Lease No.
	BSOCD SAND REPORTS ON WELLS	7 Long Name or Unit Assessment Nome
(DO NOT USE THIS FORM FOR PROPOSAL	S AND REPORTS ON WELLS S TO DRILL OR TO DEEPEN OR PLUG BACK TO A ION FOR PERMIT" (FORM C-101) FOR SUCH	<ul> <li>7. Lease Name or Unit Agreement Name</li> <li>Cave Pool Unit</li> </ul>
PROPOSALS.)	Well Other RECEIV	8. Well Number #19
2. Name of Operator		9. OGKID Number
State of New Mexico formerly Marks	& Garner LTD, Co FEB 11.201	<u>i 14070</u>
3. Address of Operator 1625 N French Drive Hobbs, NM 88	hat the second sec	T 10 Deal games on Wildoot
4. Well Location		U OB, Jackson, 7 KVS, SA, QN
	feet from the South line and	d1980feet from theWestline
Section 4	Township 17S Range	29E NMPM Eddy County
	1. Elevation (Show whether DR, RKB, RT, G	
		· · · · · ·
12. Check App	propriate Box to Indicate Nature of No	otice, Report or Other Data
NOTICE OF INTE		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🗌 🛛 P	LUG AND ABANDON	
—	—	
	IULTIPLE COMPL	EMENT JOB
OTHER:	OTHER:	
		ails, and give pertinent dates, including estimated date
or starting any proposed work). proposed completion or recomp		ple Completions: Attach wellbore diagram of
proposed completion of recomp		
		· · · · · · · · · · · · · · · · · · ·
2/04/2013 Rig up. Lay down rods. Du	ng out cellar and worked on removing wellhe	ad cap.
2/5/2013 Installed BOP and tallied tubi	ng OOH. Make scraper run. RIH and attem	npted to set 4 <sup>1</sup> /2" CIBP at 2302'. Would not set.
Stacked the tubing in the rat hole and tri	ed to get rid of the CIBP. POOH with tubing	g and the CIBP was still on the setting tool but
damaged badly. RIH with tubing and Sl	ON.	
2/5/2013 Spotted 25 sx class c cement	at 2302' and WOC. Tagged cement at 1894	'. Circulated mud. POOH to 1821' and spotted 25 sx
class c cement. Laid down tubing and p	erforated at 376'. Established circulation and	d pumped cement to perfs at 376'. Pumped 175 sx
Class c and never got cement to surface.	Well had good circulation the entire time p	umping cement. SION.
2/6/2013 Cut off well head and "one in	ched" annulus from 60' Filled up 4 ½" casi	ing to surface. Good cement on both sides. Installed
marker and cut off anchors.		
	,	
I handhu gantifuthat tha information of	ve is true and complete to the best of my kno	مر مراجع المراجع ا
Thereby certify that the information abo	ve is true and complete to the best of my kno	owieuge and bener.
6 AN	2R	
SIGNATURE	TITLE	DATE
Type or print name	E-mail address:	PHONE:
For State Use Only	L-man address	FHONE
	$1 / n \cdot 4$	GR DATE 2-11-2013
APPROVED BY:	TITLE STM	DATE -11- LO 13
Conditions of Approval (if any):	<i>,</i>	

APPROVED BY:	17	)	
Conditions of App	oval (I	any):	5