

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-20200
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-997
7. Lease Name or Unit Agreement Name Eddy BD State
8. Well Number 003
9. OGRID Number 13645
10. Pool name or Wildcat WC-015G-07 S203032G; WC

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator
Lynx Petroleum Consultants, Inc.

3. Address of Operator
P.O. Box 1708, Hobbs, NM 88241

4. Well Location

Unit Letter P : 660 feet from the South line and 990 feet from the East line
Section 32 Township 20S Range 30E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER:

OTHER: PLUGBACK TO WOLFCAMP ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PLUGBACK TO WOLFCAMP 11/27/12 to 2/11/13

11/27 to 11/28/12 - MIRU. POOH with rods. ND wellhead. NU BOP. Release TAC. TOOHH with tbq.

11/29/12 - RU wireline. Run and set CIBP @ 10960'. Run GR/CNL/CCL 10965-7400'.

12/3/12 - Load hole with 10#/gal brine. Spot 10 bbs. 15% HCL-NE-FE. Perforate Wolfcamp 1st stage 10-230-35, 10242-54, 10324-26', 10380-86'. Packer @ 9800'. Test tbq. in hole to 5000 psig.

1/21/13 - Spot 250 gals. 15% HCL-NE-FE acid. Set pkr. @ 10112'. Acidize perfs. 10230-386' with 1500 gals. HCL-NE-FE.

2/5/13 - Perforate Wolfcamp 2nd stage 10132-62'. Test tbq. to 8000 psig. Set pkr. @ 10100'. Load and test annulus to 1000 psi.

2/11/13 - Acidize Wolfcamp 2nd stage with 1500 gals. 7 1/2% HCL-NE-FE acid.

Zone is not commercial. Well is shut-in pending approval to plugback to Bone Spring.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debbie McKel TITLE Agent DATE 2/20/13

Type or print name For State Use Only E-mail address: LRDade PHONE:

APPROVED BY LRDade TITLE Dis. H. Sepura DATE 2/21/13

Conditions of Approval (if any):