RECEIVED MAR 1 4 2013

Submit One Copy To Appropriate Outre ARTES AS	plate of New Mexico	Form C-103
District I Energy, N	linerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 811 S. First St., Artesia, NM 88210 OIL CO	NSERVATION DIVISION	30-015-04700
011 5. 1 list 5t., Aitesta, 1414 00210	0 South St. Francis Dr.	5. Indicate Type of Lease
1000 Dio Prozos Dd. Aztec NM 87410		STATE FEE X
District 1 v	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPO	ORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF	l	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM	IIT" (FORM C-101) FOR SUCH	Stovall Wood
PROPOSALS.)		8. Well Number
	Other	
2. Name of Operator		9. OGRID Number
· Vanguar I Permian LLC	<u> </u>	10. Pool name or Wildcat
3. Address of Operator	D 12/20 T 70761	10. Pool name of whiceat
2626 JBS Park way Ste 205	13; Deessa 1x 17/61	Darber: Yates
1.4 Well Location 1		
Unit Letter C: 60 feet from the	line and <u>730</u> feet from the	line
Section 20 Township 205 Rang	e 30 k NMPM Falce County	-
11. Elevation	Show whether DR, RKB/RT, GR, etc.)	
3205	GR	
12. Check Appropriate Box to Indicate Natu	ire of Notice, Report or Other D	ata
		· ·
NOTICE OF INTENTION TO		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND A	_	
TEMPORARILY ABANDON CHANGE PLA	NS 🔲 COMMENCE DRII	LLING OPNS. □ ″ P`AND A
PULL OR ALTER CASING	MPL CASING/CEMENT	
• • • • • • • • • • • • • • • • • • • •		
OTHER:	☐ ☑ Location is re	ady for OCD inspection after P&A
All pits have been remediated in compliance wit		
Rat hole and cellar have been filled and leveled.	Cathodic protection holes have been	properly abandoned.
	Cathodic protection holes have been	properly abandoned.
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas	Cathodic protection holes have been pt 4' above ground level has been set in	properly abandoned. concrete. It shows the
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at least OPERATOR NAME, LEASE NAME, WI	Cathodic protection holes have been per 4' above ground level has been set in ELL NUMBER, API NUMBER, QU	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at least OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU, AND RANGE. All INFORMATIO	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at least OPERATOR NAME, LEASE NAME, WI	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU, AND RANGE. All INFORMATIO	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at least OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE M	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU, AND RANGE. All INFORMATIONARKER'S SURFACE.	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at least OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE M The location has been leveled as nearly as possib	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU, AND RANGE. All INFORMATIONARKER'S SURFACE.	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at least OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE M The location has been leveled as nearly as possible other production equipment.	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU., AND RANGE. All INFORMATIOMARKER'S SURFACE.	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at least OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE M The location has been leveled as nearly as possib other production equipment. Anchors, dead men, tie downs and risers have be	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION MARKER'S SURFACE. The solution of the continuation of	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level.
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at least OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE M The location has been leveled as nearly as possible other production equipment. Anchors, dead men, tie downs and risers have be lif this is a one-well lease or last remaining well of	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU., AND RANGE. All INFORMATION HARKER'S SURFACE. The substitution of the substitution of the substitution of the substitution of the substitution has been cut off at least two feet below ground lease, the battery and pit location(s)	ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at least OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE M The location has been leveled as nearly as possib other production equipment. Anchors, dead men, tie downs and risers have be If this is a one-well lease or last remaining well of OCD rules and the terms of the Operator's pit permit	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU., AND RANGE. All INFORMATION HARKER'S SURFACE. The substitution of the substitution of the substitution of the substitution of the substitution has been cut off at least two feet below ground lease, the battery and pit location(s)	ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at least OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE M The location has been leveled as nearly as possible other production equipment. Anchors, dead men, tie downs and risers have been leveled as nearly as possible of the production of the downs and risers have been leveled as nearly as possible of the second of the downs and risers have been leveled as nearly as possible of the second of the downs and risers have been leveled as nearly as possible of the second of the sec	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU., AND RANGE. All INFORMATION TARKER'S SURFACE. The continuation of the continuation of the continuation lease, the battery and pit location(s) and closure plan. All flow lines, product the continuation of the continuation	ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE N The location has been leveled as nearly as possib other production equipment. Anchors, dead men, tie downs and risers have be If this is a one-well lease or last remaining well of OCD rules and the terms of the Operator's pit permit from lease and well location. All metal bolts and other materials have been rem	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU., AND RANGE. All INFORMATION TARKER'S SURFACE. The continuation of the continuation of the continuation lease, the battery and pit location(s) and closure plan. All flow lines, product the continuation of the continuation	ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE NOTICE TO THE NAME Anchors, dead men, tie downs and risers have be If this is a one-well lease or last remaining well of OCD rules and the terms of the Operator's pit permit from lease and well location. All metal bolts and other materials have been rem to be removed.)	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION TARKER'S SURFACE. The continuation of the continuatio	ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE N The location has been leveled as nearly as possib other production equipment. Anchors, dead men, tie downs and risers have be lf this is a one-well lease or last remaining well occording to the operator's pit permit from lease and well location. All metal bolts and other materials have been rem to be removed.) All other environmental concerns have been add.	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU, AND RANGE. All INFORMATION TARKER'S SURFACE. The continuation of the continuatio	ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed aved. (Poured onsite concrete bases do not have
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LEASE NA	Cathodic protection holes have been pt 4' above ground level has been set in ELL NUMBER, API NUMBER, QU, AND RANGE. All INFORMATION TARKER'S SURFACE. The continuation of the continuatio	ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed aved. (Poured onsite concrete bases do not have
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WI UNIT LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE N The location has been leveled as nearly as possib other production equipment. Anchors, dead men, tie downs and risers have be If this is a one-well lease or last remaining well of OCD rules and the terms of the Operator's pit permit from lease and well location. All metal bolts and other materials have been rem to be removed.) All other environmental concerns have been add. Pipelines and flow lines have been abandoned in	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION TARKER'S SURFACE. The to original ground contour and has been cut off at least two feet below ground no lease, the battery and pit location(s) and closure plan. All flow lines, production. Portable bases have been removed.	ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed and level. All fluids have been removed from non-
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LEASE NA	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION TARKER'S SURFACE. The continuation of the continuatio	ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed and level. All fluids have been removed from non-
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LEASE NA	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION ARKER'S SURFACE. The continuation of the continuation of the least two feet below ground not lease, the battery and pit location(s) and closure plan. All flow lines, producted. Portable bases have been removed.	ARTER/QUARTER LOCATION OR NHAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed aved. (Poured onsite concrete bases do not have All fluids have been removed from non- l lines have been removed from lease and well
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LEASE NA	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION ARKER'S SURFACE. The continuation of the continuation of the least two feet below ground not lease, the battery and pit location(s) and closure plan. All flow lines, producted. Portable bases have been removed.	ARTER/QUARTER LOCATION OR NHAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed aved. (Poured onsite concrete bases do not have All fluids have been removed from non- l lines have been removed from lease and well
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LEASE NA	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION MARKER'S SURFACE. The content of the least two feet below ground and closure plan. All flow lines, production oved. Portable bases have been removed. Portable bases have been remo	ARTER/QUARTER LOCATION OR NHAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed aved. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection.
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE NOTE of the production equipment. Anchors, dead men, tie downs and risers have been leveled as nearly as possible of the production equipment. Anchors, dead men, tie downs and risers have been leveled as nearly as possible of the operator's pit permit from lease and the terms of the Operator's pit permit from lease and well location. All metal bolts and other materials have been rem to be removed.) All other environmental concerns have been addressed flow lines and pipelines. If this is a one-well lease or last remaining well of location, except for utility's distribution infrastructure. When all work has been completed, return this form to	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION MARKER'S SURFACE. The content of the least two feet below ground and closure plan. All flow lines, production oved. Portable bases have been removed. Portable bases have been remo	ARTER/QUARTER LOCATION OR NHAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed aved. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection.
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE NOTE of the production equipment. Anchors, dead men, tie downs and risers have been leveled as nearly as possible other production equipment. Anchors, dead men, tie downs and risers have been lease and the terms of the Operator's pit permit from lease and well location. All metal bolts and other materials have been rem to be removed.) All other environmental concerns have been add Pipelines and flow lines have been abandoned in retrieved flow lines and pipelines. If this is a one-well lease or last remaining well of location, except for utility's distribution infrastructure. When all work has been completed, return this form to SIGNATURE.	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION MARKER'S SURFACE. The content of the least two feet below ground and closure plan. All flow lines, production oved. Portable bases have been removed. Portable bases have been remo	ARTER/QUARTER LOCATION OR NHAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed aved. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection.
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE NOTE of the production equipment. Anchors, dead men, tie downs and risers have been leveled as nearly as possible other production equipment. Anchors, dead men, tie downs and risers have been lease and the terms of the Operator's pit permit from lease and well location. All metal bolts and other materials have been rem to be removed.) All other environmental concerns have been add Pipelines and flow lines have been abandoned in retrieved flow lines and pipelines. If this is a one-well lease or last remaining well of location, except for utility's distribution infrastructure. When all work has been completed, return this form to SIGNATURE.	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION MARKER'S SURFACE. The content of the least two feet below ground and closure plan. All flow lines, production oved. Portable bases have been removed. Portable bases have been remo	ARTER/QUARTER LOCATION OR NHAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed aved. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection.
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE NOTE of the production equipment. Anchors, dead men, tie downs and risers have been leveled as nearly as possible other production equipment. Anchors, dead men, tie downs and risers have been lease and the terms of the Operator's pit permit from lease and well location. All metal bolts and other materials have been rem to be removed.) All other environmental concerns have been add Pipelines and flow lines have been abandoned in retrieved flow lines and pipelines. If this is a one-well lease or last remaining well of location, except for utility's distribution infrastructure. When all work has been completed, return this form to SIGNATURE.	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION MARKER'S SURFACE. The content of the least two feet below ground and closure plan. All flow lines, production oved. Portable bases have been removed. Portable bases have been remo	ARTER/QUARTER LOCATION OR NHAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed aved. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection.
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAMS SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE NOTE of the production equipment. Anchors, dead men, tie downs and risers have been leveled as nearly as possible other production equipment. Anchors, dead men, tie downs and risers have been leveled as nearly as possible of the operator's pit permit from lease and well lease or last remaining well of OCD rules and the terms of the Operator's pit permit from lease and well location. All metal bolts and other materials have been rem to be removed.) All other environmental concerns have been abandoned in retrieved flow lines and pipelines. If this is a one-well lease or last remaining well of location, except for utility's distribution infrastructure. When all work has been completed, return this form to SIGNATURE. TYPE OR PRINT NAME. M. Blockworth. For State Use Only	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION MARKER'S SURFACE. The content of the least two feet below ground and closure plan. All flow lines, production oved. Portable bases have been removed. Portable bases have been remo	ARTER/QUARTER LOCATION OR NHAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed aved. (Poured onsite concrete bases do not have All fluids have been removed from non-lines have been removed from lease and well edule an inspection.
Rat hole and cellar have been filled and leveled. A steel marker at least 4" in diameter and at leas OPERATOR NAME, LEASE NAME, WILLIAM LETTER, SECTION, TOWNSHIP PERMANENTLY STAMPED ON THE NOTE of the production equipment. Anchors, dead men, tie downs and risers have been leveled as nearly as possible other production equipment. Anchors, dead men, tie downs and risers have been lease and the terms of the Operator's pit permit from lease and well location. All metal bolts and other materials have been rem to be removed.) All other environmental concerns have been add Pipelines and flow lines have been abandoned in retrieved flow lines and pipelines. If this is a one-well lease or last remaining well of location, except for utility's distribution infrastructure. When all work has been completed, return this form to SIGNATURE.	Cathodic protection holes have been to 4' above ground level has been set in ELL NUMBER, API NUMBER, QU. AND RANGE. All INFORMATION MARKER'S SURFACE. The content of the least two feet below ground and closure plan. All flow lines, production oved. Portable bases have been removed. Portable bases have been remo	properly abandoned. concrete. It shows the ARTER/QUARTER LOCATION OR ON HAS BEEN WELDED OR Deen cleared of all junk, trash, flow lines and and level. have been remediated in compliance with action equipment and junk have been removed and level. (Poured onsite concrete bases do not have All fluids have been removed from non- I lines have been removed from lease and well edule an inspection. DATE 03-11-2017