District I - (575) 393-6161	State of New Me		Form C-103
1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION		Revised August 1, 2011 WELL APLNO.
<u>District II</u> – (575) 748-1283			30-015-24760
911 S. First St., Artesia, NM 88210 <u>istrict III</u> – (505) 334-6178	1220 South St. Fran		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	·		
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	S	7. Lease Name or Unit Agreement Name
	DSALS TO DRILL OR TO DEEPEN OR PL ICATION FOR PERMIT" (FORM Ç-101) FO		DIAMOND STATE
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other		8. Well Number #2
2 Name of Operator	extro formerly MARKS	S & GARNER	9. OGRID Number 14-070
3. Address of Operator			10. Pool name or Wildcat
811 S. FIRST ST 4. Well Location	. HEICSTH, NIN	80210	JACKSON TRUS ON GB SA
Unit Letter M :	330 feet from the 5007	TH line and	190 feet from the WEST line
Section 4	Township 175 R	ange 29E	NMPM County EDBY
The second second	11. Elevation (Show whether DR	R, RKB, RT, GR, etc.	
12. Check	Appropriate Box to Indicate N	Nature of Notice,	Report or Other Data
NOTICE OF IN	NTENTION TO:	9119	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	 -
> DOWNHOLE COMMINGLE □			
OTHER:	П	OTHER:	П
	pleted operations. (Clearly state all		d give pertinent dates, including estimated dat
		C. For Multiple Co	mpletions: Attach wellbore diagram of
proposed completion or re	completion.		
SEE ATT	ACHED PLUGGING	C PROCEDI	(1 Q F
SEE ATT.	ACHED PLUGGING	G PROCED!	<u>URE</u>
SEE ATT.	ACHED PLUGGING	G PROCED)	<u>URE</u>
SEE ATT.	ACHED PLUGGING	G PROCED!	<u>URE</u>
SEE ATT.	ACHED PLUGGING	G PROCED	<u>URE</u>
			<u>URE</u>
SEE ATT.	ACHED PLUGGING Rig Release D		<u>URE</u>
			<u>URE</u>
Spud Date:	Rig Release D	Date:	
Spud Date:		Date:	
Spud Date: Thereby certify that the information	Rig Release D	Date:	ge and belief.
Spud Date:	Rig Release D	Date:	
Spud Date: Thereby certify that the information SIGNATURE	Rig Release Donato above is true and complete to the beauty TITLE	pest of my knowleds	ge and belief.
Spud Date: I hereby certify that the information SIGNATURE De or print name	Rig Release D	pest of my knowleds	ge and belief.
Spud Date: Thereby certify that the information of the second of the se	Rig Release Donato above is true and complete to the beauty TITLE	pest of my knowleds	ge and belief. PHONE:
Spud Date: Thereby certify that the information of the second of the se	Rig Release Donato above is true and complete to the beauty TITLE	pest of my knowleds	ge and belief. Office DATE 1/28/2013
Spud Date: Thereby certify that the information of the second of the se	Rig Release Donato above is true and complete to the beauty TITLE	pest of my knowleds	ge and belief. PHONE:
pud Date: hereby certify that the information IGNATURE pe or print name or State Use Only PPROVED B	Rig Release Donato above is true and complete to the beauty TITLE	pest of my knowleds	ge and belief. PHONE:

_

State of New Mexico formerly MA	RKS & GARNER PRODUC	TION LTD CO		
LEASE NAME DIAMOND	STATE # 2	API 30-0 15 - 24760		
Section 4 -T 17 S-R 29 E FROM 330 A/S L, 990 1/W L.				

SPECIAL NOTE—Mud Laden Fluid will consist of 9.5# brine with 12.5# Salt Gel per BBL (25 sacks of gel/ per 100 BBLS Brine). All cement plugs will be 25 sacks of cement or 100', whichever is greater. Unless otherwise specified in the approved procedure, cement plugs shall consist of class "C" for depths to 7500'. Class "H" will be used for plugs deeper than 7500'.

- 1. MIRU plugging unit. Lay down production equipment. SPOT CMT. Woc. TAG. 2. Set CIBP @2400-3110. Circulate MLF. Spot 25 sxs cmt on CIBP.
- 3. Perf/ Spot 25 sxs cmt @ 1850 '. If perf. WOC and TAG.
- 4. Perf/Spot @ **390** / Sqz w/ sufficient volume to circ cmt to surface inside/outside of csg strings.
- 5. Cutoff wellhead and anchors, install marker.

-SPECIAL NOTES-----

PLUGGING & ABANDONMENT WORKSHEET (3 STRING CSNG) **OPERATOR** LEASENAME WELL # 12/4 HOLE NWT SECT RNG N/S L EWL **FROM** FORMATION @ TD TD: FORMATION @ PBTD PBTD: 85/8 24# TOC TOC DETERMINED BY SIZE SET @ SURFACE @ 340 INTMED 1 TOC SURF INTMED 2 SURF PROD PERF® 390' TOP BOT TOC DETERMINED BY SIZE LINER 1 LINER 2 CUT & PULL @ TOP - BOTTOM 5/2 15.5 INTMED 1 PERFS INTMED 2 OPENHOLE PROD * REQUIRED PLUGS DISTRICT I CRT PLUG TYPE SACKS DEPTH RUSTLER (ANITYD) PLUG CMNT EXAMPLES QUEEN 255x5@ 1850' OH 25 SXS 9850 PLUUS I DRAYBURG 50 SXS 8700'-8800' rw#2 SHOE SAN ANDRES erma es CIBP/35' 5300" CIBP 25 SXS 5300 CAPITAN REEF PLUO#3 PEÙO I 4 STUB 50 SXS 4600'-4700' 2476-2485 REINR SQZ 200 SXS 400 ' PLUX386 DELAWARE 2574 SURF 10 EXE 0-10 rw0#7 BELL CARTOR PLUUS AL CHEERY CARYON FL00#2 BELLERY CARYON PLUUIS SOME SPECING PLUG#4 @ 3110 ATHINOLE ELWI E S BLINEBRY PERSONAL 6 PLUGET PLUCER ORINICARD 0 B EXL39 NDO. PEUCI 8 10 WC. PEUDF PLUUS # NWARTE ATOKA WOULSOLD TD 3111 . MITTE NATHOYEO IN 512 2476-2485 ORIGINAL PERFS

31/2 RAN.

UNKNOWN

PERFS

Considerations for Plugging Quote Bid

- 1. Inspections of roads and locations that may require repair to get equipment to/from job site.
- 2. Inspections, testing or installation of anchors.
- 3. Rental equipment that may be required for job.
- 4. Fresh and brine water requirements for plugging.
- 5. Removal of liquids and solids to approved disposal site.
- 6. Other expenses that may be required to complete job.
- 7. Provide daily estimate cost to District office.
- 8. Upon completion of plugging file C-103 subsequent report with OCD. This is to include cement volumes, cement tags and date well was plugged.
- 9. Provide District office final invoice for approval.

This is not a complete list but a guideline to help in the bid process.