

Submit 1 Copy To Appropriate District  
Office

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

WELL API NO. 30-015-02902
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Cave Pool Unit
8. Well Number #23
9. OGRID Number 14070
10. Pool name or Wildcat GB, Jackson, 7 RVS, SA, QN
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator State of New Mexico formerly Marks & Garner LTD, Co	
3. Address of Operator 1625 N French Drive Hobbs, NM 88240	
4. Well Location Unit Letter <u>K</u> :1980 feet from the <u>North</u> line and <u>2310</u> feet from the <u>West</u> line Section <u>5</u> Township <u>17S</u> Range <u>29E</u> NMPM <u>Eddy</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1/31/2013 Rig up. Lay down rods. Install BOP. POOH with tubing and tallied. Moved in remaining equipment

2/1/2013 Make scraper run. RIH and set 5 1/2" CIBP at 2294'. Circulated with mud. Spotted 25 sx class c cement on top. POOH and spot 25 sx class c cement at 1814'. POOH and SION.

2/4/2013 RIH & perforate at 307'. Pumped class c cement down 5 1/2" casing to perfs and up 5 1/2" X 8 5/8" annulus to surface. Took 140 sx to circulate. Should have taken approximately 85-90 sx. Rigged down. Cut off wellhead, installed marker and cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE MB TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_

For State Use Only

APPROVED BY: E. Gonzalez TITLE Dist. Mgr DATE 2-4-2013

Conditions of Approval (if any):

dm