Form 3160-5 (August 2007)

پيتا د د لاريز

OCD Artesia

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					MultipleSee Attached			
					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. 8920002760			
Type of Well Gas Well □ Other					Well Name and No. MultipleSee Attached			
2. Name of Operator Contact: TERRY B CALLAHAN LINN OPERATING INCORPORATED E-Mail: tcallahan@linnenergy.com					API Well No. MultipleSee Attached			
3a. Address 3b. Phone No. 600 TRAVIS STREET SUITE 5100 Ph: 281-84 HOUSTON, TX 77002 Fx: 281-60			ide area code) 72 5		10. Field and Pool, or Exploratory GRAYBURG GRAYBURG JACKSON			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State			
MultipleSee Attached				EDDY COUNTY, NM				
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION	TYPE OF ACTION				·			
☑ Notice of Intent ☐ Acidize		Deepen		☐ Production (Start/Resume)		_	er Shut-Off	
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat		☐ Reclamation		_	Integrity	
	Casing Repair	□ New Con				☑ Othe Venting	r g and/or Flari	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and . ☐ Plug Back	_	☐ Temporarily Abandon ☐ Water Disposal		ng		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) LINN WOULD LIKE TO REQUEST TO FLARE FOR 90 DAYS FROM THE NMNM98122. THE FLARING IS REQUIRED DUE TO THE FRONTIER GAS PLANT EXPERIENCING A LOW PRESSURE UNIT OUT. API Well Name Well Number 30-015-05335 SKELLY UNIT #005 30-015-05326 SKELLY UNIT #006 30-015-05327 SKELLY UNIT #007 30-015-05328 SKELLY UNIT #007 30-015-05323 SKELLY UNIT #011 30-015-05323 SKELLY UNIT #014 30-015-05322 SKELLY UNIT #014 30-015-05322 SKELLY UNIT #014 30-015-05322 SKELLY UNIT #015 SUBJECT TO LIKE APPROVAL BY STATE SUBJECT TO LIKE APPROVAL BY STATE								
14. I hereby certify that the foregoing is	Electronic Submission # For LINN OPERA	TING INCORPORAT	ED, sent to the	e Carlsbad	_	CD		
	itted to AFMSS for proces CALLAHAN	sing by JOHNNY DI			(13JLD0505SE) CIALIST III			
Name (17 mean 1) peay 1 LINN B	OALLAHAM	1100	TILOULAT	OKT SEL	CIALIST III		_ .	
Signature (Electronic S		Date						
	THIS SPACE FO	OR FEDERAL O	R STATE OF	FFICE N	PROVED		····	
Approved By JERRY BLAKLEY Conditions of approval, if any, are attached entify that the applicant holds legal of equivalent would entitle the applicant to conduct the surface of the surfa	d. Approval of this notice does hitably title to those rights in the ct operations thereon. U.S.C. Section 1212, make it a	not warrant or e subject lease Off	ice Carlsbad		PR 2 7 2013		te 04/27/2013	
States any false, fictitious of fraudulent s	tatements or representations as	to any matter within it	s jurisdiction.	STATE AU	L SRAD FIFLD OFFIC	E		

Additional data for EC transaction #204002 that would not fit on the form

5. Lease Serial No., continued

NMLC029419A NMLC029420A NMNM98122

Wells/Facilities, continued

Agreement	Lease	Well/Fac Name, Number	API Number	Location
NMNM71030A	NMNM98122	SKELLY UNIT 11	30-015-05330-00-D1	Sec 21 T17S R31E NESE 1980FSL 660FEL
NMNM71030A	NMNM98122	SKELLY UNIT 11	30-015-05330-00-D2	Sec 21 T17S R31E NESE 1980FSL 660FEL
NMNM71030A	NMLC029419A	SKELLY UNIT 116	30-015-21090-00-D2	Sec 22 T17S R31E NWSW 1330FSL 130FWL
NMNM71030A	NMLC029419A	SKELLY UNIT 117	30-015-22251-00-S1	Sec 22 T17S R31E NESW 1980FSL 1880FWL
NMNM71030A	NMLC029419A	SKELLY UNIT 125	30-015-22259-00-S1	Sec 22 T17S R31E SWNW 1980FNL 560FWL
NMNM71030A	NMLC029420A	SKELLY UNIT 126	30-015-22260-00-S1	Sec 15 T17S R31E SWSW 560FSL 760FWL
NMNM71030A	NMNM98122	SKELLY UNIT 129	30-015-22263-00-S1	Sec 21 T17S R31E NENE 660FNL 760FEL
NMNM71030A	NMNM98122	SKELLY UNIT 13	30-015-05323-00-S1	Sec 21 T17S R31E NESW 1980FSL 1980FWL
NMNM71030A	NMNM98122	SKELLY UNIT 14	30-015-05322-00-S1	Sec 21 T17S R31E NWSW 1980FSL 660FWL
NMNM71030A	NMNM98122	SKELLY UNIT 15	30-015-05332-00-S1	Sec 21 T17S R31E SWSW 760FSL 660FWL
NMNM71030A	NMNM98122	SKELLY UNIT 220	30-015-28892-00-S1	Sec 21 T17S R31E SENW 1330FNL 1400FWL
NMNM71030A	NMNM98122	SKELLY UNIT 221	30-015-28893-00-S1	Sec 21 T17S R31E SWNE 1390FNL 2530FEL
NMNM71030A	NMNM98122	SKELLY UNIT 222	30-015-28894-00-S1	Sec 21 T17S R31E SENE 1380FNL 1300FEL
NMNM71030A	NMNM98122	SKELLY UNIT 223	30-015-28964-00-\$1	Sec 21 T17S R31E SENE 1340FNL 120FEL
NMNM71030A	NMNM98122	SKELLY UNIT 233	30-015-29181-00-S1	Sec 21 T17S R31E SENW 2620FNL 1343FWL
NMNM71030A	NMNM98122	SKELLY UNIT 234	30-015-28783-00-S1	Sec 21 T17S R31E NESW 2602FSL 2562FWL
NMNM71030A	`NMNM98122	SKELLY UNIT 235	30-015-28784-00-S1	Sec 21 T17S R31E NWSE 2600FSL 1470FEL
NMNM71030A	NMNM98122	SKELLY UNIT 246	30-015-29063-00-S1	Sec 21 T17S R31E SWSW 1306FSL 1216FWL
NMNM71030A	NMNM98122	SKELLY UNIT 247	30-015-28788-00-\$1	Sec 21 T17S R31E SESW 1110FSL 2515FWL
NMNM71030A	NMNM98122	SKELLY UNIT 248	30-015-28810-00-S1	Sec 21 T17S R31E SESE 1240FSL 1190FEL
NMNM71030A	NMNM98122	SKELLY.UNIT 502	30-015-37006-00-S1	Sec 21 T17S R31E NWNW 1310FNL 560FWL
				32.823710 N Lat, 103.881499 W Lon
NMNM71030A	NMNM98122	SKELLY UNIT 503	30-015-37008-00-S1	Sec 21 T17S R31E NENW 1310FNL 1980FWL
		•	•	32.823716 N Lat, 103.876855 W Lon
NMNM71030A	NMNM98122	SKELLY UNIT 5	30-015-05335-00-S1	Sec 21 T17S R31E NENW 330FNL 1650FWL
				32.826408 N Lat, 103.877943 W Lon

32. Additional remarks, continued

30-015-21090 SKELLY UNIT #116 30-015-22251 SKELLY UNIT #117 30-015-22259 SKELLY UNIT #125 30-015-22260 SKELLY UNIT #126 30-015-22263 SKELLY UNIT #129 30-015-28892 SKELLY UNIT #220 30-015-28893 SKELLY UNIT #221 30-015-28894 SKELLY UNIT #222 30-015-28964 SKELLY UNIT #223 30-015-29181 SKELLY UNIT #233 30-015-28783 SKELLY UNIT #234 30-015-28783 SKELLY UNIT #235 30-015-28784 SKELLY UNIT #235 30-015-29063 SKELLY UNIT #246 30-015-28788 SKELLY UNIT #247 30-015-28810 SKELLY UNIT #248 30-015-37006 SKELLY UNIT #502 30-015-37008 SKELLY UNIT #503

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

4/27/2013 Condition of Approval to Flare Gas

- 1. Report all volumes on OGOR reports.
- 2. Comply with NTL-4A requirements
- 3. Subject to like approval from NMOCD
- 4. Flared volumes will still require payment of royalties
- 5. Install gas meter on vent/flare line to measure gas prior to venting/flaring operations if it is not equipped as such at this time. Gas meter to meet all requirements for sale meter as Federal Regulations and Onshore Order #5.
- 6. This approval does not authorize any additional surface disturbance.
- 7. Submit updated facility diagram as per Onshore Order #3.
- 8. Approval not to exceed 90 days for date of approval.
- 9. Submit Subsequent Report with actual volumes of gas flared for each month gas is flared.
- 10. If flaring is still required past 90 days submit new request for approval.