•	Submit 1 Copy To Appropriate District Office	State	of New Mexi	ico			Form (C-103	
	<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO.					
	1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OH GOME	73.7.4.07.03.7.F	WW.	30-015-21887				
	811 S. First St., Artesia, NM 88210	OIL CONSE		f	5. Indicate Type of Lease				
	<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410		uth St. Franc		STATE ☐ FEE ⊠				
	<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505			6. State Oil & Gas Lease No.				
	1220 S. St. Francis Dr., Santa Fe, NM 87505							,	
	SUNDRY NOTICES AND REPORTS ON WELLS O NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name or Unit Agreement Name				
1	DIFFERENT RESERVOIR. USE "APPL"				Morris Es				
1	PROPOSALS.)	_ ` ` `				8. Well Number 4			
1. Type of Well: Oil Well Gas Well Oth			ther		9. OGRID Number				
	Name of Operator ates Petroleum Corporation				025575				
ľ	3. Address of Operator	ress of Operator				10. Pool name or Wildcat			
Į	05 South Fourth Street, Artesia, NM 88210					Eagle Creek; San Andres			
1	4. Well Location	1650 6 46 41	G1	1. 1	200		***		
	Unit Letter L :	1650 feet from the	South			eet from the	West	line	
200	Section 14	Township 11. Elevation (Show	17S Rang		NMPM	Eddy (County		
0.00		11. Elevation (Snow	wneiner DK, K 3496'G						
12			3.50 3						
	12. Check	Appropriate Box to	Indicate Nat	ure of Notice, I	Report or	Other Data			
	NOTICE OF I	NTENTION TO	ţ	CLID	י פרטוורג		OF.		
	PERFORM REMEDIAL WORK	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
	PERFORM REMEDIAL WORK \square PLUG AND ABANDON $oxtimes$ REMEDIAL WORK \square ALTERING CASING [TEMPORARILY ABANDON \square CHANGE PLANS \square COMMENCE DRILLING OPNS. \square P AND A								
	PULL OR ALTER CASING			CASING/CEMENT			,,		
	DOWNHOLE COMMINGLE					_			
	OTHER)					
-	OTHER: 13. Describe proposed or com	nlated operations (Cla		OTHER:	aivo nortin	ant datas inalu	dina actima	tod dota	
	of starting any proposed w								
	proposed completion or re			i or manipro con	·P · · · · · · · · · · · · · · · · · ·		anagram or		
,	Vatas Datuslavius Camanustian ulana	to also and about on the	.:11 £-11		4,**				
	Yates Petroleum Corporation plans	to plug and abandon th	us well as follov	VS:					
]	1. MIRU any safety equipment as i	needed. NU BOP. TO	H with producti	on equipment.					
	2. RIH with bit and scraper to just								
	you are unable to get below the per	fs then TOH and TBIH	with CIBP and	set above perfs at	1230' befo	re circulating ce	ement to 50	0' (90	
	sx). 3. Cut off wellhead and verify that	there is cement behind	all casing string	s at surface. If so	cement to	surface with 60	sx If not	then	
	RU wireline unit, perforate and circ								
	casing.			CONDITIONS O	F APPROVA	AL ATTACHED	-		
	4. Install dry hole marker and clear	1 location.		A	~		FIVE	D	
1	Wellbore schematics attached			Approval Gran	ited provid	ding work is	pages a m		
_				Completed by	Ann	JANIY	3 0 201	3	
1	NOTE: Yates Petroleum Corporati	on will use steel pits a	nd no earth pits		/ U A	0011	ART!	ESIA	
Approved for plugging of well have the Liability under bond is retained pending receipt					1 2 / NI KII	9:41			
S	Spud Date:	R	ig Release Date	of C-103 (Subse	quent Report	of Well Plugging)			
				Forms, www.cms					
_	handry contify that the infamination	s above is two and some		Maritin Marita			!		
ł	hereby certify that the information	above is true and com	piete to the best	of my knowledge	and belief.				
S	SIGNATURE (In Hui	TT	ITLE <u>Regula</u>	tory Reporting Su	pervisor	DATE _ July 2	<u>26, 2013</u>		
ำ	Type or print name Tipe Hy	uanta E mail	adduaga, timal	- O-voto		DHONE. 52	75 740 416	0	
	Type or print name <u>Tina Hu</u> For State Use Only	cita E-mail	address: <u>tinal</u>	n@yatespetroleum	<u>.com</u>	PHONE:57	75-748-416	<u>o</u> .	
	- 20		ا	,		Λ	0 =		
F	APPROVED BY: Approval (if any):		ITLE ().ST A	spewis n		DATE/124	2,201	3	
(Conditions of Approval (if any):	SEE AH	Ached C	OP's					
	· · · · · · · · · · · · · · · · · · ·	• •	_						

Location: 1650' FSL & 990' FWL Sec 14-17S-25E


County: Eddy State: New Mexico
GL: 3,496' Zero: KB:

Spud Date: 8/13/1976 Completion Date: 8/26/1976

BEFORE

Comments: API # 30-015-218870000

Casing Program					
Size/Wt/Grade	Depth Set				
10 ¾" 40# K-55	356'				
7" 23# K-55	1,154'				
4½" 9.5# & 5½" 14# K-55	1,455'				
	:				



DATE: 6/6/2013

Well Name: Morris Estate CC #4 Field: Eagle Creek


Location: 1650' FSL & 990' FWL Sec 14-17S-25E

County: Eddy State: New Mexico
GL: 3,496' Zero: KB:

Spud Date: 8/13/1976 Completion Date: 8/26/1976

Comments: API # 30-015-218870000

AFTER



Casing Program					
Size/Wt/Grade	Depth Set				
10 ¾" 40# K-55	356'				
7" 23# K-55	1,154'				
4 ½" 9.5# & 5 ½" 14# K-55	1,455'				
	:				

7" csg @ 1,154' cmtd w/ 700 sx.

6 1/4" hole

San Andres perfs 1,311'-1,431' (26)

PBTD 1,455'

 $4\,\%$ " & 5 % " csg @ 1,455' cmtd w/ 150 sx.

TD 1,499'

DATE: 6/6/2013

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Yeles Petroleum Corp Well Name & Number: MOINS Estate CC #4 API#: 30-015-21887

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: Aug 2,2013

APPROVED BY: DOOL

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub
 plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).