Submit 1 Copy To Appropriate DistrictState of New MexicoFornOfficeDistrict 1 - (575) 393-6161Energy, Minerals and Natural ResourcesRevised July	n C-103
1625 N. French Dr., Hobbs, NM 88240 WELL API NO.	<u>, </u>
District II – (575) 748-1283 811 S. First St. Artesia NM 88210 OIL CONSERVATION DIVISION	
5. Indicate Type of Lease	- I
1000 Rio Brazos Rd., Aztec, NM 87410	<u></u>
District IV - (505) 476-3460 Salita 1°C, INIVI 67505 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 6. State Oil & Gas Lease No.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreemen	t NI
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreemen (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	t Maine
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH STATE CF	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other 8. Well Number 7	
2. Name of Operator 9. OGRID Number	
LEGACY RESERVES OPERATING LP 240974	
3. Address of Operator 10. Pool name or Wildcat	
PO BOX 10848, MIDLAND, TX 79702 CHISUM; DEVONIAN	
4. Well Location	1.
Unit Letter J : 2263 feet from the <u>SOUTH</u> line and <u>1430</u> feet from the <u>EAST</u>	line
Section 13 Township 11S Range 27E NMPM County CH	IAVES
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3752.5' GR	ಹಾರ್ಯಾಥ್ರಾ (ಬಿಡು ಗ್ರಾಹಾ
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB I	
CLOSED-LOOP SYSTEM	
	57
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estin	mated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram	mated date
	mated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	mated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram	mated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	mated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	mated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION.	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION.	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION. RECEIVE SEP 2 3 2013	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION.	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION. RECEIVE SEP 2 3 2013	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION. RECEIVE SEP 2 3 2013 NMOCD ARTE	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION. RECEIVE SEP 2 3 2013	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION. RECEIVE SEP 2 3 2013 NMOCD ARTE	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION.	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION.	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION. RECEIVE SEP 2 3 2013 NMOCD ARTE Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief.	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION.	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION.	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION.	mated date of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. 08/26/13 – INSTALL NEW WELLHEAD AND RETURN WELL TO PRODUCTION.	mated date of