Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS		VTERIOR	OMB	M APPROVED NO. 1004-0135 ss: July 31, 2010	
			5. Lease Serial No. NMNM100324	4	
Do not use this form for proposals to drill or to re-er abandoned well. Use form 3160-3 (APD) for such pro					
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Ag	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Gas Well Other				8. Well Name and No. PARKS FEDERAL COM 2	
2. Name of Operator Contact: CHLOE ALEXANDER CIMAREX ENERGY CO E-Mail: cdalexander@cimarex.com			9. API Well No. 30-015-39186	9. API Well No. 30-015-39186	
3a. Address3b. Phone No. (include area code)600 N MARIENFELD ST, STE. 600Ph: 432-571-7800MIDLAND, TX 79701Ph: 432-571-7800			e) 10. Field and Pool, BONE SPRIN	10. Field and Pool, or Exploratory BONE SPRING WILDCAT	
4. Location of Well (Footage, Sec.	, T., R., M., or Survey Description)	· ·	11. County or Parish, and State		
Sec 9 T25S R26E Mer NMF	990FSL 330FEL		EDDY COUN	TY, NM	
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	1	TYPE O	TYPE OF ACTION		
Notice of Intent	🗖 Acidize	Deepen	Production (Start/Resume)	□ Water Shut-Off	
_	Alter Casing	Fracture Treat	Reclamation	🗖 Well Integrity	
Subsequent Report	Casing Repair	New Construction	□ Recomplete	🛛 Other Change to Original A	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	PD	
If the proposal is to deepen directi	onally or recomplete horizontally, g	give subsurface locations and meas	Water Disposal Gate of any proposed work and appr ured and true vertical depths of all per	tinent markers and zones.	
If the proposal is to deepen directi Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for	Deration (clearly state all pertinent onally or recomplete horizontally, g work will be performed or provide t ved operations. If the operation rest Abandonment Notices shall be file r final inspection.)	t details, including estimated startin give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rec d only after all requirements, inclu-	ng date of any proposed work and appr ured and true vertical depths of all per A. Required subsequent reports shall completion in a new interval, a Form 3 ding reclamation, have been completed	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has	
If the proposal is to deepen directi Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for	Deration (clearly state all pertinem onally or recomplete horizontally, g vork will be performed or provide t ved operations. If the operation res Abandonment Notices shall be file r final inspection.) ue to expire on 5/19/13. Cima	t details, including estimated startin give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rec d only after all requirements, inclu-	ng date of any proposed work and appr ured and true vertical depths of all per A. Required subsequent reports shall completion in a new interval, a Form 3 ding reclamation, have been completed	tinent markers and zones. be filed within 30 days 160-4 shall be filed once	
If the proposal is to deepen directi Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for The permit for this well is du	Deration (clearly state all pertinem onally or recomplete horizontally, g vork will be performed or provide t ved operations. If the operation res Abandonment Notices shall be file r final inspection.) ue to expire on 5/19/13. Cima	t details, including estimated startin give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rec d only after all requirements, inclu-	ng date of any proposed work and appr ured and true vertical depths of all per A. Required subsequent reports shall completion in a new interval, a Form 3 ding reclamation, have been completed	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has	
If the proposal is to deepen directi Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for The permit for this well is du extension due to rig schedu	Deration (clearly state all pertinem onally or recomplete horizontally, g vork will be performed or provide t ved operations. If the operation res Abandonment Notices shall be file r final inspection.) ue to expire on 5/19/13. Cima	t details, including estimated startin give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rec d only after all requirements, inclu- arex respectfully requests a RECE	APPBOVED FOR2	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has	
If the proposal is to deepen directi Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for The permit for this well is du extension due to rig schedu	Deration (clearly state all pertinem) onally or recomplete horizontally, g vork will be performed or provide t ved operations. If the operation res Abandonment Notices shall be file r final inspection.) ue to expire on 5/19/13. Cima ling.	t details, including estimated starting give subsurface locations and meas the Bond No. on file with BLM/BL ults in a multiple completion or rec d only after all requirements, inclu arex respectfully requests a RECEI 3-1365 OCT 03	APPROVED FOR 2013 ENE ING	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has pied for record pied for record JO U	
If the proposal is to deepen directi Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for The permit for this well is du	Deration (clearly state all pertinem) onally or recomplete horizontally, g vork will be performed or provide t ved operations. If the operation res Abandonment Notices shall be file r final inspection.) ue to expire on 5/19/13. Cima ling.	t details, including estimated startin give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rec d only after all requirements, inclu- arex respectfully requests a RECE	APPROVED FOR 2013 ENE ING	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has pied for record pied for record J D D D D D D D D D D	
If the proposal is to deepen directi Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for The permit for this well is du extension due to rig schedu	Deration (clearly state all pertinent onally or recomplete horizontally, g vork will be performed or provide t red operations. If the operation resi Abandonment Notices shall be file r final inspection.) the to expire on 5/19/13. Cima ling.	t details, including estimated starting give subsurface locations and meas the Bond No. on file with BLM/BI. ults in a multiple completion or rec d only after all requirements, inclu- arex respectfully requests a RECEI 0CT 03 NMOCD A MMOCD A MALL COAS	APPROVED FOR 2013 ENELING STRESIA MARCAL	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has pied for record pied for record JO U	
If the proposal is to deepen directi Attach the Bond under which the following completion of the involv- testing has been completed. Final determined that the site is ready for The permit for this well is du extension due to rig schedu	Deration (clearly state all pertinent onally or recomplete horizontally, g vork will be performed or provide t red operations. If the operation res Abandonment Notices shall be file r final inspection.) ue to expire on 5/19/13. Cima ling.	t details, including estimated startin give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rec d only after all requirements, inclu- arex respectfully requests a RECE 3- 1365 RECE 0CT 03 NMOCD A <i>MMOCD A</i> <i>MMOCD A</i>	APPROVED FOR 2013 RTESIA RTESIA HING MARKAG MARK	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has pied for record pied for record JO U	
If the proposal is to deepen directi Attach the Bond under which the following completion of the involv- testing has been completed. Final determined that the site is ready for The permit for this well is du extension due to rig schedu	Deration (clearly state all pertinent onally or recomplete horizontally, g vork will be performed or provide t red operations. If the operation res Abandonment Notices shall be file r final inspection.) the to expire on 5/19/13. Cima ling.	t details, including estimated startin give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rec d only after all requirements, inclu- arex respectfully requests a RECE 3- 1365 RECE 0CT 03 NMOCD A <i>MMOCD A</i> <i>MMOCD A</i>	A Required subsequent reports shall per and true vertical depths of all per and true vertical depths o	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has pied for record pied for record pied for record pied for record	
If the proposal is to deepen directi Attach the Bond under which the following completion of the involv- testing has been completed. Final determined that the site is ready for The permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for this well is du extension due to rig schedu determined that the site is ready for the permit for t	Deration (clearly state all pertinent onally or recomplete horizontally, g vork will be performed or provide t red operations. If the operation res Abandonment Notices shall be file r final inspection.) the to expire on 5/19/13. Cima ling.	t details, including estimated startin give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rec d only after all requirements, inclu- arex respectfully requests a RECE 3- 1365 RECE 0CT 03 NMOCD A <i>MMOCD A</i> <i>MMOCD A</i>	APPROVED FOR 2013 ENDING MARKA APPROVED FOR 2013 ENDING MARKA MA	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has pied for record pied for record pied for record pied for record	
If the proposal is to deepen directi Attach the Bond under which the following completion of the involv- testing has been completed. Final determined that the site is ready for The permit for this well is du extension due to rig schedu development of the second development of t	Deration (clearly state all pertinent onally or recomplete horizontally, g work will be performed or provide t red operations. If the operation res Abandonment Notices shall be file r final inspection.) the to expire on 5/19/13. Cima ling.	t details, including estimated startin give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or rec d only after all requirements, inclu- arex respectfully requests a RECEI 0CT 03 NMOCD A MOCD A MOCD A MAN COAS	APPROVED FOR 2013 ENE ING MACAGE M	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has pied for record pied for record pied for record pied for record	
If the proposal is to deepen directi Attach the Bond under which the following completion of the involv- testing has been completed. Final determined that the site is ready for The permit for this well is du extension due to rig schedu development of the second development of t	Deration (clearly state all pertinent onally or recomplete horizontally, g work will be performed or provide t red operations. If the operation res Abandonment Notices shall be file r final inspection.) the to expire on 5/19/13. Cima ling.	t details, including estimated starting give subsurface locations and meas the Bond No. on file with BLM/BI. ults in a multiple completion or red d only after all requirements, inclu- arex respectfully requests a RECEI 0CT 03 NMOCD A MMOCD A MM	APPROVED FOR 2013 ENE ING MACAGE M	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has piect for record piect for record piect for record piect for record	
If the proposal is to deepen directi Attach the Bond under which the following completion of the involv- testing has been completed. Final determined that the site is ready for The permit for this well is due extension due to rig schedu deve OIL Wywh L Mane OIL Wywh L Mane (Printed/Typed) CHLOE Signature (Electroni	Deration (clearly state all pertinemionally or recomplete horizontally, g work will be performed or provide the operations. If the operation resident and onment Notices shall be file the to expire on 5/19/13. Cime and the to expire on the tother o	t details, including estimated starting ive subsurface locations and meas the Bond No. on file with BLM/BI. ults in a multiple completion or red d only after all requirements, inclu- arex respectfully requests a RECEI 0CT 03 NMOCD A MOCD A Cossing by JOHNNY DICKE Tritle REGUL Date 04/29/2 R FEDERAL OR STATE	APPROVED FOR 2013 ENE ING MACAGE M	tinent markers and zones. be filed within 30 days 160-4 shall be filed once d, and the operator has pied for record 10-4-1 2000 2	

n"

٠

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME:	Cimarex Energy Co of Colorado
LEASE NO.:	
WELL NAME & NO.:	Parks Federal Com 2
SURFACE HOLE FOOTAGE:	990' FSL & 330' FEL
BOTTOM HOLE FOOTAGE	850' FSL & 330' FWL
LOCATION:	Section 9, T.25S., R.26E., NMPM
COUNTY:	Eddy County, New Mexico

TABLE OF CONTENTS

Standard Conditions of Approval (COA) apply to this APD. If any deviations to these standards exist or special COAs are required, the section with the deviation or requirement will be checked below.

General Provisions
 Permit Expiration
 Archaeology, Paleontology, and Historical Sites
 Noxious Weeds
 Special Requirements
 Preconstruction fencing

Preconstruction fencing

Cave/karst

Communitization Agreement

Construction

Notification

Topsoil

Closed Loop System

Federal Mineral Material Pits

Well Pads

Roads

Road Section Diagram

Drilling

Cement requirements
 Critical Cave/Karst
 H₂S – Onshore Order 6
 Logging Requirements
 Waste Material and Fluids

Production (Post Drilling)

Well Structures & Facilities Pipelines - Not permitted with APD Electric Lines - Not permitted with APD

Interim Reclamation

Final Abandonment & Reclamation

I. GENERAL PROVISIONS

The approval of the Application For Permit To Drill (APD) is in compliance with all applicable laws and regulations: 43 Code of Federal Regulations 3160, the lease terms, Onshore Oil and Gas Orders, Notices To Lessees, New Mexico Oil Conservation Division (NMOCD) Rules, National Historical Preservation Act As Amended, and instructions and orders of the Authorized Officer. Any request for a variance shall be submitted to the Authorized Officer on Form 3160-5, Sundry Notices and Report on Wells.

II. PERMIT EXPIRATION

If the permit terminates prior to drilling and drilling cannot be commenced within 60 days after expiration, an operator is required to submit Form 3160-5, Sundry Notices and Reports on Wells, requesting surface reclamation requirements for any surface disturbance. However, if the operator will be able to initiate drilling within 60 days after the expiration of the permit, the operator must have set the conductor pipe in order to allow for an extension of 60 days beyond the expiration date of the APD. (Filing of a Sundry Notice is required for this 60 day extension.)

III. ARCHAEOLOGICAL, PALEONTOLOGY & HISTORICAL SITES

Any cultural and/or paleontological resource discovered by the operator or by any person working on the operator's behalf shall immediately report such findings to the Authorized Officer. The operator is fully accountable for the actions of their contractors and subcontractors. The operator shall suspend all operations in the immediate area of such discovery until written authorization to proceed is issued by the Authorized Officer. An evaluation of the discovery shall be made by the Authorized Officer to determine the appropriate actions that shall be required to prevent the loss of significant cultural or scientific values of the discovery. The operator shall be held responsible for the cost of the proper mitigation measures that the Authorized Officer assesses after consultation with the operator on the evaluation and decisions of the discovery. Any unauthorized collection or disturbance of cultural or paleontological resources may result in a shutdown order by the Authorized Officer.

IV. NOXIOUS WEEDS

The operator shall be held responsible if noxious weeds become established within the areas of operations. Weed control shall be required on the disturbed land where noxious weeds exist, which includes the roads, pads, associated pipeline corridor, and adjacent land affected by the establishment of weeds due to this action. The operator shall consult with the Authorized Officer for acceptable weed control methods, which include following EPA and BLM requirements and policies.

V. SPECIAL REQUIREMENT(S)

Preconstruction Fencing

The well pad and access road shall be fenced with a three strand wire fence prior to construction in order to prevent disturbance from occurring outside the permitted area. The fence around the perimeter of the approved well pad dimensions and area for stockpiled topsoil shall not exceed the permitted area by farther than three feet. The fence shall be maintained until the well is placed on production.

Cave and Karst

** Depending on location, additional Drilling, Casing, and Cementing procedures may be required by engineering to protect critical karst groundwater recharge areas.

Cave/Karst Surface Mitigation

The following stipulations will be applied to minimize impacts during construction, drilling and production.

Construction:

In the advent that any underground voids are opened up during construction activities, construction activities will be halted and the BLM will be notified immediately.

No Blasting:

No blasting will be utilized for pad construction. The pad will be constructed and leveled by adding the necessary fill and caliche.

Tank Battery Liners and Berms:

Tank battery locations will be lined and bermed. A 20 mil permanent liner will be installed with a 4 oz. felt backing to prevent tears or punctures. Tank battery berms must be large enough to contain $1\frac{1}{2}$ times the content of the largest tank.

Leak Detection System:

A method of detecting leaks is required. The method could incorporate gauges to measure loss, situating values and lines so they can be visually inspected, or installing electronic sensors to alarm when a leak is present. Leak detection plan will be submitted to BLM for approval.

Automatic Shut-off Systems:

Automatic shut off, check values, or similar systems will be installed for pipelines and tanks to minimize the effects of catastrophic line failures used in production or drilling.

Cave/Karst Subsurface Mitigation

The following stipulations will be applied to protect cave/karst and ground water concerns:

Rotary Drilling with Fresh Water:

Fresh water will be used as a circulating medium in zones where caves or karst features are expected. SEE ALSO: Drilling COAs for this well.

Directional Drilling:

Kick off for directional drilling will occur at least 100 feet below the bottom of the cave occurrence zone. SEE ALSO: Drilling COAs for this well.

Lost Circulation:

ALL lost circulation zones from the surface to the base of the cave occurrence zone will be logged and reported in the drilling report.

Regardless of the type of drilling machinery used, if a void of four feet or more and circulation losses greater than 70 percent occur simultaneously while drilling in any cavebearing zone, the BLM will be notified immediately by the operator. The BLM will assess the situation and work with the operator on corrective actions to resolve the problem.

Abandonment Cementing:

Upon well abandonment in high cave karst areas additional plugging conditions of approval may be required. The BLM will assess the situation and work with the operator to ensure proper plugging of the wellbore.

Pressure Testing:

Annual pressure monitoring will be performed by the operator on all casing annuli and reported in a sundry notice. If the test results indicated a casing failure has occurred, remedial action will be undertaken to correct the problem to the BLM's approval.

Fluorescent Dyes:

Nontoxic Fluorescent dyes will be added to the drilling fluid when the hole is spudded and will be circulated to the bottom of the karst layers. BLM must witness the dye being injected.

Florescene Dye (Acid Yellow 73):

Thirty-two (32) ounces dry powder Florescene (Acid Yellow 73) dye will be added to the drilling fluid before the well is spudded AND to the pre-flush fluids of the surface interval of casing.

These dyes will track the fluids if lost circulation occurs.

Arrangements will be made to have BLM witness the dye being injected prior to spudding the hole <u>AND</u> before the pre-flush of the surface casing. Contact the BLM cave specialist at (575) 361-3566 to make arrangements.

.

<u>Communitization Agreement</u> A Communitization Agreement covering the acreage dedicated to this well must be filed for approval with the BLM. The effective date of the agreement shall be prior to any sales.

VI. CONSTRUCTION

A. NOTIFICATION

The BLM shall administer compliance and monitor construction of the access road and well pad. Notify the Carlsbad Field Office at (575) 234-6235 at least 3 working days prior to commencing construction of the access road and/or well pad.

When construction operations are being conducted on this well, the operator shall have the approved APD and Conditions of Approval (COA) on the well site and they shall be made available upon request by the Authorized Officer.

B. TOPSOIL

The operator shall stockpile the topsoil in a low profile manner in order to prevent wind/water erosion of the topsoil. The topsoil to be stripped is approximately 6 inches in depth. The topsoil will be used for interim and final reclamation.

C. CLOSED LOOP SYSTEM

Tanks are required for drilling operations: No Pits.

The operator shall properly dispose of drilling contents at an authorized disposal site.

D. FEDERAL MINERAL MATERIALS PIT

Payment shall be made to the BLM prior to removal of any federal mineral materials. Call the Carlsbad Field Office at (575) 234-5972.

E. WELL PAD SURFACING

Surfacing of the well pad is not required.

If the operator elects to surface the well pad, the surfacing material may be required to be removed at the time of reclamation.

The well pad shall be constructed in a manner which creates the smallest possible surface disturbance, consistent with safety and operational needs.

F. ON LEASE ACCESS ROADS

Road Width

The access road shall have a driving surface that creates the smallest possible surface disturbance and does not exceed fourteen (14) feet in width. The maximum width of surface disturbance, when constructing the access road, shall not exceed twenty (20) feet.

Surfacing

Surfacing material is not required on the new access road driving surface. If the operator elects to surface the new access road or pad, the surfacing material may be required to be removed at the time of reclamation.

Where possible, no improvements should be made on the unsurfaced access road other than to remove vegetation as necessary, road irregularities, safety issues, or to fill low areas that may sustain standing water.

The Authorized Officer reserves the right to require surfacing of any portion of the access road at any time deemed necessary. Surfacing may be required in the event the road deteriorates, erodes, road traffic increases, or it is determined to be beneficial for future field development. The surfacing depth and type of material will be determined at the time of notification.

Crowning


Crowning shall be done on the access road driving surface. The road crown shall have a grade of approximately 2% (i.e., a 1" crown on a 14' wide road). The road shall conform to Figure 1; cross section and plans for typical road construction.

Ditching

Ditching shall be required on both sides of the road.

Turnouts

Vehicle turnouts shall be constructed on the road. Turnouts shall be intervisible with interval spacing distance less than 1000 feet. Turnouts shall be constructed on all blind curves. Turnouts shall conform to the following diagram:




Drainage

Drainage control systems shall be constructed on the entire length of road (e.g. ditches, sidehill outsloping and insloping, lead-off ditches, culvert installation, and low water crossings).

A typical lead-off ditch has a minimum depth of 1 foot below and a berm of 6 inches above natural ground level. The berm shall be on the down-slope side of the lead-off ditch.

Cross Section of a Typical Lead-off Ditch



All lead-off ditches shall be graded to drain water with a 1 percent minimum to 3 percent maximum ditch slope. The spacing interval are variable for lead-off ditches and shall be determined according to the formula for spacing intervals of lead-off ditches, but may be amended depending upon existing soil types and centerline road slope (in %);

Formula for Spacing Interval of Lead-off Ditches

Example - On a 4% road slope that is 400 feet long, the water flow shall drain water into a lead-off ditch. Spacing interval shall be determined by the following formula:

400 foot road with 4% road slope: $\underline{400'} + 100' = 200'$ lead-off ditch interval 4%

Culvert Installations

Appropriately sized culvert(s) shall be installed at the deep waterway channel flow crossing.

Cattleguards

An appropriately sized cattleguard(s) sufficient to carry out the project shall be installed and maintained at fence crossing(s).

Any existing cattleguard(s) on the access road shall be repaired or replaced if they are damaged or have deteriorated beyond practical use. The operator shall be responsible for the condition of the existing cattleguard(s) that are in place and are utilized during lease operations.

Public Access

Public access on this road shall not be restricted by the operator without specific written approval granted by the Authorized Officer.




Figure 1 – Cross Sections and Plans For Typical Road Sections

VII. DRILLING

A. DRILLING OPERATIONS REQUIREMENTS

The BLM is to be notified a minimum of 4 hours in advance for a representative to witness:

- a. Spudding well (minimum of 24 hours)
- b. Setting and/or Cementing of all casing strings (minimum of 4 hours)
- c. BOPE tests (minimum of 4 hours)

Eddy County Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822

- 1. A Hydrogen Sulfide (H2S) Drilling Plan should be activated prior to drilling out the surface shoe. As a result, the Hydrogen Sulfide area must meet Onshore Order 6 requirements, which includes equipment and personnel/public protection items. If Hydrogen Sulfide is encountered, please provide measured values and formations to the BLM.
- Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval. If the drilling rig is removed without approval an Incident of Non-Compliance will be written and will be a "Major" violation.
- 3. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works is located, this does not include the dog house or stairway area.
- 4. The record of the drilling rate along with the GR/N well log run from TD to surface (horizontal well vertical portion of hole) shall be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

B. CASING

Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.).

Centralizers required on surface casing per Onshore Order 2.III.B.1.f.

Wait on cement (WOC) time prior to drilling out for a primary cement job will be a minimum 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compressive strength, whichever is greater for all casing strings. DURING THIS WOC TIME, NO DRILL PIPE, ETC. SHALL BE RUN IN THE HOLE. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing each casing string. IF OPERATOR DOES NOT HAVE THE WELL SPECIFIC CEMENT DETAILS ONSITE PRIOR TO PUMPING THE CEMENT FOR EACH CASING STRING, THE WOC WILL BE 30 HOURS. See individual casing strings for details regarding lead cement slurry requirements.

No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.

Critical cave/karst.

Possible lost circulation in the Delaware formation.

- 1. The 13-3/8 inch surface casing shall be set at approximately 450 feet (a minimum of 25 feet into the Rustler Anhydrite and above the salt) and cemented to the surface.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.

b. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry.

c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.

- d. If cement falls back, remedial cementing will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the 9-5/8 inch intermediate casing is:
 - Cement to surface. If cement does not circulate see B.1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst.

Centralizers required on horizontal leg, must be type for horizontal service and a minimum of one every third joint unless lateral doglegs require greater spacing between centralizers.

The pilot hole plugging procedure is approved as written. Note plug top on drilling report.

3. The minimum required fill of cement behind the **5-1/2** inch production casing is:

Cement to surface. If cement does not circulate, contact the appropriate BLM office. Additional cement may be required – excess calculates to 7%.

4. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

C. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. Variance approved to use flex line from BOP to choke manifold. Check condition of flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer's requirements. The flexible hose can be exchanged with a hose of equal size and equal or greater pressure rating. Anchor requirements, specification sheet and hydrostatic pressure test certification matching the hose in service, to be onsite for review. These documents shall be posted in the company man's trailer and on the rig floor. If the BLM inspector questions the straightness of the hose, a BLM engineer will be contacted and will review in the field or via picture supplied by inspector to determine if changes are required (operator shall expect delays if this occurs).

- 3. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **3000** (**3M**) psi.
 - a. For surface casing only: If the BOP/BOPE is to be tested against casing, the wait on cement (WOC) time for that casing is to be met (see WOC statement at start of casing section). Independent service company required.
- 4. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips, the minimum wait time before cut-off is eight hours after bumping the plug. BOP/BOPE testing can begin after cut-off or once cement reaches 500 psi compressive strength (including lead when specified), whichever is greater. However, if the float does not hold, cut-off cannot be initiated until cement reaches 500 psi compressive strength (including lead when specified).
 - b. The tests shall be done by an independent service company utilizing a test plug **not a cup or J-packer**. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (18 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).
 - c. The test shall be run on a 5000 psi chart for a 2-3M BOP/BOP, on a 10000 psi chart for a 5M BOP/BOPE and on a 15000 psi chart for a 10M BOP/BOPE. If a linear chart is used, it shall be a one hour chart. A circular chart shall have a maximum 2 hour clock.
 - d. The results of the test shall be reported to the appropriate BLM office.
 - e. All tests are required to be recorded on a calibrated test chart. A copy of the **BOP/BOPE test chart and a copy of independent service company test** will be submitted to the appropriate BLM office.
 - f. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug. This test shall be performed prior to the test at full stack pressure.

D. DRILL STEM TEST

If drill stem tests are performed, Onshore Order 2.III.D shall be followed.

E. WASTE MATERIAL AND FLUIDS

ł

All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area.

Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

JAM 053013

VIII. PRODUCTION (POST DRILLING)

A. WELL STRUCTURES & FACILITIES

Placement of Production Facilities

Production facilities should be placed on the well pad to allow for maximum interim recontouring and revegetation of the well location.

Containment Structures

The containment structure shall be constructed to hold the capacity of the entire contents of the largest tank, plus 24 hour production, unless more stringent protective requirements are deemed necessary by the Authorized Officer.

Painting Requirement

All above-ground structures including meter housing that are not subject to safety requirements shall be painted a flat non-reflective paint color Shale Green, Munsell Soil Color Chart # 5Y 4/2

B. PIPELINES (not applied for in APD)

C. ELECTRIC LINES (not applied for in APD)

IX. INTERIM RECLAMATION

During the life of the development, all disturbed areas not needed for active support of production operations should undergo interim reclamation in order to minimize the environmental impacts of development on other resources and uses.

Within six (6) months of well completion, operators should work with BLM surface management specialists (Jim Amos: 575-234-5909) to devise the best strategies to reduce the size of the location. Interim reclamation should allow for remedial well operations, as well as safe and efficient removal of oil and gas.

During reclamation, the removal of caliche is important to increasing the success of revegetating the site. Removed caliche that is free of contaminants may be used for road repairs, fire walls or for building other roads and locations. In order to operate the well or complete workover operations, it may be necessary to drive, park and operate on restored interim vegetation within the previously disturbed area. Disturbing revegetated areas for production or workover operations will be allowed. If there is significant disturbance and loss of vegetation, the area will need to be revegetated. Communicate with the appropriate BLM office for any exceptions/exemptions if needed.

All disturbed areas after they have been satisfactorily prepared need to be reseeded with the seed mixture provided below.

Upon completion of interim reclamation, the operator shall submit a Sundry Notices and Reports on Wells, Subsequent Report of Reclamation (Form 3160-5).

X. FINAL ABANDONMENT & RECLAMATION

At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land are restored.

Earthwork for final reclamation must be completed within six (6) months of well plugging. All pads, pits, facility locations and roads must be reclaimed to a satisfactory revegetated, safe, and stable condition, unless an agreement is made with the landowner or BLM to keep the road and/or pad intact.

After all disturbed areas have been satisfactorily prepared, these areas need to be revegetated with the seed mixture provided below. Seeding should be accomplished by drilling on the contour whenever practical or by other approved methods. Seeding may need to be repeated until revegetation is successful, as determined by the BLM.

Operators shall contact a BLM surface protection specialist prior to surface abandonment operations for site specific objectives (Jim Amos: 575-234-5909).

Seed Mixture 4, for Gypsum Sites

The holder shall seed all disturbed areas with the seed mixture listed below. The seed mixture shall be planted in the amounts specified in pounds of pure live seed (PLS)* per acre. There shall be <u>no</u> primary or secondary noxious weeds in the seed mixture. Seed will be tested and the viability testing of seed will be done in accordance with State law(s) and within nine (9) months prior to purchase. Commercial seed will be either certified or registered seed. The seed container will be tagged in accordance with State law(s) and available for inspection by the authorized officer.

Seed will be planted using a drill equipped with a depth regulator to ensure proper depth of planting where drilling is possible. The seed mixture will be evenly and uniformly planted over the disturbed area (smaller/heavier seeds have a tendency to drop the bottom of the drill and are planted first). The holder shall take appropriate measures to ensure this does not occur. Where drilling is not possible, seed will be broadcast and the area shall be raked or chained to cover the seed. When broadcasting the seed, the pounds per acre are to be doubled. The seeding will be repeated until a satisfactory stand is established as determined by the authorized officer. Evaluation of growth will not be made before completion of at least one full growing season after seeding.

Species to be planted in pounds of pure live seed* per acre:

Species	<u>lb/acre</u>
Alkali Sacaton (Sporobolus airoides)	1.0
DWS Four-wing saltbush (Atriplex canescens)	5.0

DWS: DeWinged Seed

*Pounds of pure live seed:

Pounds of seed x percent purity x percent germination = pounds pure live seed