opies To Appropriate District	Otata of No.	Massiaa		Form C-103
Clarifor I	State of Nev Energy, Minerals and		WELL API NO.	October 25, 200
1625 N. French Dr., Hobbs, NM 88240	Energy, willicrais and	Natural Nesources		5-21542
District II 1301 W. Grand Ave. Artesia, NM 98210 - OCD OIL CONSERVATION DIVISION			30-015-21542 5. Indicate Type of Lease	
1301 W. Grand Ave., Artesia, NM 88210 CD	·		STATE [_
1000 Rio Brazos Rd. Aztec, NM 87410	3 1220 South St.	,		
1220 S. St. Francis Dr. Santa Fe. NMUL 2	Santa Fe, N	M 87505	6. State Oil & Gas Leas	e No.
1000 Rio Brazos Rd. Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NMUL 2 9 201 87505	<u> </u>			
SUNDRY NOTIGES:AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Empire Abo Unit "I"	
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well Gas Well V Other			231	
2. Name of Operator			9. OGRID Number 00873	
Apache Corporation 3. Address of Operator			10. Pool Name	
303 Veterans Airpark Lane, Ste. 3000, Midland, TX, 79705			Empire Abo	
4. Well Location	100	A		
Unit Letter B : Section 6 To	1260 feet from the pwnship 18S R	N line and ange 28E	1580 feet from the NMPM	E line County Eddy
	evation (Show whether DF	<u> </u>	(VIVIE IVI	County Ludy
		71' GR		
12. Check Appropriate Box To Indicate Na	ature of Notice. Report.	or Other Data		
· · ·	, , ,			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A				
	= 1	ASING/CEMENT JOB	TIOS.	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
DOWNHOLE COMMINGLE				
OTHER:		✓ Location is	ready for OCD inspection a	after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
✓ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from the lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)	ddagaa dagaa oo o			
✓ All other environmental concrens have been a ✓ Pipelines and flow lines have been abandoned	•	714.B(4)(b) NMAC. All flu	uids have been removed from	n
non-retrieved flow lines and pipelines.	,			
When all work has been completed, return this	form to the appropriate Dist	rict office to schedule an i	nspection. If more than one	
inspection has to be made to a P&A location b				,
0.00				
SIGNATURE SIN ALLIQUE	TITLE _	P&A Technic	ianDATE	7/24/13
TYPE OR PRINT NAME Leon Selle	rs E-MAIL	leon.sellers@apache	ecorp.com PHONE:	432-208-0349
For State Lise Only				
APPROVED BY:	Genziti =	C. A.	DATE	10/11/12
Conditions of Approval (if any):	GrimHILE 14. TO RELL	54C 25	DAIL	,,,,,
	14,101666	- 11 76 .		