Fcm 3160-5 (August 2007)

## **UNITED STATES**

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPRO	VED
OMB NO. 1004	-0135
Evniree: July 31	2010

_	Expires: July 3
	Lease Serial No.
	NMNM10893

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use form 3160-3 (APD) for such proposals	÷.

6. If Indian, Allottee or Tribe Name

abandoned wei	II. Use form 3160-3 (APL	)) for such p	roposals.		o. It makin, monec o	· · · · · · · · · · · · · · · · · · ·		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
Type of Well     Oil Well			8. Well Name and No. GODFREY MP FEDERAL 5					
Name of Operator YATES PETROLEUM CORPO	TS m	9. API Well No. 30-005-61139-00-S1						
3a. Address 105 SOUTH 4TH STREET ARTESIA, NM 88210	(include area code 8-4272 -4585	)	10. Field and Pool, or Exploratory PECOS SLOPE-ABO					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, and State				
Sec 15 T7S R25E NENE 660F	FNL 660FEL			CHAVES COUNTY, NM				
12. CHECK APPE	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, REI	PORT, OR OTHER	R DATA		
TYPE OF SUBMISSION			TYPE Q	F ACTION				
		☐ New	ture Treat  Construction and Abandon	☐ Reclamat	ete rily Abandon	☐ Water Shut-Off ☐ Well Integrity ☐ Other		
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. of file with BLMBIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  Yates Petroleum Corporation plans to Plug and Abandon this well as follows:  1. MIRU WSU. Rig up safety equipment as needed. No casing recovery will be attempted. POOH with 2-3/8 inch tubing.  2. Set a CIBP at 3,956 ft and cap it with 35 ft of cement. This puts a plug over the Abo.  3. Perforate at 1,610 ft and spot a 30 sx Class C cement plug from 1,510 ft to 1,610 ft. This puts a 100 ft plug across the top of Glorieta, inside and outside the casing. WOC and tag plug.  4. Perforate at 900 ft and spot a 40 sx Class C cement plug from 800 ft to 900 ft. This puts a 100 ft plug across Surface Casing Shoe. WOC and tag plug.  5. Perforate at 60 ft and spot a 25 sx Clas C cement plug from 60 ft up to the surface.  6. Remove all surface equipment, weld dry hole marker and clean location as per regulations.  Schematics attached  ACCEPTED  AND OF ARTESIA  14. Thereby certify that the foregoing is true and correct.								
, , , ,	Electronic Submission #2 For YATES PETRO d to AFMSS for processing	DLEUM CORP	ORATION, sent WEATHERFOR	to the Roswell	3 (14BMW1427SE)			
Signature (Electronic S	Submission)		Date 10/16/2	2013				
. ,	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	E			
_Approved By_DAVID_R GLASS Conditions of approval, if any, are attached	d. Approval of this notice does	not warrant or	TitlePETROLE	EUM ENGINEI	ER	Date 11/04/2013		
certify that the applicant holds legal or equ which would entitle the applicant to condu	Office Roswell			· · · · · · · · · · · · · · · · · · ·				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212; make it a catatements or representations as	crime for any pe to any matter wi	rson knowingly and thin its jurisdiction.	d willfully to mak	te to any department or	agency of the United		

NMOCD

Artesia

MONTH PERIOD **CONDITIONS OF APPROVAL** ENDING FEB 0 4 2014

WELL NAME: Godfrey MP Fed #5. FIELD: Pecos Slope Abo LOCATION: 660' FSL & 660'FEL Sec 15-7S-25E Chaves County GL: 3777.6' ZERO:\_\_\_\_ KB: **CASING PROGRAM** SPUD DATE: 12/1/81 **COMPLETION DATE: 12/10/81** 10 ¾"40.5# J-55 , 850° COMMENTS:\_ 4 ½" 9.5# J-55 4498 14-3/4" hole **Before** 10 3/4" csg @ 850' w/700 sx(circ) Formation tops: San Andres : 476' Glorieta : 1,560' Abo 3,643 7 7/8" hole TOC @ 2816', CBL Abo perfs: 4006-4018 (13) 4 ½' csg @ 4,498' w/450 sx Not to Scale TD 4500' 9/10/13 FC 4423' (PBTD) MMFH

WELL NAME: Godfrey MP Fed #5 FIELD: Pecos Slope Abo Chaves County LOCATION: 660' FSL & 660' FEL Sec 15-7S-25E GL: 3777.6' ZERO:\_\_\_ KB: **CASING PROGRAM** SPUD DATE: 12/1/81 **COMPLETION DATE: 12/10/81** 10 3/4"40.5# J-55 850 COMMENTS:\_ 4 1/2" 9.5# J-55 4498 60', 25sx cmt surface plug 14 3/4" hole **After** 10 3/4" csg @ 850' w/700 sx(circ) 100'; 40sx cmt plug 800'-900' Formation tops: San Andres : 476' Glorieta : 1,560' : 3,643' Abo 100', 30sx cmt plug 1,510'-1610' 7 7/8" TOC @ 2816', CBL hole CIBP @ 3,956' + Abo perfs: 4006-4018 (13) 35' cmt 4 1/2' csg @ 4,498' w/450 sx Not to Scale TD 4500' 9/10/13 FC 4423' (PBTD) **MMFH** 

## BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90<sup>th</sup> day provide the BLM Roswell Field Office (RFO), prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.
- 2. <u>Notification</u>: Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. <u>Dry Hole Marker:</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.