Form 3160-5 (March 2012)

Approved by

entitle the applicant to conduct operations thereon

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. OIL CONSERVATION DIVISION

811 S. FIRST STREET

Expires: Oc

NM-4433

ARTESIA, NM 88210 Lease Serial No.

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

JAN 17 2014

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No.
1. Type of Well			
Oil Well Gas Well Other			8. Well Name and No. Round Tank Queen Unit #5
2. Name of Operator Armstrong Energy Corporation			9. API Well No. 30-005-00392
3a. Address 3b. Phor		3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area
P.O. Box 1973, Roswell, NM 88202		575-625-2222	Round Tank Queen
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1980' FSL & 1980' FEL Section 24, Township 15 South, Range 26			11. County or Parish, State Chaves County, NM
12. CHECK	THE APPROPRIATE BO	X(ES) TO INDICATE NATURE OF NO	TICE, REPORT OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACT		CTION	
Notice of Intent	Acidize Alter Casing		roduction (Start/Resume) Water Shut-Off eclamation Well Integrity
Subsequent Report	Casing Repair Change Plans		ecomplete Other Other
Final Abandonment Notice	Convert to Injection		ater Disposal
following completion of the involved	l operations. If the operation of the logical	on results in a multiple completion or reco	Required subsequent reports must be filed within 30 days empletion in a new interval, a Form 3160-4 must be filed once ing reclamation, have been completed and the operator has
Notify BLM 24 hrs prior to start of	oporations		
,	,	14251 12251 25 av. DOLL CD WOO	TILL and tog plus circulate halo w/ 0.5 ppg mud
			FIH and tag plug, circulate hole w/ 9.5 ppg mud.
leave 4-1/2" casing full of ceme	ent.	Establish circulation, pump 80 sx Cla	iss "C" cement, circulate annulus with cement and
3. Cut off wellhead and install dry	hole marker. BGL		RECENTER
4. Clean location, cut off anchors, remove caliche, rip location and reseed.			
5. Notify BLM for Final Inspection	n.	12D 1/31 b	JAN 27 2014 NMOCD ARTESIA
14. I hereby certify that the foregoing is tru	e and correct. Name (Printe	rd/Typed)	
Bruce A. Stubbs		Title Vice Presid	ent - Operations
Signature B	Stille	Date 12/17/2013	·

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title


Office

PETROLEUM ENGINEER

ROSWELL FIELD OFFICE

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

that the applicant holds legal or equitable title to those rights in the subject lease which would



BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90th day provide the BLM Roswell Field Office (RFO), prior to the 90th day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.
- 2. <u>Notification:</u> Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. Monument: Upon abandonment of the well, all casing shall be cut-off at the base of the cellar or 3-feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. Timing Limitation Lease Stipulation / Condition of Approval For Lesser Prairie-Chicken: Oil and gas activities including 3-D geophysical exploration, and drilling will not be allowed in lesser prairie-chicken habitat during the period from March 1 through June 15 annually. During that period, other activities that produce noise or involve human activity, such as the maintenance of oil and gas facilities, geophysical exploration other than 3-D seismic operations, and pipeline, road, and well pad construction, will be allowed except between 3:00 am and 9:00 am. The 3:00 am to 9:00 am restriction will not apply to normal, around-the-clock operations, such as venting, flaring, or pumping, which do not require a human presence during this period. Additionally, no new drilling will be allowed within up to 200 meters of leks known at the time of permitting. Normal vehicle use on existing roads will not be restricted. Exhaust noise from pump jack engines must be muffled or otherwise controlled so as not to exceed 75 db measured at 30 feet from the source of the noise.
- 8. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.