orm 3160-5 (August 2007)

(Instructions on page 2)

# UNITED STATES DEPARTMENT OF THE INFREDOR BUREAU OF LAND MANAGEMENT 1 2 2014

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.
NMLC-029395B

	SUNI	DRY I	NOTICES	S AND RE	PORTS	ON WEDI	SHIP
o n	ot use	this f	orm for	S AND REI	to drill	lorto-re-c	nter and

6. If Indian, Allottee or Tribe Name

	se this form for proposals to c ed well.  Use Form 3160-3 (AP								
	RIPLICATE – Other instructions on		7. If Unit of CA/Agreement, Name and/or No.						
1. Type of Well	Gas Well Other		8. Well Name and No. LEE FEDERAL 65						
2. Name of Operator	ORPORATION <873>	l l	9. API Well No.						
3. Address	3b. Phone 1		30-015-41109 10. Field and Pool or Exploratory Area						
	NIDDADK I N. #2000	8-1000 / 432-818-11(	·	CEDAR LAKE					
4. Location of Well (Footage, S	Sec., T., R., M., or Survey Description	on)	11. County	y or Parish, St	ate				
UL P, SEC 17, T17S, R31E, 240	' FSL & 990' FEL		EDDY CO	EDDY COUNTY, NM					
12. CHECK T	THE APPROPRIATE BOX(ES) TO IN	DICATE NATURE O	F NOTICE, REPORT	CE, REPORT OR OTHER DATA					
TYPE OF SUBMISSION		ТҮРЕ О	TYPE OF ACTION						
<ul><li>Notice of Intent</li><li>Subsequent Report</li><li>Final Abandonment Notice</li></ul>	Casing Repair New Change Plans Plug	pen ure Treat Construction and Abandon Back	Production (Start/Resu Reclamation Recomplete Temporarily Abandon Water Disposal	´	Water Shut-Off Well Integrity Other DRILLING OPS: CASING & CEMENT REPORT				
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration there If the proposal is to deepen directional or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attached the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 da following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed one testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  Bond No: BLM-CO-1463  11/15/2013 SPUD									
11/15/2013 Surface Csg 1	3 3/8, Hole 17.5", H-40, 48# set	@ 322' Cmt with	<u>ı:</u>		- TILOUID				
CIRC 274 SX T WOC, Surface Csg F REPORT CONTINUED ON PAG	Pressure Test: 1500 PSI/30 min EE 2.	URD 3/14/19 Accepted for the PET DOB	HAZOI	MAR J BAN REALL OF LAN	8 2014 				
14. I hereby certify that the foregoname ( <i>Printed/Typed</i> )	ing is true and correct.			CARLSBAD F	FIELD OFFICE				
MICHEL	LE COOPER	Title DRILL	ING TECH						
Signature Muhelle	Cooper	Date 1/21/2	013						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved by		Title		Date					
	ched. Approval of this notice does not warn equitable title to those rights in the subject landuct operations thereon.	ant or		, Date					
	e 43 U.S.C. Section 1212, make it a crime for ments or representations as to any matter wit		nd willfully to make to a	iny department o	r agency of the United States				

and the second second

# LEE FEDERAL 65 - Csg & Cmt End of Well Sundry

### 11/20/2013 Drl F/3295' - T/3540' TD. Circ and Cond Hole.

### 11/20/2013 Intermediate Csg 8 5/8, Hole 11", J-55, 32# SET @ 3540'

<u>Lead</u>: 800 sx Class C (12.5 wt, 2.13 yld)

Tail: 450 sx Class C (14.8 wt, 1.33 yld)

Circ 0 sx to surface.

#### 11/21/2013

500 sx Class C (14.8 wt, 1.33 yld)
WOC Circ 0 sx to surface.

#### 11/22/2013

#1

PU 1" pipe, Tag 530'

100 sx Class C

WOC Circ 0 xs to surface

#2

PU 1" pipe, Tag 412'

50 sx Class C

WOC Circ 0 xs to surface

#3

PU 1" pipe, Tag 530'

100 sx Class C

WOC Circ 0 xs to surface

#4

PU 1" pipe, Tag 493'

50 sx Class C

WOC Circ 0 xs to surface

#### 11/23/2013

#5

50 sx Class C

WOC Circ 0 xs to surface

#### 11/24/2013

#6

Lead: 200 sx Class C (14.8 wt, 1.55 yld)

<u>Tail:</u> 400 sx Class C (14.8 wt, 1.33 yld)

Circ 0 sx to surface. WOC

#7

PU 1" pipe, Tag 672'

130 sx Class C

WOC Circ 0 xs to surface

## LEE FEDERAL 65 - Csg & Cmt End of Well Sundry

## 11/26/2013

#8 PU 1" pipe, Tag 751' 150 sx Class C

PU 1" pipe, Tag 751' pipe plug PU 1" pipe, Tag 430 lay 1" to 150', PU 1"pipe Tag @630 100 sx Class C WOC

PU 1" pipe, Tag 380'
PU to 150' Tag 639'
300 sx Class C
CIRC 30 GAL MIN; WOC

Squeeze, 250 sx Class C

#### 11/27/2013

CMT: 250 sx Class C WOC

Inter Csg pressure test 2000 PSI/30 min-OK.

#### 12/01/2013 Dri F/6270' - T/6400' TD. Circ and Cond Hole. RU Schlumberger Loggers

#### 12/02/2013 Production Csg 5.5, Hole 7.875, J-55, 17# set @ 6400' Cmt with:

Lead: 430 sx Class C (12.6 wt, 2.00 yld)

<u>Tail:</u> 580 sx Class C (14.2 wt, 1.31 yld)

Circ 190 sx to surface.

Prod Csg pressure test 2500 PSI/30 min-OK.

12/02/2013- RR