

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-63719
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator ARMSTRONG ENERGY CORPORATION		6. State Oil & Gas Lease No. VA-2011
3. Address of Operator P.O. Box 1973, Roswell, NM 88022-1973		7. Lease Name or Unit Agreement Name Z-28 State
4. Well Location Unit Letter <u>M</u> : <u>660</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line Section <u>24</u> Township <u>10S</u> Range <u>26E</u> NMPM <u>Chaves</u> County		8. Well Number 2
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3710' GR		9. OGRID Number 001092
		10. Pool name or Wildcat Comanche Spring Wolfcamp

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
 DOWNHOLE COMMINGLE ☐
 CLOSED-LOOP SYSTEM ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ P AND A ☒
 CASING/CEMENT JOB ☐
 OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2-27-14 Move in, RU, ND wellhead, install BOP, unseat pkr and POH w/ 171 jts, 2-3/8" tbq. SDON.

2-28-14 PU 5-1/2" CIBP, RIH and set @ 5600', circ hole w/ 9.5 ppg Brine mud. Test csg @ 250 psi, OK. Spot 25 sx Class "C" cement. POH to 4624', spot 25 sx plug, POH, WOC. RIH, tag @ 4375', 249' plug. POH to 2360', spot 25 sx, POH, WOC. SDON

3-03-14 RIH, tag @ 2122', 238' plug. POH to 1294', spot 25 sx plug, POH, WOC. RIH, tag @ 1067', 227' plug. Perf @ 430' w/ 4 shots, establish circ, pump 120 sx Class "C" cement, fill 5-1/2" x 8-5/8" annulus w/ cement and leave 5-1/2" csg full of cement. Cut off wellhead, top off both casing strings with 15 sx, install Dry Hole plate, back-fill cellar, cut off anchors, clean location. RD and move out.

Will notify OCD when location is rehabilitated and re-seeded.

Approved for plugging of well bore only,
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms. www.emnrd.state.nm.us/oed.

RECEIVED

MAR 27 2014

NMOCD ARTESIA

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE B. Stubbs TITLE Vice President - Operations DATE 3/25/14

Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: 575-625-2222

For State Use Only

APPROVED BY: [Signature] TITLE Dist. Supervisor DATE 3/27/2014

Conditions of Approval (if any):

★ Submit Subsequent C-103