Form 3160-5 (August 2007)


UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS MAK 1 9 2014 Do not use this form for proposals to drill or to te-enter an abandoned well. Use form 3160-3 (APD) for such proposits ARTESIA SUBMIT IN TRIPLICATE - Other instructions on reverse side.					NMNM38636 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.		
							Type of Well Gas Well □ Ott
Name of Operator CIMAREX ENERGY CO OF (LER S.COM		9. API Well No. 30-015-25720				
3a. Address 600 N. MARIENFELD, SUITE MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-687-3033			10. Field and Pool, or Exploratory BRUSHY DRAW; DELAWARE			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State		
Sec 27 T26S R29E Mer NMP			EDDY COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHER	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize ☐ Alter Casing	☐ Frac	☐ Deepen ☐ Fracture Treat		ion (Start/Resume)	☐ Water Shut-Off ☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	ng Repair		¹□ Recomplete		☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	•		☐ Tempor	arily Abandon	·	
<u> </u>	Convert to Injection	nvert to Injection Plug Back Water		Disposal			
13. Describe Proposed or Completed Op If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involvec testing has been completed. Final Al determined that the site is ready for f	ally or recomplete horizontally rk will be performed or provide d operations. If the operation re bandonment Notices shall be fil inal inspection.)	, give subsurface e the Bond No. o esults in a multip led only after all	locations and measing file with BLM/BI/ e completion or recrequirements, include	ired and true ve A. Required sub empletion in a r	ertical depths of all pertin osequent reports shall be new interval, a Form 316 n, have been completed, a	ent markers and zones. filed within 30 days 0-4 shall be filed once and the operator has	
1) SET 5-1/2" CIBP @ 4,850; 2) PUMP 80 SXS.CMT. @ 3,7 3) PUMP 25 SXS.CMT. @ 2,8 4) PERF. X ATTEMPT TO SC 5) PERF. X CIRC. TO SURF., 6) DIG OUT X CUT OFF WEL	TAG CMT. PLU TAG CMT. PLU HOE T/SAI T-AI	CMT. PLUG. ATTACHED					
DURING THIS PROCEDURE THE REQUIRED DISPOSAL,	WE PLAN TO USE THE PER OCD RULE 19.15.	CLOSED-LC	OP SYSTEM W			• ,	
A	and the second of the second o			SEE AT	TACHED FOR	₹ '	
400 MARSON 3DS/8014				CONDI	TIONS OF AP	PROVAĽ	
14. I hereby certify that the foregoing is	Electronic Submission # For CIMAREX ENE	236861 verifie RGY CO OF C	d by the BLM We OLORADO, sent	II Information	System pad		
Name (Printed/Typed) DAVID A	Committed to AFMSS	ror processing	Title AGENT		2014 ()		
Signature (Electronic S	Submission)		Date 02/25/2		:		
	THIS SPACE FO	OR FEDERA		 	SE		
Approved By James	J. Omo _		Title 5	E.AS		3-12-19 Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent to conduct the conduction of the conducti	uitable title to those rights in the	s not warrant or e subject lease .	Office Co	20		/	

Cimarex Energy Co. of Colorado Amoco Federal 10 API 30-015-25720 1650' FNL & 990' FWL, Sec 27, T26S R29E Eddy County, NM GL:2881.4' KB: 2886.4' Spud: 1/20/87 8 5/8" 24# csg @ 485" Cmt-w/538 sx, circ to surface 12 1/4" hole to 485' **Tubing Detail** TOC EST @ 2076' Rod Detail Amoco Federal 10 **KB Controlon** DV Tool @ 3230' Delaware Perfs: 4886-87', 4889', 4898', 4900'-01', 4911'-12', 4918', 4921'-22', 4930'-31', 4936, 4938'-40', 5-1/2" 15.5# J55 LTC csg @ 5067' 4945'-46', 4950'-51', 4955', 4959', 4962'-63' Cmt w/480 sx 1 SPF, 25 holes 7 7/8" hole to TD 5067' PBTD: 5023' TD: 5073'



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Wexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Interim Reclamation Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses.

Interim reclamation consists of minimizing the footprint of disturbance by reclaiming all portions of the well site not needed for production operations. The portions of the cleared well site not needed for operational and safety purposes are recontoured to a final or intermediate contour that blends with the surrounding topography as much as possible. Sufficient level area remains for setup of a workover rig and to park equipment. Topsoil is respread over areas not needed for all-weather operations. Production facilities should be clustered to maximize the opportunity for interim reclamation. In order to inspect and operate the well or complete workover operations, it may be necessary to drive, park, and operate on restored, interim vegetation within the previously disturbed area. This is generally acceptable provided damage is repaired and reclaimed following use.

To reduce final reclamation costs; maintain healthy, biologically active topsoil; and to minimize habitat, visual, and forage loss during the life of the well, all salvaged topsoil should be spread over the area of interim reclamation, rather than stockpiled.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). Interim reclamation is to be completed within 6 months of well completion.
- .3. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with interim reclamation as per approved APD or Sundry Notice. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 4. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 5. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909 (Office), 575-361-2648 (Cell)

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen . Environmental Protection Specialist 575-234-5905

Mike Burton Environmental Protection Specialist 575-234-2226

Jeffery Robertson Natural Resource Specialist

Solomon Hughes . Natural Resource Specialist 575-234-5951

Douglas Hoag Civil Engineering Technician 575-234-5979