Form 3160-5

## UNITED STATES

FORM APPROVED

(August 2007)	DEPARTMENT OF THE I	IVILITION -	2 5 2014		O. 1004-0135 July 31, 2010
BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS DECEIVED  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				5. Lease Serial No. NMNM56429	
				6. If Indian, Allottee or Tribe Name	
SUBMIT II	N TRIPLICATE - Other instru	ctions on reverse side		7. If Unit or CA/Agre	ement, Name and/or No.
Type of Well	Other			8. Well Name and No. TRAVIS D FED 21	
Name of Operator ALAMO PERMIAN RES		9. API Well No. 30-015-24709-00-S1			
3a. Address 415 WEST WALL STRE MIDLAND, TX 79701	ET SUITE 500	3b. Phone No. (include area code) Ph: 432-897-0673		10. Field and Pool, or Exploratory LOCO HILLS	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State		
Sec 17 T18S R29E NW	SW 2030FSL 760FWL		EDDY COUNTY, NM		
12. CHECK	APPROPRIATE BOX(ES) T	O INDICATE NATUR		PORT, OR OTHE	R DATA
TYPE OF SUBMISSION		T			
	☐ Acidize	☐ Deepen	☐ Producti	on (Start/Resume)	☐ Water Shut-Off
☐ Notice of Intent	☐ Alter Casing <sup>*</sup>	☐ Fracture Treat	☐ Reclama	ition	■ Well Integrity
Subsequent Report	☐ Casing Repair	■ New Construct	nstruction		Other
☐ Final Abandonment No	ice Change Plans Convert to Injection	☑ Plug and Aban ☐ Plug Back	don 🗖 Tempora 🗖 Water D	arily Abandon pisposal	7-15-14
determined that the site is read 7/10/14 CONTACTED BOBBY V REMOVE; ND WH; NU 5-1/2" CSG SCRAPER OWASHED & ROTATED 7/11/14 MIRU WIRELINE; RIH V & RIH W/ 4-3/4" BIT & 5 TAGGED FILL HIGH AT	N/ BLM-RU APPROVED; MIR BOP; MOVE IN OFF LOADED ON 2-3/8" WS; SOFT TAG FIL DWN & COULD NOT WORK N/ WL; SET 5-1/2" X 15.5# CII 1-1/2" CSG SCRAPER; WORK 1-2067"; PU SWIVEL & CIRC II 075"; PU & SET CIBP @ 2074 S & SPOT 35 SKS CLASS C N	U; TRY TO BREAK TOP 0 72 JTS 2-3/8" WS & SI L @ 2072'; RU SWIVEL PAST 2096'; PLUGGED BP, HIT TIGHT SPOT IN THRU TIGHT SPOT IN DWN TO 2087'; CIRC W I' (OK'D BY BLM); POOI NEAT CMT UP TO 1731 #253175 verified by the B	P CAP OFF WH; WET ON PIPE RACK L, KILL TRK ON WED BIT; POOH W/ TE L CSG @ 1799; POUS & CONT RUI ELL CLEAN W/ 65 L & RD WL; RIH W L; PULL UP TO 150  LM Well Information sent to the Carlsba	AIT ON WELDER (S; PU 4-3/4" BIT, ELL & BREAK CIR( G) PULLING WET; DOH W/ CIBP; PU NNING IN HOLE; BBLS FW; POOH (/ OE 2-3/8" WS TO (0) & REVERSED C	TO HEAT CAP & C; SWI; SDON W/
Name (Printed/Typed) CAF	RIE STOKER	Title F	REGULATORY AFF	AIRS COORDINA	TOR
Signature (Elec	tronic Submission)	<del></del>	7/15/2014		
	THIS SPACE F	OR FEDERAL OR S	TATE OFFICE US	SE	,
_Approved By_JAMES A AMQS			PERVISOR EPS		Date 07/21/2014
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			arisbad		·
Title 18 U.S.C. Section 1001 and 7	Title 43 U.S.C. Section 1212, make it	a crime for any person knowi	ngly and willfully to ma	ke to any department o	r agency of the United

Accepted as to plugging of the Well Bore.\* BLM REVISED \*\* BLM REVI



## Additional data for EC transaction #253175 that would not fit on the form

## 32. Additional remarks, continued

OF TBG; WOC 4 HRS; RIH TAGGED PLUG @ 1717'; PU & CIRC 19 BBLS 9# PLUG MUD; PUMP FW SPACER & PUMPED 25 SKS CLASS C NEAT CMT FRM 927' UP TO 679'; PUH TO 400' & REVERSED OUT CMT; POOH W/ 10 STANDS. SWI. SDOWE.

7/14/14 RIH W/ 2-3/8' TBG; TAG CMT @ 590'; PUH TO 450' PUMPED 55 SX CLASS C NEAT CMT; CIRC TO SURF; POOH LAYING DWN WS; TOP OFF CMT; WASH OUT LINES & PUMP; WASH CMT OFF ALL EQUIPMENT & ID OF WS; CLEAN LOC & WAIT ON CMT; CMT DROPPED 2"; RDMO

7/15/14
SET DRY HOLE MARKER (OK'D BY BLM)SEE ATTACHED PICTURE; WELL PLUGGED