Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMLC054988B 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agre	ement, Name and/or No.	
1. Type of Well Gas Well Other				8. Well Name and No. JENKINS B FEDERAL 8		
Name of Operator Contact: KANICIA CASTILLO COG OPERATING LLC E-Mail: kcastillo@concho.com				9. API Well No. 30-015-29388-00-S1		
3a. Address ONE CONCHO CENTER 600 W ILLINOIS AVENUE MIDLAND, TX 79701 3b. Phone No. (include area code) Ph: 432-685-4332				10. Field and Pool, or Exploratory GRAYBURG		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, and State		
Sec 20 T17S R30E SENW 2310FNL 1650FWL				ÉDDY COUNTY, NM		
		,				
12. CHECK APP	ROPRIATE BOX(ES) TO IN	DICATE NATURE OF I	NOTICE, REI	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume) ☐ Water Shut-Off			
-	☐ Alter Casing	☐ Fracture Treat `	□ Reclamation☑ Recomplete		■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction			☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon			
	☐ Convert to Injection	☐ Plug Back	☐ Water Dis	posal		
Attach the Bond under which the wo following completion of the involved	ally or recomplete horizontally, give rk will be performed or provide the E I operations. If the operation results i bandonment Notices shall be filed on	subsurface locations and measu Bond No. on file with BLM/BIA in a multiple completion or reco	ared and true verti A. Required subsempletion in a never propertion in a never in a ne	cal depths of all pertin equent reports shall be v interval, a Form 316	ent markers and zones. filed within 30 days 0-4 shall be filed once	
COG Operating LLC respectful	ally requests to recomplete this	s well to the San Andres	as foliows:	SUMMIT IN	m (-10g)	
	Minimum after deal	APPI ods and pump we top most perf) 30 SX Tag. Sac	SEE	ATTACHE	ARTESIA DISTRICT OCT 0 3 2014 DFORECEIVED OF APPROVAL	

14. I hereby certify that the foregoing is true and correct. NMOCD Electronic Submission #251625 verified by the BLM Well Information System
For COG OPERATING LLC, sent to the Carlsbad
Committed to AFMSS for processing by JENNIFER MASON on 09/30/2014 (14JAM0411SE) PREPARER Name(Printed/Typed) KANICIA CASTILLO **APPROVED** (Electronic Submission) Signature Date 07/03/2014 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved By Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease AU OF LANZ CARLSBAD FIELD OFFICE which would entitle the applicant to conduct operations thereon. Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #251625 that would not fit on the form

32. Additional remarks, continued

- ? Test Casing to 4,200 psi and report back to engineering if the pressure holds.
- ? Secure wellbore ? RDMO WSU

Tentative Recompletion Procedure

- ? NU frac valve, and test casing to 4200 psi
- ? Rig.up wireline.
- ? RIH w/ perforating guns and perforate San Andres Zone from 3418?-3616? w/ 3 spf, 60? phasing, 51 holes.
 ? Acidize w/ 1500 gals of 15% HCl.
 ? Frac zone w/ 181,250 # of sand.
 ? Record ISIP and FG, Get 5, 10, 15 min SIP
 ? Rig up Wireline
 ? RIH w/ WL and set Composite Plug @ 3400?
 ? Perforate San Andres Zone from 3146?-3310? w/ 3 spf, 60? phasing, 51 holes.
 ? Acidize w/ 1500 gals of 15% HCl.
 ? Frac zone w/ 181,250 # of sand.
 ? Record ISIP and FG, Get 5, 10, 15 min SIP
 ? RU WSU
 ? RIH with Production tbg and tag for fill w/ bailer at knocked Composite plug @ 3400?
 ? Clean out fill to new PBTD @ 4260?
 ? POOH bailer and tbg
 RIH with production tubing and locate intake at 3650?.
 ? Set TAC @ 3000?
 ? RIH w/ rods and pump.
 ? RDMO rig. holes.

- ? RDMO riq.

COG Operating LLC

Lease & Well #

Jenkins B Federal #8

Sec 20F, 17S, 30E, Eddy Co., NM

8 5/8" 24# J-55 @ 470', 350 sx cmt, circ. 20 sx

Spud: 10/10/97 3001529451 Elevation - 3639'

KB -

- 1

Marker jt - 3262'

DV tool - 4003'

Yeso

4331 - 4729.5' , 62 holes Acidized w/3500 gal 15% HCl Treat w/32,000 gal 20% HCL, 54,000 gal LG, 5,000 gal 15% HCL

. PBTD - 4772'

1st stage: 150 sx 50/50/2 CL C, circ 61 sx

2nd stage: 650 sx 35/65/6 CL C, 350sx 50/50/2,circ 113 sx

5 1/2" 17# csg @ 4783'.

COG Operating LLC

Lease & Well

Jenkins B Federal #8

Spud: 10/10/97 3001529451

Elevation - 3639'

8 5/8" 24# J-55 @ 470', 350 sx cmt, circ. 20 sx

Sec 20F, 17S, 30E, Eddy Co., NM

KB -

3146'-3310' w/ 3 spf, 60° phasing, 53 holes Acidize w/ 1500 gals of 15% HCl. Frac zone w/ 181,250 # of sand

Marker jt - 3262'

DV tool - 4003'

3418'-3616' w/ 3 spf, 60° phasing, 53 holes.

Acidize w/ 1500 gals of 15% HCI. Frac zone w/ 181,250 # of sand

CIBP @ 4300' w/ 40' of CMT to 4260'

Yeso

4331 - 4729.5', 62 holes Acidized w/3500 gal 15% HCI Treat w/32,000 gal 20% HCL, 54,000 gal LG, 5,000 gal 15% HCL

PBTD - 4772'

1st stage: 150 sx 50/50/2 CL C, circ 61 sx

2nd stage: 650 sx 35/65/6 CL C, 350sx 50/50/2,circ 113 sx

5 1/2" 17# csg @ 4783'.

Jenkins B Federal 8 30-015-29388 COG Operating, LLC. September 30, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by December 30, 2014.

- 1. Operator shall set a CIBP at 4,250' and place 30sx Class C cement on top. Tag required at a minimum of 3,950' to seal the top of the Glorietta and DV tool.
- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a **2000** (**2M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 9. Subsequent sundry required detailing work done and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 10. See attached for general requirements.

JAM 093014

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat** Class "C", for up to 7,500 feet of depth or **Neat** Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.