Form 3160-5 (August 2007) OCD Artesia

**UNITED STATES** DEPARTMENT OF THE INTERIOR

## BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS not use this form for proposals to drill or to re-enter

FORM APPROVED OMB NO. 1004-0135

		Expires:	July 3	1,201	.0	
5.		erial No. 1101113				
_	TOT II	. 11	- T. 11			

abandoned we	ell. Use form 3160-3 (APD)	for such proposals.	6. If Indian, Allotte	e or Tribe Name
SUBMIT IN TRI	IPLICATE - Other instruction	ons on reverse side.	7. If Unit or CA/Ag	greement, Name and/or No.
1. Type of Well			8. Well Name and N BELLATRIX 28	
Oil Well Gas Well Otl		AVID H COOK	9. API Well No.	
DEVON ENERGY PRODUCT	FION CO EPMail: david.cook@d	dvn.com	30-015-42371	I-00-X1
3a. Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 7310	. [F	Bb. Phone No. (include area cod Ph: 405-552-7848	de) 10. Field and Pool, GATUNA CA	or Exploratory NYON
4. Location of Well (Footage, Sec., 7	r., R., M., or Survey Description)		11. County or Paris	h, and State
Sec 29 T19S R31E NESE 13: 32.627877 N Lat, 103.883311			EDDY COUN	TY, NM
12. CHECK APPI	ROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION		TYPE	OF ACTION	
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Fracture Treat	□ Reclamation	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	Other
☐ Final Abandonment Notice	Change Plans	Plug and Abandon	□ Temporarily Abandon	Change to Original A PD
	Convert to Injection	☐ Plug Back	☐ Water Disposal	
Devon Energy Production Corproduction string of 7" x 5.5" conditions permits. If lost circles 5-1/2" production longstring.  Please see the attached Casin production string and the 5-1/2"	asing to a total depth of 13,2 ulation is encountered we wi	206 ft measured depth as ill stay as originally planne esign for both the 7" x 5-1	long as hole ed to run a SEE ATTAC /2" taperedCONDITION	HED FOR IS OF APPROV
	•	ADD 2/16/15 ACCOPTED XX TOCOT NEADCD	d NM OIL CO	ONSERVATION IA DISTRICT
				2 0 2015
14. I hereby certify that the foregoing is  Common Name (Printed/Typed) DAVID H (	Electronic Submission #287 For DEVON ENERGY ! mitted to AFMSS for processi	PRODUCTION CO LP, sen ng by JENNIFER MASON o	ell Information System t to the Carlsbad on 01/12/2015 (15JAM0177SE)	EIVED
- Company Briving 19		· · · · · · · · · · · · · · · · · · ·	ADDDOVE L	1
Signature (Electronic S	Submission)	Date 01/12/	2D15 APPROVEL	)
	THIS SPACE FOR	FEDERAL OR STATE		
Approved By		Title	JAW A 2 2010	Marie
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the subct operations thereon.	oject lease Office	BUREAU OF LAND MANAGE CARLSBAD FIELD OFFI	
Title 18 U.S.C. Section 1001 and Title 43 V States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crin statements or representations as to a	ne for any person knowingly an any matter within its jurisdiction	d willfully to make to any department on.	or agency of the United
	-			

## Bellatrix 28 Fed Com 8H - Sundry Request

AAA 1-9-2015: Add option for a 7" x 5.5" Combination Production String

## **Sundry Request:**

Devon Energy Production Company, L.P. respectfully requests adding the option to run a tapered production string of 7" x 5.5" casing to a total depth of 13,206 ft measured depth as long as hole conditions permits. If lost circulation is encountered we will stay as originally planned to run a 5-1/2" production longstring. Casing design requirements are below as well as the cement design for both the 7" x 5-1/2" tapered production string and the 5-1/2" production longstring.

Casing Program Changes: 7" x 5.5" Tapered Production String

Hole Size	Hole Interval	OD Csg	Csg Casing Interval		Collar	Grade	
8-3/4"	4250 - 7586	7"	0 - 7586	29#	BTC	P-110	
8-3/4"	7586 - 13206	5-1/2"	7586 - 13206	17#	втс	P-110	

Original Option: 5.5 Production Longstring

	Hole Size	Hole Interval	OD Csg	Casing Interval	Weight	Collar	Grade
- [	8-3/4"	0 - 13206	5-1/2"	0 - 13206	17#	BTC	P-110

Note: only new casing will be utilized

MAXIMUM LATERAL TVD 8,279

Design Factors: 7" x 5.5" Tapered Production String

	Casing Size	Collapse Design Factor	Burst Design Factor	Tension Design Factor	
Ī	7" 29# P-110 BTC	2.40	3.16	4.22	
	5-1/2" 17# P-110 BTC	1.93	2.75	5.71	

Original Option: 5.5 Production Longstring

Casing Size	Collapse Design Factor	Burst Design Factor	Tension Design Factor
5-1/2" 17# P-110 BTC	1.93	2.75	2.43

## **CEMENTING TABLE:**

String	Number of sx	Weight Ibs/gal	Water Volume g/sx	Yield cf/sx	Stage; Lead/Tail	Slurry Description
70 - 4/00	190	11.80	13.16	2.30	i <sup>st</sup> Lead	(50:50) Poz (Fly Ash):Class H + 0.5% bwoc FL-52 + 0.3% bwoc ASA-301 + 10% bwoc Bentonite + 0.35% bwoc R-21 + 130.7% Fresh Water
7" x 5-1/2" Production Casing Single Stage	200	12.50	11.01	2.01	2 <sup>nd</sup> Lead	(35:65) Poz (Fly Ash):Prem Plus H + 3% bwow Sodium Chloride + 0.2% bwoc R-3 + 0.125 lbs/sack Cello Flake + 0.7% bwoc FL- 52 + 0.3% bwoc ASA-301 + 6% bwoc Bentonite + 105.5% Fresh Water
Jingle Stage	1370	14.20	5.77	1.28	Tail	(50:50) Poz (Fly Ash):Class H + 5% bwow Sodium Chloride + 0.3% bwoc CD-32 + 0.5% bwoc FL-25 + 0.4% bwoc FL-52 + 0.5% bwoc Sodium Metasilicate + 57.3% Fresh Water

## **TOC** for all Strings:

Production

@

2435' (Cement top will tie-back 50' above Capitan Reef estimated at 2485')

#### Notes:

- Cement volumes Production based on at least 25% excess
- Actual cement volumes will be adjusted based on fluid caliper and caliper log data
- If lost circulation is encountered while drilling the production wellbore, the 5.5" original production longstring will be used with a DV tool installed a minimum of 50' below the previous casing shoe and of 200' above the current shoe. If the DV tool has to be moved, the cement volumes will be adjusted proportionately.

# PECOS DISTRICT CONDITIONS OF APPROVAL

**OPERATOR'S NAME:** | Devon Energy Production Company, L.P.

**LEASE NO.: | NMNM-101113** 

WELL NAME & NO.: | Bellatrix 28 Fed Com 8H SURFACE HOLE FOOTAGE: | 1358' FSL & 0163' FEL

BOTTOM HOLE FOOTAGE | 0930' FSL & 0340' FEL Sec. 28, T. 19 S., R 31 E.

LOCATION: | Section 29, T. 19 S., R 31 E., NMPM

**COUNTY:** Eddy County, New Mexico

API: 30-015-42371

## The original COAs still stand with the following drilling modifications:

## I. DRILLING

## A. DRILLING OPERATIONS REQUIREMENTS

The BLM is to be notified in advance for a representative to witness:

- a. Spudding well (minimum of 24 hours)
- b. Setting and/or Cementing of all casing strings (minimum of 4 hours)
- c. BOPE tests (minimum of 4 hours)

## **Eddy County**

Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822

- 1. A Hydrogen Sulfide (H2S) Drilling Plan shall be activated 500 feet prior to drilling into the Yates formation. As a result, the Hydrogen Sulfide area must meet Onshore Order 6 requirements, which includes equipment and personnel/public protection items. If Hydrogen Sulfide is encountered, please provide measured values and formations to the BLM. Operator has stated that they will have monitoring equipment in place prior to drilling out of the surface shoe.
- 2. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval. If the drilling rig is removed without approval an Incident of Non-Compliance will be written and will be a "Major" violation.
- 3. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works is located, this does not include the dog house or stairway area.

4. The record of the drilling rate along with the GR/N well log run from TD to surface (horizontal well – vertical portion of hole) shall be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

#### B. CASING

Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.).

Centralizers required on surface casing per Onshore Order 2.III.B.1.f.

Wait on cement (WOC) time prior to drilling out for a primary cement job will be a minimum 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compressive strength, whichever is greater for all casing strings. DURING THIS WOC TIME, NO DRILL PIPE, ETC. SHALL BE RUN IN THE HOLE. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing each casing string. See individual casing strings for details regarding lead cement slurry requirements.

No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.

#### Capitan Reef

Possibility of water flows in the Artesia Group, Salado, and Capitan Reef. Possibility of lost circulation in the Red Beds, Rustler, Artesia Group, Capitan Reef, and Delaware.

- 1. The 20 inch surface casing shall be set at approximately 600 feet (a minimum of 25 feet into the Rustler Anhydrite and above the salt) and cemented to the surface. If salt is encountered, set casing at least 25 feet above the salt.
  - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.

- b. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry.
- c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- d. If cement falls back, remedial cementing will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the 13-3/8 inch 1<sup>st</sup> intermediate casing is:
  - Ement to surface. If cement does not circulate see B.1.a, c-d above.
- 3. The minimum required fill of cement behind the 9-5/8 inch 2<sup>nd</sup> intermediate casing is:

Operator has proposed DV tool at depth of 2450'. Operator is to submit sundry if DV tool depth varies by more than 100' from approved depth.

- a. First stage to DV tool:
- Ement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with second stage cement job. Operator should have plans as to how they will achieve circulation the next stage.
- b. Second stage above DV tool:
- □ Cement to surface. If cement does not circulate see B.1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to Capitan Reef. Excess calculates to 4% Additional cement may be required.

Centralizers required on horizontal leg, must be type for horizontal service and a minimum of one every other joint.

## 4. Production Casing Options:

## Option #1:

The minimum required fill of cement behind the 5-1/2 inch production casing is:

Operator has proposed DV tool at depth of 5500', but will adjust cement proportionately if moved. DV tool shall be set a minimum of 50' below previous shoe and a minimum of 200' above current shoe. Operator shall submit sundry if DV tool depth cannot be set in this range.

- a. First stage to DV tool:
- □ Cement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with second stage cement job. Operator should have plans as to how they will achieve approved top of cement on the next stage. Excess calculates to 14% Additional cement may be required.
- b. Second stage above DV tool:
- □ Cement should tie-back at least 50 feet above the Capitan Reef. Operator shall provide method of verification. Excess calculates to 14% Additional cement may be required.

## Option #2:

The minimum required fill of cement behind the 7 X 5-1/2 inch production casing is:

- Cement should tie-back at least 50 feet above the Capitan Reef. Operator shall provide method of verification.
- 5. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

## C. PRESSURE CONTROL

1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.

- 2. Variance approved to use flex line from BOP to choke manifold. Check condition of flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer's requirements. The flexible hose can be exchanged with a hose of equal size and equal or greater pressure rating. Anchor requirements, specification sheet and hydrostatic pressure test certification matching the hose in service, to be onsite for review. These documents shall be posted in the company man's trailer and on the rig floor. If the BLM inspector questions the straightness of the hose, a BLM engineer will be contacted and will review in the field or via picture supplied by inspector to determine if changes are required (operator shall expect delays if this occurs).
- 3. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **2000** (**2M**) psi.
  - a. For surface casing only: If the BOP/BOPE is to be tested against casing, the wait on cement (WOC) time for that casing is to be met (see WOC statement at start of casing section). Independent service company required.
- 4. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the 13-3/8 1<sup>st</sup> intermediate casing shoe shall be 3000 (3M) psi.
- 5. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
  - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips, the minimum wait time before cut-off is eight hours after bumping the plug. BOP/BOPE testing can begin after cut-off or once cement reaches 500 psi compressive strength (including lead when specified), whichever is greater. However, if the float does not hold, cut-off cannot be initiated until cement reaches 500 psi compressive strength (including lead when specified).
  - b. The tests shall be done by an independent service company utilizing a test plug **not** a **cup** or **J-packer**. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (18 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).

- c. The test shall be run on a 5000 psi chart for a 2-3M BOP/BOP, on a 10000 psi chart for a 5M BOP/BOPE and on a 15000 psi chart for a 10M BOP/BOPE. If a linear chart is used, it shall be a one hour chart. A circular chart shall have a maximum 2 hour clock. If a twelve hour or twenty-four hour chart is used, tester shall make a notation that it is run with a two hour clock.
- d. The results of the test shall be reported to the appropriate BLM office.
- e. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- f. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug. This test shall be performed prior to the test at full stack pressure.

### D. DRILL STEM TEST

If drill stem tests are performed, Onshore Order 2.III.D shall be followed.

#### E. WASTE MATERIAL AND FLUIDS

All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area.

Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

JAM 011215