Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135

Ex	pire.	s: .	uly	3
Lease Serial I	Vo.			
NMI C0293	195	R		

SUNDRY NOTICES AND REPORTS ON WELLS

D	in forms for municipals to	almill an Am o			1	•	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.		7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well State Oil Well Gas Well Other			8. Well Name and No. LEE FEDERAL 78				
Name of Operator APACHE CORPORATION E-Mail: sandra.belt@apachecorp.com Contact: SANDRA J BELT E-Mail: sandra.belt@apachecorp.com				9. API Well No. 30-015-42189			
3a. Address 3b. Phone N 303 VETERANS AIRPARK LANE Ph: 432-8 MIDLAND, TX 79705 Fx: 432-81					10. Field and Pool, or Exploratory CEDAR LAKE; GLORIETA-YESO		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish	, and State	
Sec 20 T17S R31E 2125FSL 2345FEL 32.818646 N Lat, 103.890982 W Lon					EDDY COUN	ΓY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATI	E NATURE OF N	IOTICE, RI	EPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	☐ De	epen	☐ Producti	ion (Start/Resume)	■ Water Shut-Off	
	Alter Casing	☐ Fra	cture Treat	☐ Reclama	ation	■ Well Integrity	
Subsequent Report	□ Casing Repair	☐ Ne	w Construction	□ Recomp	lete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plu	g and Abandon	□ Tempora	arily Abandon	Production Start-up	
	□ Convert to Injection	🗖 Plu	g Back	☐ Water D	isposal	•	
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final Abdetermined that the site is ready for final Apache Corporation wishes to 5/27/14: Perforate the Lower 48, 62, 70, 90 & 62087. 5/28/1 acid.6/9/14: STAGE 1: RU Ba 44, 68, 80, 98, 6121, 48, 62, 7 Spot 1000 GAL 15% HCL. Standard	operations. If the operation respandonment Notices shall be file in all inspection.) report the completion of the interpretation of	this well as f 0, 28, 50, 83, from 5900'- nebry zone 035# 16/30 I 1/ 5 1/2 CBP 70, 96, 541 , 30 & 49? 2 5250, 80, 5	ele completion or reco requirements, includi ollows: 94, 6017, 44, 68, 6208' W/ 3397 G/ @ 5900, 10, 28, 5 Brown, 31,094# 16 & 3 1/8 Tag Gun: 7, 30, 38, 55, 74, 9 Pump 3,570 Gal 5306, 25, 50, 70, 9	mpletion in a n ng reclamation . 80, 98, 612 ALS 15% HC 0, 83, 94,60 6/30 SIBER s. Set CBP 98, 5516, 36 15% 96, 5417, 30	ew interval, a Form 31, have been completed (ACC). All	60-4 shall be filed once l, and the operator has	
14. I hereby certify that the foregoing is	Electronic Submission #2 For APACHE Committed to AFMSS fo	80958 verifie CORPORAT or processing	ON, sent to the C by DEBORAH HA	arlsbad M on 01/16/2	ACCEPTED	FOR RECORD	
Name(Printed/Typed) SANDRA	BELI		Title SR. REG	GULATORY	ANALYST		
Signature (Electronic S	ubmission)		Date 11/20/20	14	NAC	2 8 2015	
	THIS SPACE FO	R FEDERA	L OR STATE C	FFICE US		ale Have	
1					BUREAU OF LA	ND MANAGEMENT FIELD OFFICE	
Approved By			Title	L	ONICODAD	ILLL ARTICE	
Conditions of approval, if any, are attached certify that the applicant holds legal or equal which would entitle the applicant to conduct	itable title to those rights in the	not warrant or subject lease	Office				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #280958 that would not fit on the form

32. Additional remarks, continued

CBP & 3 1/8 Tag Guns. Set CBP @ 5,230' perforate the Paddock/Glorieta @ 4718, 28, 34, 66, 76, 96, 4812, 29, 47, 70, 99, 4917, 49, 70, 5004, 28, 44, 53, 72, 91, 5104, 18, 36, 56 & 88?. Break down perfs @ 1,433#, Pump 3,738 Gals 15% HCL. RU Baker Hughes, frac the Paddock/Glorieta @ 4718, 28, 34, 66, 76, 96, 4812, 29, 47, 70, 99, 4917, 49, 70, 5004, 28, 44, 53, 72, 91, 5104, 18, 36, 56 & 88?. Pump 191,191# 16/30 Brown, 40,915# 16/30 Siber Prop. 6/11/14: Prep To DO CBPs & Circ Hole Clean To PBTD. 6/12/14: Tag sand @ 5091'. RU swivel. Break circ & wash sand. RIH w/bit & tag up on CBP @ 5230'. DO CBP. RIH w/bit & tag up on sand @ 5807'. Break circ & wash sand. Tag CBP @ 5875'. DO CBP. RIH. Tag sand @ 6242'. Break circ & wash sand to PBTD @ 6380'. Circ clean. Prep to RIH w/ prod equip

prod equip.

6/13/14: RIH W/ 2-7/8" J-55 TBG. ETD @ 6312.87' RKB. SN @ 6222.85' RKB. TAC Set @ 4626.28'.

Prep TO RIH W/ Pump & Rods. 6/16/14: Load Tbg & Psi Test to 500#. Clean location & RDMOSU. Build wellhead & lay flowline. SD.

SI Well. SDFN. Prep to set pumping unit @ later date. 6/23/14: Set New Ampscot 640-365-168 Pumping Unit. Install electric & start production to battery.