Comm 3163-5 (Spril 2004) UNITED STATES DEPARTMENT OF THE INTERIO BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS O Do not use this form for proposals to drill or abandoned well. Use Form 3160-3 (APD) for s SUBMIT IN TRIPLICATE- Other instructions o	MAR 0 2 2015 5. Lease Serial No. SN WELLS NMNM68040 to re-eRECAPTIVED 6. If Indian, Allottee or Tribe Name
DEPARTMENT OF THE INTERIO BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS O Do not use this form for proposals to drill or abandoned well. Use Form 3160-3 (APD) for s SUBMIT IN TRIPLICATE- Other instructions o	MAR 0 2 2015 5. Lease Serial No. DN WELLS NMNM68040 to re-eRTECAPIL/ED 6. If Indian, Allottee or Tribe Name
SUNDRY NOTICES AND REPORTS O Do not use this form for proposals to drill or abandoned well. Use Form 3160-3 (APD) for s SUBMIT IN TRIPLICATE- Other instructions o	MAR 0 2 2015 5. Lease Serial No. DN WELLS NMNM68040 to re-eRTECAPIL/ED 6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or abandoned well. Use Form 3160-3 (APD) for s SUBMIT IN TRIPLICATE- Other instructions o	to re-entermit/FD 6. If Indian, Allottee or Tribe Name
abandoned well. Use Form 3160 - 3 (APD) for s SUBMIT IN TRIPLICATE- Other instructions o	
	such proposals.
1	7. If Unit or CA/Agreement, Name and/or No. Parker Federal
1. Type of Well Oil Well O Gas Well O Other	8. Well Name and No. Parker Deep 5 Federal Com #3
2. Name of Operator NADEL AND GUSSMAN HEYCO, LLC	9. API Well No.
3a. Address 3b. Phone N PO BOX 1936 ~ ROSWELL NM 88202-1936 575.623.0	No. (incluide area code) 3001532555 6601 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Shugart; Strawn
690' FSL & 1980' FWL, Sec. 5 SESW, T18S, R31E	11. County or Parish, State Eddy, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE	NATURE OF NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION
Acidize Deepen Acidize Acidize Fracture 1	Treat Production (Start/Resume) Water Shut-Off Well Integrity
	Instruction Recomplete Change of Operator
Final Abandonment Notice Change Plans Plug and plu	
testing has been completed. Final Abandonment Notices shall be filed only after determined that the site is ready for final inspection.)	altiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once r all requirements, including reclamation, have been completed, and the operator has
This is a notification of Change of Operator on the above referenced	well.
Harvey E. Yates Company, as new operator, accept all applicable ter conducted on this lease or portion of lease described.	rms, conditions, stipulations and restrictions concerning operatings
BLM Bond No. NMB000317 Harvey E. Yates Company	
P.O. Box 1933 Roswell, NM 88202-1933	SEE ATTACHED FOR
Change of Operator EFFECTIVE 9/1/2014	
Change of Operator EFFECTIVE 9/1/2014	CONDITIONS OF APPROVA
Accepted for record	
 I hereby certify that the foregoing is true and correct Name (Printed/Typed) 	
Tammy R. Link	Title Production Tech
Signature R. Link	Date 109/10/2014.0V/10
THIS SPACE FOR FEDERA	L OR STATE OFFICE USE
Approved by	
certify that the applicant holds legal or equitable title to those rights in the subject l	lease Office BURYAU OF LANDAMANAGLINENT

Į

BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE 620 E. Greene St Carlsbad, NM 88220 Ph: (575) 234-5972

Conditions of Approval for Change of Operator

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.