		OCD Artesi	a
Form 3160-5 (April 2004) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.ED			FORM APPROVED         OM B No. 1004-0137         Expires: March 31, 2007         5. Lease Serial No.         NMLC029393A         6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No. Arco 8 Fed
1. Type of Well Oil Well II Gas Well III Other			8. Well Name and No.
2. Name of Operator NADEL AND GUSSMAN HEYCO, LLC.			Arco 8 Federal #5 9. API Well No.
3a. Address         3b. Phone No. (include area code)           PO BOX 1936 ~ ROSWELL NM 88202-1936         575.623.6601			3001527213 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Shugart; Bone Spring North
			11. County or Parish, State
1980' FSL & 660' FWL, Sec. 8 NWSW, T18S, R31E			Eddy, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION TYPE OF ACTION			
Notice of Intent	Casing Repair New (	rn Production (S re Treat Reclamation Construction Recomplete Ind Abandon Temporarily	Well Integrity Other Change of Operator
Final Abandonment Notice	Convert to Injection Plug E	Back Water Dispos	al
If the proposal is to deepen dir Attach the Bond under which the following completion of the in testing has been completed. F determined that the site is read <b>This is a notification of C</b>	ectionally or recomplete horizontally, give sub the work will be performed or provide the Bon wolved operations. If the operation results in a inal Abandonment Notices shall be filed only a	surface locations and measured and d No. on file with BLM/BIA. Requ multiple completion or recompletio after all requirements, including recla sed well.	any proposed work and approximate duration thereof. true vertical depths of all pertinent markers and zones. nired subsequent reports shall be filed within 30 days n in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has
conducted on this lease of BLM Bond No. NMB000 Harvey E. Yates Compan P.O. Box 1933	r portion of lease described. 317 By		
P.O. Box 1933 Roswell, NM 88202-1933 Change of Operator EFFECTIVE 9/1/2014 ACCEPTED STATE CONDITIONS OF APPROVAL MIACCO			
14. I hereby certify that the form Name (Printed/Typed) Tammy R. Link		Title Production Tech	
Signature	m & Sid	Date	09/10/2014 APPROVED
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
		m:	FEB 2 4/2015
	attached. Approval of this notice does not w al or equitable title to those rights in the subje to conduct operations thereon.		BURT O UF LAW MANAGEMENT
Title 19 11 5 C. Section 1001 and Title 42 11 5 C. Section 1212, make it a grime for any person transvinely, and will fully to make the any demonstration are seen of the United			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Ś

r

ţ

## BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE 620 E. Greene St Carlsbad, NM 88220 Ph: (575) 234-5972

## Conditions of Approval for Change of Operator

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.

う

- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.