<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

## **NM OIL CONSERVATION**

ARTESIA DISTRICT Form C-141

MAY 1 3 2015 Revised August 8, 2011
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## **Release Notification and Corrective Action**

						OPERAT	OR		Initial	Report	$\boxtimes$	Final Report		
Name of Co	mpany: Bo	Contact: Tony Savoie												
Address: 52			Telephone No. 575-887-7329											
Facility Nan #34H) FWK	_		Facility Type: Exploration and Production											
Surface Ow	ner: State	vner:	State and Federal API No. 30-015-42008											
				<u> </u>					<u></u> -		-			
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County:														
P	21	218	30E	rect nom the	NOI till	South Ellic	Teet from the	Last	Vest Ellie	Eddy				
Latitude N 32.456585 Longitude W 103.879241														
NATURE OF RELEASE														
Type of Release: Crude oil and produced water											ime Recovered: 3 bbls crude oil and ls produced water			
Source of Release: Heater-treater							Date and Hour of Occurrence:			Date and Hour of Discovery: 2/9/15 at				
							2/9/15 time unknown approx. 8:2							
Was Immediate Notice Given?   ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Heather Patterson, in person.								
By Whom? Tony Savoie						Date and Hour: 2/9/15 at 10:20 a.m.								
Was a Watercourse Reached?  ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.								
If a Watercourse was Impacted, Describe Fully.*														
· · · · · · · · · · · · · · · · · · ·														
Describe Cause of Problem and Remedial Action Taken.*  A gasket failed on the free water knock out man-way plate. The vessel was by-passed and the gasket was replaced. All free standing fluid was removed with a vacuum truck.														
Describe Area Affected and Cleanup Action Taken.*  The spill impacted an area that had just been backfilled on a remediation for spill reference 2RP-2615. Basin Environmental and a roustabout crew started removing the impacted soil the day of discovery. The equipment has been washed-down; the misted pasture area will be washed and treated with microblaze. The remediation activity will continue until the site meets the NMOCD remediation requirements established in the original remediation plan.  The spill remediation was continued on 2/9/15, the field activities were completed on 3/6/15, following backfill approval on 3/4/15. Please find the attached Soil Closure Request prepared by Basin Environmental dated May 2015.														
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.														
					OIL CONSERVATION DIVISION									
Signature: Day Sauce							Americand by Engirenmental Specialists							
Printed Name: Tony Savoie							Approved by Environmental Specialist:							
Title: Waste Management and Remediation Specialist							Approval Date: 5/13/15 Expiration Date: NA							
E-mail Address: tasavoie@basspet.com						Conditions of Approval:  Attached								
Date: 5/13/15 Phone: 432-556-8730														