NM OIL CONSERVATION

--Form 3160-5


ARTESIA DISTICO Artesia FORM APPROVED UNITED STATES (August 2007) OMB NO. 1004-0135 DEPARTMENT OF THE INTERIOR UL 29 2015Expires: July 31, 2010 BUREAU OF LAND MANAGEMENT Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to receive the NMLC029395B 6. If Indian, Allottee or Tribe Name. abandoned well. Use form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side. 8. Well Name and No. TURNER B 40 1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other Name of Operator Contact: LAURA A MORENO API Well No LINN OPERATING INCORPORATED E-Mail: Imoreno@linnenergy.com 30-015-05194-00-S1 3b. Phone No. (include area code) 10. Field and Pool, or Exploratory 600 TRAVIS STREET SUITE 5100 Ph: 713.904.6657 GRAYBURG Fx: 832.209.4316 HOUSTON, TX 77002 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, and State EDDY COUNTY, NM Sec 17 T17S R31E NWSW 1650FSL 990FWL 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize Deepen □ Production (Start/Resume) ☐ Water Shut-Off ☐ Fracture Treat ☐ Well Integrity ☐ Alter Casing □ Reclamation ☐ Subsequent Report □ Casing Repair ■ New Construction ☐ Recomplete □ Other □ Change Plans □ Plug and Abandon ☐ Final Abandonment Notice ▼ Temporarily Abandon ☐ Convert to Injection □ Plug Back ☐ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Based on the attached successful attached MIT chart, LINN respectfully requests a one year extension of the current TA status. A reservoir study has been conducted to determine and quantify remaining potential in the area. At this time, the most promising project is an extension of the existing Seven Rivers Flood in the area of the subject well. LINN is working towards submitting a C-108 application for injector conversions and/or new injector drilling within the next twelve months MIT See COAS FORTA CONDITIONS OF APPROVAL 14. I hereby certify that the foregoing is true and correct. Electronic Submission #287228 verified by the BLM Well Information System For LINN OPERATING INCORPORATED, sent to the Carlsbad Committed to AFMSS for processing by JAMES AMOS on 01/08/2015 (15JA0166SE) Name (Printed/Typed) LAURA A MORENO Title REG COMPLIANCE ADVISOR FOR NM (Electronic Submission) Signature Date 01/07/2015

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

enieb 7.23-1 pproved By ams Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.



If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.