Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires March 31, 2007

NM-29623

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Expires March 31, 2007

5. Lease Serial No.

abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Oil Well Gas	: Well Other	RECE	INED	8. Well Name and	No
		NOV 1 5 2005			
Name of Operator Yates Petroleum Corporation		OCU-ARTESIA		Filaree AEL Federal #8	
3a. Address	3b. Phone No. (include area co			30-005-63750	
105 S. 4th Str., Artesia, NM	505-748-1471	505-748-1471		10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M.,				Foor Ranch Wolfcamp, Northwest	
				11. County or Parish, State	
1650'FNL & 990'FEL of Section				nty, New Mexico	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity
	Casing Repair	New Construction	Recomplete		X Other Completion
Subsequent Report	Change Plans	Plug and Abandon	Temporarily		Operations
Tr. 100 - 100 - 100 - 100					Operations
Final Abandonment Notice 13. Describe Proposed of Completed Operation (cle	Convert to Injection	Plug Back	Water Dispe		
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports shall be filed within 30 days. following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 10/4/05 Tested production casing to 1000 psi for 30 min, OK. 10/5/05 Perforate Strawn 5946'-5970' (100). Acidize with 2500g 7-1/2% IC acid and 150 balls. 10/11/05 Perforate Strawn 5856'-5864' (36). Acidize with 1000g 7-1/2% IC acid and 50 balls. 10/17/05 Perforate Silurian 6152'-6162' (44). 10/20/05 Perforate Silurian 6068'-6074', 6099'-6104' with a total of 52 holes. Acidize with 500g 20% IC acid. 10/26/05 Set CIBP at 6000' with 35' cement on top. Set CIBP at 5800' with 35' cement on top. Perforate Wolfcamp 5426'-5430' (10). Acidize with 500g 20% IC acid. 10/31/05 Perforate Wolfcamp 5166'-5174' (36). Acidize with 1000g 20% IC acid. Set RBP at 5230'. Set packer at 5126'.					
Name (Printed/Typed)	and correct				
Tina Huerta	Title Regu	latory Compli	ance Supervis	sor	
Signature ()	herta	Date Nove	mber 11, 200	5	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by		Title		Date	9
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					
Title 18 U.S.C. Section 1001 and Title 43 LL.	S.C. Section 1212 make it a	crime for any person knowingly	and willbully to make	o to pou deportment	or agana, of the United