Form 3160-5 (August 2007)

#### UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED 1004-0135

OCD Artesia	OMB NO. Expires: Ju
	F. I Carriel Ma

NMNM35607

SUNDRY NO	DIICES AND REPORTS ON WELLS
. Do not use this f	form for proposals to drill or to re-enter an
abandoned well.	Use form 3160-3 (APD) for such proposals.
	, , ,

6.	If Indian, Allottee or Tribe Name	

apandoned well. Use form 3160-3 (APD) for such proposals.					•			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. RDX FEDERAL COM 28 9H			
2. Name of Operator Contact: HEATHER BREHM RKI EXPLORATION & PROD LLC E-Mail: hbrehm@rkixp.com					9. API Well No. 30-015-43294-00-X1			
3a. Address 210 PARK AVE SUITE 900 OKLAHOMA CITY, OK 73102	(include area code) 6-5769 1-2223		10. Field and Pool, or Exploratory UNDESIGNATED					
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)				11. County or Parish, and State			
Sec 28 T26S R30E NENW 36			EDDY COUNTY, NM					
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION		TYPE OF ACTION						
Notice of Intent	□ Acidize	☐ Acidize ☐ Deepen		☐ Production (Start/Resume)		■ Water Shut-Off		
_	☐ Alter Casing	☐ Frac	ture Treat	☐ Reclam	ation	☐ Well Integrity		
☐ Subsequent Report	Casing Repair	□ New	Construction	☐ Recomp	lete	Other		
☐ Final Abandonment Notice	□ Change Plans	Plug	and Abandon	□ Tempor	arily Abandon	Drilling Operations		
	□ Convert to Injection	Plug	Back	■ Water Disposal				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  RKI respectfully requests approval for for the cement squeeze performed on 12/2/15 on the subject well using the following procedure:  Job Summary: Tie into 2? 5M valve on casing head and establish an injection rate with 50 bbl 10 ppg brine of 6 bpm at 980 psi. Pump 10 bbl FW followed by 2750 sack squeeze cement. Final pump pressuring OIL CONSERVATION was 980 psi at 6 bpm. Shut in backside with 543 psi.  Squeeze Cement: 35:65 Class C Poz w/additives  DEC 2 1 2015								
Density: 12.9ppg Yield 1.91 cuft/sk		Annes	nêm al Seu	•		•		
Mix Fluid: 9.919			겨울에 for reco NMOCD		REC	EIVED		
		Ses	12	122/15				
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #325504 verified by the BLM Well Information System For RKI EXPLORATION & PROD LLC, sent to the Carlsbad Committed to AFMSS for processing by CHRISTOPHER WALLS on 12/04/2015 (16CRW0026SE)  Name (Printed/Typed) HEATHER BREHM Title REGULATORY ANALYST								
Signature (Electronic S	Submission)		Date 12/04/2	015	1			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By CHRISTOPHER WALLS  Conditions of approval, if any, are attached. Approval of this notice does not warrant or entify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			TitlePETROLE	TitlePETROLEUM ENGINEER Date 12/04/2				
			Office Carlsbad					

### Additional data for EC transaction #325504 that would not fit on the form

#### 32. Additional remarks, continued

Cement Calculations: Lead OH: 5,980' - 710'=5270 ft x .3132 cuft/ft=1650 cuft x 200% XS=4952 cuft Lead Cased: 710 ft x .3627 cuft/ft = 257 cutft Lead Total: 5209 cuft / 1.91 cuft/sk = 2727 sx = 2750 sx

Run bond log at KOP to confirm TOC. Bond log will be sent to Chris Walls.

Attached Documents: Original Bond log before squeeze Squeeze pump chart and job log.



# DESIGN - EXECUTE - EVALUATE - REPORT

## SQUEEZE

RKI RDX FED COM 28 #9H EDDY COUNTY, NM

Prepared By: JOHN INGRAM


FIELD SPECIALIST

ARTESIA DISTRICT

1-575-748-8610

PUMP:2019 BACK UP PUMP: 2014

12-2-15



Sugar Paris