Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## **NMOCD** Artesia

5. Lease Serial No.

	PUKM A	おないいい
	OMB NO	1004-0135
i	expires: Ju	uly 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM54290  6. If Indian, Allottee or Tribe Name		
1. Type of Well  Soli Well Gas Well Other				<u></u>	8. Well Name and No. NORTH BRUSHY DRAW FEDERAL 35 6		
Name of Operator Contact: HEATHER BREH     RKI EXPLORATION & PROD LLC E-Mail: hbrehm@rkixp.com				9. API Well No. 30-015-42293-00-X1			
3a. Address 3b. Phone N 210 PARK AVE SUITE 900 Ph: 405-9 OKLAHOMA CITY, OK 73102 Fx: 405-9			. (include area code 6-5769 3-2223	de) 10. Field and Pool, or Exploratory CORRAL CANYON			
4. Location of Well (Footage, Sec., 7			11. County or Parish,	and State			
Sec 35 T25S R29E NWNE 17 32.053509 N Lat, 103.571390		EDDY COUNTY, NM					
12. CHECK APP	ROPRIATE BOX(ES) TO	) INDICATE	NATURE OF	NOTICE, RE	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				<del> </del>		
☐ Notice of Intent	☐ Acidize	Deep Deep	oen	Producti	on (Start/Resume)	☐ Water Shut-Off	
•	☐ Alter Casing	☐ Frac	ture Treat	☐ Reclama	ntion	■ Well Integrity	
Subsequent Report	☐ Casing Repair	☐ Casing Repair ☐ New Construction		□ Recomp	lete	Other	
☐ Final Abandonment Notice	☐ Change Plans	nge Plans 🔲 Plug and		☐ Tempora	arily Abandon	Drilling Operations	
	☐ Convert to Injection	Plug	☐ Plug Back ☐ Water		isposal		
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for f COMPLETION SUNDRY ***R (continued completion/frac act	k will be performed or provide operations. If the operation resondonment Notices shall be filtered in the inspection.)  EVISION***REPLACE #3 ivities after repairs-revise	the Bond No. on sults in a multiple only after all r	file with BLM/BI/ e completion or rec- equirements, include	<ol> <li>Required sub completion in a n</li> </ol>	sequent reports shall be ew interval, a Form 316	filed within 30 days 60-4 shall be filed once and the operator has	
Completion activities began of RIH with tools to 10,684'. Plactor at 5414'. Test lines to 9500' psi, pressur minutes 9/5/15 Perf Stage 1 14,860' - 14,862' 2' 6-SPF 12 14,813' - 14,815' 2' 5-SPF 10 14,766' - 14,768' 2' 5-SPF 10 14,766' - 14,768' 2' 5-SPF 10 10 14,766' - 14,768' 2' 5-SPF 10 10 10 10 10 10 10 10 10 10 10 10 10	ed 1000 psi on well, ran f ed tested 5 1/2" Prod cas Holes Holes	RBL/CBL/GR// A CORS ing to 9000 ps	CCL to 4400'. E	stimated cen	ARTESI	ONSERVATION A DISTRICT () 8 ZÜIĞ	
					REC	CEIVED	
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #3 For RKI EXPLOR mitted to AFMSS for proce	CATION & PR	D'LLC, sent to t	he Carlsbad	7		
Name (Printed/Typed) HEATHER	BREHM		Title REGUL	ATORY ÁNA			
Signature (Electronic Submission)			Date 01/07/2016 PED FOR RECORD				
	THIS SPACE FO	R FEDERA		<del></del>	E	X 1 / 1	
Approved By			Title	di	1/0/	I IIIM	
Approved By	Approval of this notice does	ot warrent or	Title	DILLEGIT	OF LAND MANAGEM	NY T	
conditions of approval, if any, are attached. Approval of this notice does not warrant or ertify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office	CARL	SBAD FIELD OFFICE		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Additional data for EC transaction #327945 that would not fit on the form

## 32. Additional remarks, continued

9/10/15 frac prep
9/15/15 Frac & Perf Stages 1-8 (10,984'-14,862')
9/18/15 coiled tubing/CIBP failure
9/22/15 slickline/set CHBP
9/23/15 logging
9/25/15 Perf 5-1/5" prod casing
9/26/15 Flowback
10/14/15 Shut in 5.5?? and 9.625?? Csg w/250 psi.
10/15/15 Pull 5.5?' Csg
10/16/15 TIH w/TBG
10/18/15 Set CIBP
10/21/15 Run Casing
RIH w/5.5?? 20# GBCD P-110 w/torque turn (14,500 ft/lb on torque) to 4,460?. Latch onto 5.5?? Csg
w/Csg Patch @ 4,461?. Pull test to 140k and pressure test to 4,000 psi for 30 min. Land 5.5?? Csg
in slips @ 120k (30k over string wt)
10/23/15 drill out plugs
10/26/15 wireline
10/28/15 drill out plugs
10/29/15 turn over to production; flowback
11/12/15 run gas lift
5 ? 17-20# AS-1X Pkr @ 10,323?
EOT @ 10,332'