Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135

	Expires: July 31, 2010
ξ.	Lease Serial No.
	NML C061407

SUNDRY	NMLC061497 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.					
SUNDRY Do not use thi abandoned we						
SUBMIT IN TRI						
1. Type of Well	8. Well Name and No. FULLER 13 24 W1LM FED COM 3H					
☐ Oil Well 🗷 Gas Well 🗀 Oil		TEM FED COM 3H				
 Name of Operator MEWBOURNE OIL COMPAN 	9. API Well No. 30-015-43517-0	0-X1				
3a. Address P O BOX 5270 HOBBS, NM 88241		3b. Phone No Ph: 575-39). (include area code 93-5905)	10. Field and Pool, or Exploratory BRUSHY DRAW	
4. Location of Well (Footage, Sec., T	; R., M., or Survey Description))		.	11. County or Parish,	and State
Sec 13 T26S R29E NWSW 26	620FSL 440FWL				EDDY COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, I	REPORT, OR OTHE	R DATA
TYPE OF SUBMISSION			ТҮРЕ О	F ACTION		
C Nation of lateral	☐ Acidize	☐ Dee	pen	☐ Produ	ction (Start/Resume)	☐ Water Shut-Off
☐ Notice of Intent	☐ Alter Casing	☐ Frac	ture Treat	☐ Reclai	mation	Well Integrity
Subsequent Report	Casing Repair	□ Nev	v Construction	Recon	nplete	⊘ Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon		Tempe	orarily Abandon	Drilling Operations
	☐ Convert to Injection	n Plug Back . Wate			Disposal	
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 01/02/2016 TD 12 1/4" hole @ 3076. Ran 3076 of 9 5/8" 40# N80 LT&C csg. Cemented with 700 sks Lite Class C (35:65:4) w/additives. Mixed @ 12.5#/g w/2.19 yd. Tail w/200 sks Class C w/0.2% retarder. Mixed @ 14.8#/g w/1.32 yd. Plug down @ 4:30 P.M 01/02/16. Circ 120 sks of cmt to the pit. WOC. Tested BOPE to 5000# & Annular to 2500#. At 3:15 P.M. 01/03/2016, tested csg to 1500# for 30 min, held ok. Drilled out with 8 3/4" bit. Charts and schematic attached. Bond on file: NM1693 nationwide & NMB000919 RECEIVED RECEIVED						0-4 shall be filed once and the operator has SERVATION DISTRICT 2016
					\sim	
14. I hereby certify that the foregoing is true and correct. Electronic Submission #328638 verified by the BLM Well Information System For MEWBOURNE OIL COMPANY, sent to the Carlsbad / Committed to AFMSS for processing by PRISCILLA PEREZ on 01/15/2016 (16PP0116SE)						
Name (Printed/Typed) JACKIE LA	ATHAN		Title AUTHC	NOCKE	Presentative PVED FUR KE	CORD //
Signature (Electronic S	ubmission)		Date 01/15/2	06	/ / /	
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE !	SEN 2 6/2016	1/0
Approved By			Title		JANA JANA	A haje W
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the		Office	a mnaa	ARLSBAD FILLD OF THE	

MAN WELDING SERVICES, INC.

Company Heurogene Date 1-2-16
Lease Faller 13/24 WILM Fed Com# 34 County Foldy County Will
Drilling Contractor Patterion #271 Plug & Drill Pipe Size 11"CZZ 27-75
Accumulator Pressure: Manifold Pressure: 1500 Annular Pressure: 1100
Accumulator Function Test - OO&GO#2
To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)
 Make sure all rams and annular are open and if applicable HCR is closed. Ensure accumulator is pumped up to working pressure! (Shut off all pumps) 1. Open HCR Valve. (If applicable) 2. Close annular. 3. Close all pipe rams. 4. Open one set of the pipe rams to simulate closing the blind ram. 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems). 6. Record remaining pressure (4 / 37) psi. Test Fails if pressure is lower than required. a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system} 7. If annular is closed, open it at this time and close HCR.
To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)
 Start with manifold pressure at, or above, maximum acceptable pre-charge pressure: a. {800 psi for a 1500 psi system} b. {1100 psi for 2000 and 3000 psi system}
 Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure) Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to. Record pressure drop to to psi. Test fails if pressure drops below minimum. Minimum: a. (700 psi for a 1500 psi system) b. (900 psi for a 2000 & 3000 psi system)

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS .(III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
 - 1. Open the HCR valve, (if applicable)
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time have 135cc. Test fails if it takes over 2 minutes.
- a. {950 psi for a 1500 psi system}
 b. {1200 psi for a 2000 & 3000 psi system}



WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

Loyington, NM • 575-398-4540

Pg.	- {	 of	

	•	
company: Manbaccule	1 Date: 1 - 2 -	16 trivoice # 067826
Lease: Fuller 13/24 WILLIA Fall	(et. h ?() Drilling Contractor	: Patterson Rig# 231
Plug Size &Type:	Drill Pipe Size <u> </u>	Tester: Mr. Hhew Davis
Required BOP:	Installed BOP:	
'Appropriate Casing Valve Must Be Open During BOP Test '		* Check Valve Must Be Open/Disabled To Test Kill Line Valve
Annular #15 Annular #15 Annular #15 Blind Rams #13 #11 #10 #9 #7 #8 Plipe Rams #14	#26 = 1 Q #2 #4 #5 #6 #3 #8B #1 Mud Gatige Valve tt 5 2 = 3	Dart Valve #19 Stand Pipe Valve #24 Trop Drive #24 Walve #17 Manual 180P #16 Pump Valve Pump Valve #21

TEST #	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	REMARKS
1,4.	13 9.7 20.21 22.27	Buch	2673	(710)	Mr. Ter Ma Pressure formed
B#					beat Hide India Better unt
638			•		cloud Sideraly they are Unballed
			<u> </u>		Correct le
10	13 97 20,21 21, 27	WHILL	ኢኖጛ	Man.	LAND Good LEAK on High as these
					Sun Tore son likeont
116	13, 4, 7, 20, 22, 32	10 11. 2		FIXI	Proceeded back in the Horn Hoge
<u></u>				ı	Soul Control
2	199 6 261	RN 307	<u>) (m)</u>	1	Comment Texas
[13.10 88 54 3 17	IN Miles	(1) (27)	/ meno	Contin
	13 11 93 6629.2116	1 1	250	500	Grant Tork
1	15.11,88.6 29 3 1.11		2000	2500	Gerel Tiss.
	12 11. 6 282 7 31	10 HGA	250	5001	Const Tick
1	12, 11,6,25,26.30	Enno		5000	Bing Test God
ુ	19	In all a	ጋኖъ	<i>5</i> 100	Garel Tost
4	18	10 Milon	257 6	SONO.	(-oat Tist-
·					
			-		1







