
Form 3160-5					
August 2007)	UNITED STATE DEPARTMENT OF THE BUREAU OF LAND MAN	INTERIOR	10	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM81220	
SU	NDRY NOTICES AND REPO				
Do not abando	use this form for proposals to ned well. Use form 3160-3 (Al	o drill or to re-enter an PD) for such proposals.	enter an broposals. 6. If Indian, Allottee or Tribe Name		
SUBMIT	IN TRIPLICATE - Other instru	ictions on reverse side.	7. If Unit or CA	Agreement, Name and/or No.	
1. Type of Well ☐ Oil Well 🛛 Gas Wel	1 🗖 Other		8. Well Name and No. OLD RANCH KNOLL 8 FEDERAL 1		
2. Name of Operator Contact: DAVID STEWART   OXY USA WTP LP E-Mail: david_stewart@oxy.com				9. API Well No. 30-015-10588	
3a. Address P.O. BOX 50250		3b. Phone No. (include area co Ph: 432-685-5717	e) 10. Field and Pool, or Exploratory INDIAN BASIN UP PENN		
MIDLAND, TX 79710 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State		
-	NW 841FNL 1065FWL		EDDY COUNTY, NM		
12. CHEC	K APPROPRIATE BOX(ES) T	O INDICATE NATURE O	F NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSIC	N	TYPE OF ACTION			
□ Notice of Intent	□ Acidize	Deepen	Production (Start/Resum	e) 🔲 Water Shut-Off	
—	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
🛛 Subsequent Report	Casing Repair	New Construction	Recomplete	🗖 Other	
Final Abandonment Notice	otice 🛛 🗖 Change Plans	🛛 Plug and Abandon	Temporarily Abandon		
	Convert to Injection	n 🗖 Plug Back	Water Disposal	4-18-16	
Attach the Bond under which following completion of the testing has been completed. determined that the site is re 3/28/2016 MIRU, RU E	directionally or recomplete horizontally the work will be performed or provid- involved operations. If the operation r Final Abandonment Notices shall be f eady for final inspection.) BOP & accumulator on wellhead er, pump FW to kill well, POOH	le the Bond No. on file with BLM/ esults in a multiple completion or i iled only after all requirements, inc I.	BIA. Required subsequent reports sh recompletion in a new interval, a Forr luding reclamation, have been compl	all be filed within 30 days n 3160-4 shall be filed once	
3/30/2016 RIH w/ guag confirm setting, BLM a tag CIBP @ 7915'.	ge ring to 7920', POOH. RIH & pproved setting CIBP @ 7915'.	set CIBP @ 7920', POOH w RIH & set CIBP & 7915', P(	/ setting tool, couldn't OOH. RIH w/ tbg &	APR 2 5 2015	
3/31/2016 M&P 10# M	LF, no circulation, due to possit Salcido-BLM, PUH to 6945', W	ole holes in csg. RIH to 791 OC. RIH to 7915', no tag, M		RECEIVED RECEIVED	
14. I hereby certify that the for	Electronic Submission	#337135 verified by the BLM V Y USA WTP LP, sent to the C	Vell Information System arlsbad	oted to CD	
Name (Printed/Typed) DA		Title SR. F		Co, 1%.	
la:1	W		N N	~	
Signature (Ele	ectronic Submission)	Date 04/21	1/2016		
	THIS SPACE F	OR FEDERAL OR STAT	E OFFICE USE		
			·····		
	e attached. Approval of this notice doe gal or equitable title to those rights in the to conduct operations thereon.			Date	
tle 18 U.S.C. Section 1001 and States any false, fictitious or fra	Title 43 U.S.C. Section 1212, make it audulent statements or representations a	a crime for any person knowingly a is to any matter within its jurisdicti	and willfully to make to any departme	ent or agency of the United	
	·····				
** OI	PERATOR-SUBMITTED ** (	DPERATOR-SUBMITTEE	0 ** OPERATOR-SUBMIT	'ED **	

\*



## 32. Additional remarks, continued

4/1/2016 RIH to 7915', no tag, M&P 45sx CL H cmt, PUH, WOC. RIH to 7915', no tag, M&P 45sx CL H cmt, PUH, WOC.

4/4/2016 RIH to 7915', no tag, pump LCM pill, wait one hr, M&P 45sx CL H cmt, PUH, WOC.

4/5/2016 RIH to 7915', no tag, pump LCM pill, wait one hr, M&P 80sx CL H cmt, PUH, WOC. RIH to 7915', no tag, pump LCM pill, wait 30 min, M&P 80sx CL H cmt, PUH, WOC.

4/6/2016 RIH to 7915', no tag, pump LCM pill, M&P 100sx CI H cmt w/ 2%CaCl2, PUH, WOC. RIH to 7915', no tag, pump LCM pill, M&P 100sx CI H cmt w/ 2%CaCl2, PUH, WOC.

4/7/2016 RIH to 7915', no tag, pump LCM pill, M&P 100sx CI H cmt w/ 2%CaCl2, PUH, WOC. RIH to 7915', no tag, pump LCM pill, M&P 100sx CI H cmt w/ 2%CaCl2, PUH, WOC.

4/8/2016 RIH to 7915', no tag, pump LCM pill, M&P 100sx CI H cmt w/ 2%CaCl2, PUH, WOC. RIH to 7915', no tag, pump LCM pill, M&P 100sx CI H cmt w/ 2%CaCl2, PUH, WOC.

4/11/2016 RIH to 7915', no tag, pump LCM pill, PUH. Rec approval Jim Amos-BLM to set CIBP @ 7621', POOH w/ tbg. RIH & set CIBP @ 7621'.

4/12/2016 RIH w/ tbg & tag CIBP @ 7621', circ hole w/ 10# MLF, visually confirmed, M&P 70sx CI H cmt, PUH, WOC. RIH & tag cmt @ 6894', PUH to 4735'.

4/13/2016 M&P 75sx CL C cmt @ 4735', PUH, WOC. RIH & tag cmt @ 4096', PUH to 3613', SI, cmt pump repair.

4/14/2016 M&P 75sx CL C cmt @ 3613', PUH, WOC. RIH & tag cmt @ 3416', POOH. RIH & set pkr @ 2254', RIH & perf @ 2650', attempt to EIR, pressure to 1500#, no rate or loss, BLM approved spotting plug. RIH to 2715', M&P 30sx CL C cmt, PUH, WOC.

4/15/2016 RIH & tag cmt @ 2507', PUH & set pkr @ 756', RIH & perf @ 1100', attempt to EIR, pressure to 1500#, no rate or loss, BLM approved spotting plug. RIH to 1152'. M&P 30sx CL C cmt, PUH, WOC. RIH & tag cmt @ 930', PUH & set pkr @ 30', SI wind gusts.

4/18/2016 RIH & perf @ 408', attempt to EIR, pressure to 1500#, no rate or loss, BLM approved spotting plug. RIH to 467', M&P 25sx CL C cmt, POH, WOC. RIH & tag cmt @ 265', PUH & perf @ 65', EIR @ 2bpm @ 0psi. RIH to 265', M&P 30sx CL C cmt, circ to surface, then sqz 20sx CL C cmt @ 65' to surface, both visually confirmed. ND BOP & accumulator.

4/19/2016 RDPU