Form 3160-5 3

(June 2015)

NMOCD

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

NMNM 36648

Expires: January 31, 2018 5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well.	Use Form 3160-3 (A	PD) for such proposals	s		
SUBMIT IN	TRIPLICATE - Other instr	uctions on page 2		7. If Unit of CA/Ago	eement, Name and/or No.
1. Type of Well				1	
Oil Welt Gas V	Well Dther			8. Well Name and N	6. See Attached List
2. Name of Operator Vanguard Oper	ating, LLC			9, API Well No.	See Attached List
3a, Address 5847 San Felip	e. Suite 3000	3b. Phone No (include area cod	e)	10. Field and Pool o	r Exploratory Area
Houston, Texas		(832) 377-2243			See Attached List
4. Location of Well (Footage, Sec., T.,	R.,M., or Survey Description,			11. Country or Paris	h, State
√See Attached I	ist	•			CHAVES, NM
12, CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATURI	OF NOT	ICE, REPORT OR OT	THER DATA
TYPE OF SUBMISSION		, TY	PE OF AC	TION	
[]National Classical	Acidize	Deepen	Proc	luction (Start/Resume) Water Shut-Off
Notice of Intent	Alter Casing	Hydraulic Fracturing	Reci	amation	Well Integrity
[7] (1)	Casing Repair	New Construction	Rece	omplete	✓ Other
✓ Subsequent Report	Change Plans	Plug and Abandon	Tem	porarily Abandon	<u></u>
Final Abandonment Notice	Convert to Injection		=	er Disposal	
13 Describe Proposed or Completed (Decation: Clearly state all ne	rtinent details, including estimate	d starting d	ate of any proposed u	ork and approximate duration theraof. If

the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)

This is notification of Change of Operator on the above referenced well. Vanguard Operating, LLC, as new operator, accepts all applicable terms, conditions, stipulations and restrictions concerning operations conducted on this lease or portion of lease described. Bond Coverage: BLM Bond File No. NMB000797, Surety Bond No. B006616 Bond Coverage Roswell Field Office: BLM Bond File No. NMB000857, Surety Bond No. B007133 Change of Operator Effective: October 5, 2015

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Former Operator: LRE Operating, LLC

(Instructions on page 2)

Accepted for record
NASCD AB 5/25/16

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Conditions of approval, if any, are attached. Approval of this notice does not warra tertify that the applicant holds legal or equitable title to those rights in the subject I which would entitle the applicant to conduct operations thereon.				
/S/ DAVID R. GLASS	Title PETROLEUM ENGINEER Date MAR 2 5 2016			
THE SPACE FOR FED	ERAL OR STATE OFICE USE			
Signature 2	Date 10.5. 7015			
I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Britt Pence	Executive Vice President, Operations Title			

ATTACHMENT TO LEASE SERIAL NO. NMNM 36648

WELL NAME	V	API NUMBER	EXPLORATORY AREA	UNITLIR	SEC [$\mathbf{S}_{\mathbf{A}}$	RNG	NOILVOOT	
CHINA FEDERAL 1	30-005-60863 300056	300056	PECOS SLOPE; ABO, WEST	В	18	75	23E	23E 660 FNL 1	1980 FEL
CHINA FEDERAL 11		300056	PECOS SLOPE; ABO, WEST	В	20	75	23E	23E 660 FNL 2	2310 FEL
CHINA FEDERAL 12	CHINA FEDERAL 12 30-005- 6/659 300056	300056	PECOS SLOPE; ABO, WEST	E .	19	75	23E	23E 1980 FNL 5	500 FWL
CHINA FEDERAL 13	CHINA FEDERAL 13 30,005- 6/688 300056	300056	PECOS SLOPE; ABO, WEST	٦	20	75	23E	23E 2310 FSL 9	990 FWL
CHINA FEDERAL 14	CHINA FEDERAL 14 30-005-6/649 300056	300056	PECOS SLOPE; ABO, WEST		19	75	23E	23E 2310 FSL 6	990 FEL
CHINA FEDERAL 15	CHINA FEDERAL 15 30-005-6/1/30 300056	300056	PECOS SLOPE; ABO, WEST	Τ.	19	75	23E	23E 1444 FSL 1	1950 FWL
CHINA FEDERAL 2	CHINA FEDERAL 2 30-005-608 6 300056	300056	PECOS SLOPE; ABO, WEST	Е	18	75	23€	23E 1800 FNL 6	660 FWL
CHINA FEDERAL 3 30-005-1/1086	30-005-61086	300056	PECOS SLOPE; ABO, WEST	E	17	75	23E	23E 1850 FNL 6	660 FWL
CHINA FEDERAL 4 30.005 - 10/1/7	30005-101117	300056	PECOS SLOPE; ABO, WEST	Κ	17	7 S	23E	23E 1650 FSL 1	1870 FWL
CHINA FEDERAL 5	CHINA FEDERAL 5 30-005- 11/105	300056	PECOS SLOPE; ABO, WEST	J	18	7 S	23E	23E 1322 FSL 2	2080 FEL
CHINA FEDERAL 7	CHINA FEDERAL 7 30-005-101/028	300056	PECOS SLOPE; ABO, WEST	K	18	75	23E	23E 1650 FSL 3	1875 FWL
CHINA FEDERAL 8 30-005- 1110-38	80-005-61638	300056	PECOS SLOPE; ABO, WEST	Α	19	75	23E	23E 660 FNL : 5	560 FEL
CHINA FEDERAL 9 30-005-11/457	80-005-61657	300056	PECOS SLOPE; ABO, WEST	F	20	75	23E	23E 1650 FNL	784 FWL
			•						

Vanguard Operating, LLC Change of Operator **Conditions of Approval**

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days.
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and
- abandon this well or obtain approval to do otherwise within 90 days.

 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.