Form 3160-5 - \ (June 2015)

✓ Subsequent Report

(Instructions on page 2)

Final Abandonment Notice

Former Operator: LRE Operating, LLC

NMOCD

UNITED STATES Artesia DEPARTMENT OF THE INTERIOF

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

6. If Indian, Affortee or Tribe Name

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

5. Lease Serial No NMNM 36648

adandoned Well. Use F	OFM 3100-3 (A	APD) for such proposals.			
SUBMIT IN TRIPLI	CATE - Other inst	ructions on page 2	7. If Unit of CA/A	greement, Name and/or No.	
1, Type of Well					
Oil Well	Other		8. Well Name and	No. See Attached List	
2. Name of Operator Vanguard Operating, L	LC .		9. API Well No	See Attached List	
3a. Address 5847 San Felipe, Suite	3000	3b. Phone No. (include area code)	10, Field and Pool	or Exploratory Area	
Houston, Texas 77057	3000	(832) 377-2243	,	See Attached List	
4. Location of Well (Footage, Sec., T.R., M., or	Survey Description	i)	11. Country or Par	ish, State	_
See Attached List		•		CHAVES, NM	
12. CHECK TH	E APPROPRIATE I	BOX(ES) TO INDICATE NATURE OF N	OTICE, REPORT OR C	OTHER DATA	
TYPE OF SUBMISSION		, TYPE OF	ACTION		
Notice of Intent	Acidize	Deepen1	Production (Start/Resum	ne) Water Shut-Off	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)

Hydraulic Fracturing

New Construction

Plug and Abandon

Plug Back

Reclamation

Recomplete

Water Disposal

Temporarily Abandon

This is notification of Change of Operator on the above referenced well. Vanguard Operating, LLC, as new operator, accepts all applicable terms, conditions, stipulations and restrictions concerning operations conducted on this lease or portion of lease described. Bond Coverage: BLM Bond File No. NMB000797, Surety Bond No. B006616 Bond Coverage Roswell Field Office: BLM Bond File No. NMB000857, Surety Bond No. B007133 Change of Operator Effective: October 5, 2015

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Alter Casing

Casing Repair

Change Plans

Convert to Injection

Accepted for record 5/25/16

Well Integrity

✓ Other

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Britt Pence Titl	Executive Vice President, Operations
Signature Date	: 10.5. 7015
THE SPACE FOR FEDERA	AL OR STATE OFICE USE
/S/ DAVID R. GLASS	PETROLEUM ENGINEER Date MAR 2 5 2016
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office ROSWELL FIELD OFFICE

ATTACHMENT TO LEASE SERIAL NO. NMNM 36648

	-						-			
	784 FWL	23E 1650 FNL 7	23E	75	20	E	PECOS SLOPE; ABO, WEST	300056	0-005-6/1457	CHINA FEDERAL 9 30-005-11/457
-	560 FEL	23E 660 FNL 5	23E	75	19	Α	PECOS SLOPE; ABO, WEST	300056	0-005-101038	CHINA FEDERAL 8 30-005-1010-38
	1875 FWL	1650 FSL	23E	75	18	K	PECOS SLOPE; ABO, WEST	300056	2005-1011028	CHINA FEDERAL 7 30-006-101/028
	2080 FEL	23E 1322 FSL 2	23E	75	18	ſ	PECOS SLOPE; ABO, WEST	300056	0-005-41605	CHINA FEDERAL 5 30-005-4/105
_	1870 FWL	23E 1650 FSL 1	23E	75	17	×	PECOS SLOPE; ABO, WEST	300056	80.005-101117	CHINA FEDERAL 4 30.005-10/1/7
	660 FWL	23E 1850 FNL 6	23E	75	17	Е	PECOS SLOPE; ABO, WEST	300056	0-005-11081	CHINA FEDERAL 3 30-005-1/1086
	660 FWL	23E 1800 FNL 6	23E	75	18	3	PECOS SLOPE; ABO, WEST	300056	0-005-60865	CHINA FEDERAL 2 30-005-60863
	1950 FWL	23E 1444 FSL 1	23E	75	19	K	PECOS SLOPE; ABO, WEST	300056	80-005-611-71	CHINA FEDERAL 15 30-005-611-70 300056
	990 FEL	23E 2310 FSL 9	23E	27	19	ļ	PECOS SLOPE; ABO, WEST	300056	30-005-616h	CHINA FEDERAL 14 30-005-6/649 300056
	990 FWL	23E 2310 FSL 9	23E	75	20	٦	PECOS SLOPE; ABO, WEST	300056	30,005-6/688	CHINA FEDERAL 13 30.005- 4/488 300056
	500 FWL	23E 1980 FNL 5	23E	75	19	E	PECOS SLOPE; ABO, WEST	300056	30-005-61654	CHINA FEDERAL 12 30-005- 6/659 300056
	2310 FEL	660 FNL	23E	75	20	В	PECOS SLOPE; ABO, WEST	§ 300056	30-005-11/458 300056	CHINA FEDERAL 11
	1980 FEL	23E 660 FNL 1	23E	75	18	8	PECOS SLOPE; ABO, WEST	300056	30005-60863 300056	CHINA FEDERAL 1
	ION.	SEC TWN RNG LOCATION	RNG	TWN		UNITLTR	EXPLORATORY, AREA	API.NUMBER		WELL NAME
							And the case of th			

Vanguard Operating, LLC Change of Operator Conditions of Approval

- 1. Tank battery must be bermed/diked (must be able to contain 1/1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days.
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.