

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720
District III
1000 Rio Brazos Road, Aztec, NM 87410
Phone: (505) 334-6178 Fax: (505) 334-6170
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505
Phone: (505) 476-3460 Fax: (505) 476-3462

State of New Mexico
Energy, Minerals & Natural Resources Department
NM OIL CONSERVATION
ARTESIA DISTRICT
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-102
Revised August 1, 2011
Submit one copy to appropriate
District Office

SEP 02 2016

RECEIVED

☒ AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

¹ API Number 30-015-37515	² Pool Code 40297	³ Pool Name Los Medanos, Delaware
⁴ Property Code 13749	⁵ Property Name Glow Worm ALX Federal	⁶ Well Number 19H
⁷ OGRID No. 025575	⁸ Operator Name Yates Petroleum Corporation	⁹ Elevation 3396'GR

¹⁰ Surface Location


UL or lot no. O	Section 3	Township 23S	Range 31E	Lot Idn	Feet from the 30	North/South line South	Feet from the 2310	East/West line East	County Eddy
--------------------	--------------	-----------------	--------------	---------	---------------------	---------------------------	-----------------------	------------------------	----------------

¹¹ Bottom Hole Location If Different From Surface

UL or lot no. G	Section 3	Township 23S	Range 31E	Lot Idn	Feet from the 1946	North/South line North	Feet from the 2384	East/West line East	County Eddy
--------------------	--------------	-----------------	--------------	---------	-----------------------	---------------------------	-----------------------	------------------------	----------------

¹² Dedicated Acres 120	¹³ Joint or Infill	¹⁴ Consolidation Code	¹⁵ Order No.
--------------------------------------	-------------------------------	----------------------------------	-------------------------

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

¹⁶						¹⁷ OPERATOR CERTIFICATION <i>I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or released mineral interest in the land including the proposed bottom hole location or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.</i>  Signature September 1, 2016 Date Tina Huerta Printed Name tinalh@yatespetroleum.com E-mail Address
						¹⁸ SURVEYOR CERTIFICATION <i>I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.</i> Date of Survey Signature and Seal of Professional Surveyor: Certificate Number

1946H
BHL
2384'E
SHL
2310'E

Sharp, Karen, EMNRD

From: Tina Huerta <Tinah@yatespetroleum.com>
Sent: Friday, September 02, 2016 9:07 AM
To: Sharp, Karen, EMNRD
Subject: RE: DSU for Glow Worm ALX Federal #19H
Attachments: GlowWorm19Deviation.pdf; GlowWorm19Hsurvey.pdf; GlowWorm19HsurveyMWD.pdf; GlowWorm19HC-102.pdf

Good Morning Karen,

The only thing I found in our files was an email saying there was a fish in the hole so that is why the BHL was not where we APD'd the well, I did not find a sundry and the drilling person that was in charge of that well is no longer with Yates. Please let me know if you needed anything else. Thank you ma'am and have a great weekend!

*Tina Huerta
Yates Petroleum Corporation
Regulatory Reporting Supervisor
tinah@yatespetroleum.com
575-748-4168*

From: Sharp, Karen, EMNRD [mailto:Karen.Sharp@state.nm.us]
Sent: Tuesday, August 30, 2016 1:36 PM
To: Tina Huerta
Cc: Kyle Morris; Bayliss, Randolph, EMNRD
Subject: FW: DSU for Glow Worm ALX Federal #19H

Tina:
Could you provide me with the sundry approving the change of the bottom hole location for this well? It is still posted as it was originally designated with the APD. There is a plat on file showing the bottom hole location in Unit Letter G, but does not outline a new spacing unit, so I am guessing it was 'overlooked' when submitted (2012) and not updated in our system. I will be glad to do that when I receive the change. Thanks very much!
ks

From: Kyle Morris [mailto:KMorris@yatespetroleum.com]
Sent: Friday, August 26, 2016 2:53 PM
To: Sharp, Karen, EMNRD
Subject: DSU for Glow Worm ALX Federal #19H

Karen,

I hope everything is going great for you.

Regarding the captioned well, can you confirm whether the DSU that is identified on the website is accurate? The SHL is in UL-O and the BHL appears to be in UL-G. However, the DSU is shown as including UL-B. Please let me know if clarification is needed.

Link: <https://wwwapps.emnrd.state.nm.us/ocd/ocdpermitting/Data/WellDetails.aspx?api=30-015-37515>

I appreciate your help. Have a nice weekend.

Regards,

Kyle V. Morris

Land Department
Yates Petroleum Corporation
Phone: 575 748 4115

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
