Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office District I – (575) 393-6464 OIL CONSERVEnergy, Minerals and Natural Resources	Revised July 18, 2013
1025 N. FIERCH DI., HOUDS, NUM DESTRIC	WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88218 R 27 2017 OIL CONSERVATION DIVISION District III – (505) 334-6178 MAR 27 2017 0IL CONSERVATION DIVISION	30-005-63762 5. Indicate Type of Lease
	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, RACEIVEL	VA 2401
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	SCROUNGER STATE
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number 1
2. Name of Operator	9. OGRID Number 26307
JALAPENO CORPORATION 3. Address of Operator	10. Pool name or Wildcat
PO BOX 1608, ALBUQUERQUE, NM 87103	Wolf Lake South
4. Well Location	
Unit Letter A : 412 feet from the North line and	330 feet from the East line
Section 13 Township 9-S Range 27-	E NMPM County Chaves
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
GR 3877'	
12 Check Appropriate Boy to Indicate Nature of Notice Report or Other Data	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	
	T JOB
	ES TO P&A PLANS
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
proposed completion of recompletion.	
3/17/17 -	
 Jalapeno Corporation commenced the P&A job for the Scrounger State#1. 	
• Rotary Wireline services set a CIBP at 2108' and perforated the 15.5# production casing at 1100'.	
• Par 5 services set an initial cement plug and shut down for 4 hours. After 4 hours the crew went to tag the	
bottom plug and found that the cement plug rose to 2078'.	
• Por 5 then reentered the well and set another 25 sack coment plug	
• The job was shut down for the day.	ability receipt
al pore additional and the second s	
3/18/17 - (Continued on second page. Attachments follow.)	Approved for place in the second of Web Pase under http://www.second.org/org/ http://www.second.org/
	r husend is Report Veroch
Spud Date: 10/17/05 Rig Release Date:	roved under bequee at account
	APL STORE STATES
	of Child Former French
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE March 21, 2017	
Type or print name <u>H. Emmons Yates, III</u> E-mail address: <u>eyates@jalapenocorp.com</u> PHONE: <u>505-242-2050</u>	
For State Use Only	
APPROVED BY: Jant 1 Byrel TITLE COMPLIANCE OFFICER DATE 3/29/2017	
Conditions of Approval (if any):	

Page 1 of 2

(#13, continued from previous page)

3/18/17 -

- The crew arrives on location and tags the bottom plug at 1908'.
- The crew then fills the hole with salt water spacing gel to 1100'.
- The crew then begins to try and circulate fluid through the perforations at 1100'. The crew begins to gain pressure and eventually reaches 1000# PSI.
- It is determined that a call needs to be made to Jalapeno Corporations home office in order to determine how to proceed.
- It is determined that the initial schematic Jalapeno Corporation submitted to the OCD was inaccurate. Jalapeno had originally believed that the production casing had only been cemented to 1100'. However, after reexamining the cement bond log submitted to the OCD when the well was originally completed, it is determined that the production cement had been cemented to surface.
- After realizing that the approved P&A process would have to be deviated from, Emmons Yates proceeded to call Mr. Byrd at the OCD. Emmons Yates was unable to reach Mr. Byrd on his phone, as his voicemail box had not yet been set up.
- Mr. Yates then proceeded to call both the OCD Artesia field office and the number that the OCD left for 24 hour emergency contacts. He left messages for people to call him back because we needed some direction on the Scrounger P&A job.
- However, after not receiving a call back and still having the crews on the Scrounger location, Mr. Yates decided to send a fax message to the Artesia field office detailing what had taken place.
- After having not heard from the OCD, Mr. Yates told the field crew to fill up the borehole with cement from 1100' to surface.

With this subsequent report notice, Jalapeno Corporation is also submitting copies of the cement bond log, the fax sent to the OCD, as well as phone call record detailing the phone calls that Mr. Yates made on the 18th.

Also included are revised and accurate before and after well bore schematics.