NM OIL CONSERVATION ARTESIA DISTRICT

Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Artesia SUNDRY NOTICES AND REPORTS ON WELL

SUNDRY NOTICES AND REPORTS ON WELLS Artesia Do not use this form for proposals to drill or to re-enter and abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM0115465A 6. If Indian, Allottee or Tribe Name	
1. Type of Well ☐ Oil Well Gas Well ☐ Other					8. Well Name and No. TOLES FEDERAL 1	
Name of Operator Contact: KELLY BARAJAS READ & STEVENS INCORPORATED E-Mail: kbarajas@read-stevens.com					9. API Well No. 30-005-60782-00-S1	
3a. Address P.O. BOX 1518 ROSWELL, NM 88202		3b. Phone No. (include area code) Ph: 575-622-3770			10. Field and Pool or Exploratory Area DIAMOND MOUND-MORROW	
4. Location of Well <i>(Footage, Sec., T</i> Sec 34 T15S R27E SWSE 660				11. County or Parish, State CHAVES COUNTY, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE	, REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			ACTION		
☑ Notice of Intent ☐ Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction		☐ Produc ☐ Reclaim ☐ Recom		☐ Water Shut-Off ☐ Well Integrity ☐ Other
Final Abandonment Notice	(-		☐ Plug and Abandon		Temporarily Abandon	
	Convert to Injection	☐ Plu	g Back	□ Water l	Disposal	
following completion of the involved testing has been completed. Final Abdetermined that the site is ready for final fin	eandonment Notices must be filmal inspection. eaks were isolated with a late casing during cemen 52'. A CBL will be ran to least the second of the 3' cement on top of the 3'	ed only after all bridge plug/ t job. The ce confirm whe n cement is a	requirements, including packer combination out a received out a received to the combination of the combinati	ing reclamation on from 23 after the nd casing a n a cement	n, have been completed at 74' to 2 DONE and Appro- rowl af	emidation.
above the Atoka-Morrow perfs 3. The CIBP is at 8660' +/		ord - NMO	C.D.			
Current top of cement is at	Accepted for rec	-20-1	SEE AT	TTACH TIONS	IED FOR S OF APPRO	VAL
14. I hereby certify that the foregoing is Comr Name (Printed/Typed) RORY MC	#Electronic Submission # For READ & STE nitted to AFMSS for proce	VENS INCORI	PORATED, sent to	the Roswe on 04/17/201	u (
Signature (Electronic S	ubmission)		Date 04/17/20)17 A	PPROVED	
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE /	
Approved By Conditions of approval, if any, are attached. Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the sul which would entitle the applicant to conduct operations thereon.			Title Office	$\frac{1}{\sqrt{n}}$	PR 17 2017 DF LAND MANAGEMEN SBAD FIELD OFFICE	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a statements or representations as	crime for any p to any matter w	erson knowingly and ithin its jurisdiction.	willfully to m	ake to any department or a	gency of the United
(Instructions on page 2) ** BLM REV	SED ** BLM REVISED	O ** BLM R	EVISED ** BLM	// /REVISEI	O ** BLM REVISED	,**

Additional data for EC transaction #373057 that would not fit on the form

- 32. Additional remarks, continued
- 5. Anticipate the new top of cement above CIBP #1 will be at 8460' +/-.
- 6. SD to allow for cement to cure.
- 7. Run packer and set at 7560'.
- 8. Swab the Penn-Strawn formation. If testing is not encouraging we will set CIBP above Penn-Strawn together with 200' of cement above the next CIBP #2.
- 9. Move forward with testing Grayburg-Premier Sand (Grayburg Top @ 1255') Premier Sand perforations at 1710'-1720'. San Andres (Top 1736') and the Glorieta (Top 2924') with perforations at 2930'-2935'.
- 10. If testing is encouraging we will return well to production. If unfavorable we will plug and abandon the well.

must have an approved sundry to PDA the well.

Revisions to Operator-Submitted EC Data for Sundry Notice #373057

Operator Submitted

BLM Revised (AFMSS)

Sundry Type:

RCMPL

NOI

RCMPL NOI

Lease:

NMNM0115465A

NMNM0115465A

Agreement:

Operator:

READ & STEVENS P. O. BOX 1518 ROSWELL, NM 88202 Ph: 575-622-3770

READ & STEVENS INCORPORATED P.O. BOX 1518 ROSWELL, NM 88202

Admin Contact:

KELLY BARAJAS REPORT PREPARER

E-Mail: kbarajas@read-stevens.com

Ph: 575-622-3770

KELLY BARAJAS REPORT PREPARER

Ph: 575-622-3770

Tech Contact:

RORY MCMINN

PRESIDENT

E-Mail: rmcminn@readoperating.com

Ph: 575-624-3754

RORY MCMINN

PRESIDENT

E-Mail: rmcminn@readoperating.com

E-Mail: kbarajas@read-stevens.com

Ph: 575-624-3754

Location: State:

County:

NM

CHAVES

NM **CHAVES**

Field/Pool:

DIAMOND MOUND-MORROW

DIAMOND MOUND-MORROW

Well/Facility:

TOLES FEDERAL 1 Sec 34 T15S R27E 660FSL 1980FEL

TOLES FEDERAL 1 Sec 34 T15S R27E SWSE 660FSL 1980FEL

Toles Federal 1 30-005-60782 Read and Stevens, INC. April 17, 2017 Conditions of Approval

Notify BLM at 575-627-0205 a minimum of 24 hours prior to commencing work.

Work to be completed by July 17, 2017.

- 1. If CBL shows cement less than 500' above top most desired perf (1710'). Contact BLM.
- 2. Operator shall add 165' of Class H cement on top of the CIBP at 8660' to seal the Morrow formation. WOC and TAG.
- 3. If Penn-Strawn is uneconomic, operator will set a CIBP 50'-100' above top most perf and place 200' Class H Cement on top as proposed.
- 4. Must conduct a casing integrity test before <u>perforating</u> and <u>fracturing</u>. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails
- **5.** Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 6. Surface disturbance beyond the originally approved pad must have prior approval.
- 7. Closed loop system required.
- 8. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 9. Operator to have H2S monitoring equipment on location.

- 10. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 11. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.
- 12. If operator desires to P&A the well, submit NOI to P&A with current and proposed wellbore diagram.
- 13. See attached for general requirements.

JAM 041717

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220

575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>.

7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.