

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NM OCD
Artesia

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

MELW Enterprise, Inc.

3a. Address

300 S. Kentucky, Roswell, NM 88203

3b. Phone No. (include area code)

575-626-2464

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1-15-08S-23E 2200 FSL 815 FEL

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Tales Federal #4

9. API Well No.

30-005-62486

10. Field and Pool or Exploratory Area

11. Country or Parish, State

Charles, N.M.

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Rig up Pulling Unit, Pull + Lay down Rods + Pump, Pull TBG, Run in TBG with Sealing N. ppl. on Bottom, Set TBG Above Perfs, Swab well dry; Pump 1 Barrel Acid Soap Down TBG, Followed By 2 Barrels Fresh water, Let set 2 Hours, Pump 10 Barrels Fresh water Down TBG, S.2. 24-48 Hours, Swab well off and Put Back on Production.

SC 5-31-17
accepted for record - NM OCD

NM OIL CONSERVATION
ARTESIA DISTRICT

MAY 30 2017

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)

Billy Walker

Title

Sec / Treas

RECEIVED

Signature

Billy Walker

Date

4-3-17

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

(ORIG SGD.) DAVID R. GLASS

Title

Date

Conditions of approval, if any, and a statement of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

DAVID R. GLASS

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or reports or to furnish any false information in any matter within its jurisdiction.

(Instructions on page 2)