£	OCD-ARTESIA						
iorm 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010		
				5. Lease Serial No. NMNM0506A			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals NMI OIL CONSERVATION				6. If Indian, Allottee of	or Tribe Name		
ARTESTA DISTRICT SUBMIT IN TRIPLICATE - Other instructions on reverse side. MAY 1 1 2017					7. If Unit or CA/Agreen NMNM71016X	ement, Name and/or No.	
1. Type of Well Oil Well Gas Well Other: UNKNOWN OTH					 Well Name and No. POKER LAKE UN 	NIT 043 🛩	
2. Name of Operator BOPCO LP	HERRYECEIV	EL	9. API Well No. 30-015-21700				
3a. Address P O BOX 2760 MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-683-2277			10. Field and Pool, or Exploratory 50384 SWD; DELAWARE Poker Lake; Delaware, S			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State				
24 Sec 21 T24S R31E Mer NMP SWSW 660FSL 660FWL					EDDY COUNTY, NM		
12. CHECK APP	ROPRIATE BOX(ES) T	O INDICATE	NATURE OF	NOTICE, R	L EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
- Notice of Intent	🗖 Acidize	🗖 Dee	pen	Product	tion (Start/Resume)	□ Water Shut-Off	
Subsequent Report	□ Alter Casing	—	ture Treat	🗖 Reclam		U Well Integrity	
Final Abandonment Notice	Casing Repair Change Plans	•		C Recom	—		
			and Abandon		-		
following completion of the involve testing has been completed. Final A detennined that the site is ready for BOPCO, LP respectfully subi- disposal well to an Observati The Poker Lake Unit #43 will in the Delaware formation du obtained by monitoring the su submitted to the BLM by Sun details of this observation pro The subject well was unsucc completed as an SWD in Dee was granted 08/25/1994 per <u>Menitor Well Shu</u> 14. Thereby certify that the foregoing Name (<i>Printed/Typed</i>) TRACIE	bandonment Notices shall be fi final inspection.) mits this sundry notice of on/Monitoring well. be one of seven (7) wells e to historical offset dispo- urface pressure and obtai dry Notice. Please refer to ogram.	intent to conve to be used for sal influence. ning annual flu o BOPCO, LP fication and ware in Janua ough perforat order SWD-56	requirements, incluent the reference or monitoring property of the reference Pressure informulated levels. Data ?s 2016 Plan or of details in any 1976 then re- tions 4404-4550 7. The attached <u>il 02/03</u> d by the BLM Went to the Carlsb	iding reclamation WEV ed saltwater essure chang nation will be f Development roo roo content d and f Development f	n, have been completed, L LOST IN AUTHOLIN LEXPILED NO USANGER F Sw0 WER authority gram shows <u>ULL OAO</u> authority gram shows	and the operator has USECTION ISW D PERMIT OF 2016- CAN NO SE USED AS AN - NMOCD STITIT Poted for record NMOCD	
			D. 05/00/				
Signature (Electronic	Submission) THIS SPACE F	OR FEDERA	Date 05/20/		SE		
		UNT EDEIG	T				
Approved By	16 twark		Title	TPE	:T	Date 5317	
Conditions of approval, if any, are attach certify that the applicant holds legal or ea which would entitle the applicant to conc	uitable title to those rights in the	es not warrant or ne subject lease	Office	CFO	2		
Title 18 U.S.C. Section 1001 and Title 4. States any false, fictitious or fraudulent					ake to any department or	r agency of the United	

.*

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Order of the Authorized Officer BOPCO/XTO Poker Lake Unit – 43, API 3001521700 T24S-R31E, Sec 21, 660FSL & 660FWL May 03, 2017

Records indicate no disposal volume injected since 02/2015.

The New Mexico Bureau of Land Management (BLM) Policy guideline limits total idle well status to five years. With sufficient documentation and justification via subsequent sundry reporting the AO may authorize renewal on a year-to-year, case-by-case basis.

Operator's designation of Monitoring Well status (MW) indicates the well is a service well for "Delaware Formation Observation and Monitoring". BLM accepts conversion from a Delaware WDW to a Shut-In Delaware Formation Observation/Monitoring Well.

05/03/2017 - Beginning 02/2015 until 05/03/2018 (the BLM designated renewal date) SI status accepted for record with this attached order of authorized officer. pswartz

To extend SI compliance beyond the BLM designated renewal date, submit a subsequent sundry listing:

- 1. Provide BLM with an (when available) electronic copy (Adobe Acrobat Document) of a cement bond log record from Packer depth or below_to the top of cement with 0psig casing pressure. Attach the CBL to a <u>pswartz@blm.gov</u> email.
- 2. Provide a witnessed recent MIT record (taken in the last year) of the tubing/casing annulus.
 - i) The minimum MIT pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with a minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need reduction).
 - ii) Verify that all annular casing vents are open to the surface atmosphere during this pressure test.
 - iii) Document the pressure test on a one hour full rotation chart recorder (calibrated within the last 6 months) registering within 35 to 75 per cent of its full range. Greater than 10% pressure leakoff viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict status approval.
- 3. Maintain the annulus full of packer fluid at atmospheric pressure. Installation of equipment that will display a continuous open-air packer fluid level above the tubing/casing annulus vent is required.
- 4. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov></u>, cell phone 575-200-7902) to arrange for approval of the annular monitoring system.

- 5. Loss of packer fluid above five barrels per month indicates a developing problem. Submit a NOI plan of correction compliance for BLM approval.
- 6. Submit dated reports of each taken stabilized inactive shut-in wellhead and annulus pressure, fluid level, and tubing psig from no more than 20-30 feet above the injection packer on a request for renewal subsequent sundry.
- 7. Report operator's reasoning and conclusions drawn from the monitoring information.
- 8. If you do not comply as noted, you shall be issued an Incident of Noncompliance (INC) in accordance with 43 CFR 3163.1(a). Failure to comply with the INC may result in assessments as outline in 43 CFR 3163.1, and may also incur civil penalties (43CFR 3163.2). All self-certified corrections must be postmark no later than the next business day after the prescribed time frame for correction.
- 9. Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.
- 10. A person contesting a decision shall request a State Director review of the Written Order. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.