Form 3160-5 (June 2015)

#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

#### NMNM042625 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter any Rield Officen, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well Well Name and No **COTTON DRAW UNIT 272H** 🖾 Oil Well 🔲 Gas Well 🔲 Other 2. Name of Operator Contact: LINDA GOOD API Well No. DEVON ENERGY PRODUCTION CONTINUES. linda.good@dvn.com 30-015-43724 Field and Pool or Exploratory Area PADUCA; BONE SPRING 3b. Phone No. (include area code) 333 WEST SHERIDAN AVE Ph: 405-552-6558 OKLAHOMA CITY, OK 73102 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Sec 3 T25S R31E Mer NMP NWNE 225FNL 1350FEL EDDY COUNTY, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ■ Water Shut-Off ☐ Acidize □ Deepen ☐ Production (Start/Resume) ■ Notice of Intent ☐ Hydraulic Fracturing ■ Well Integrity ☐ Alter Casing ☐ Reclamation ☐ Subsequent Report Other Casing Repair ■ New Construction □ Recomplete Change to Original A ☐ Plug and Abandon ☐ Temporarily Abandon ☐ Final Abandonment Notice □ Change Plans Convert to Injection ☐ Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Devon Energy respectfully requests to change the 5.5" production cement job from a 2 stage job as stated in the original APD to a single stage job. We propose to pump an 11 ppg lead slurry, and will use a 13.2 ppg tail slurry instead of the 14.8 ppg tail slurry in the original APD. Attached are the casing and cement design tables. SEE ATTACHED FOR CONDITIONS OF ATTROVAL NM OIL CONSERVATION ARTESIA DISTRICT 14. I hereby certify that the foregoing is true and correct. Electronic Submission #378599 verified by the BLM Well Information System For DEVON ENERGY PRODUCTION COMPAN, sent to the Carlsbad Committed to AFMSS for processing by MUSTAFA HAQUE on 06/12/2017 () RECEIVED Title REGULATORY SPECIALIST Name (Printed/Typed) LINDA GOOD (Electronic Submission) 6/12/20° Signature THIS SPACE FOR FEDERAL OR S ATE OFFICE USE PETROLLEUM ENGINZER Date 6/12 Title Approved By Musto Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease BUREAU OF LAND MANAGEMENT

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

which would entitle the applicant to conduct operations thereon

\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\*

Office

CARLSBAD FIELD GEFICE

Ruf 6-19.17

## **Cotton Draw Unit 272H Production Cement Sundry Request**

## **Casing Design**

Hole	Casing Interval		Csg.	Weight	Grade	Conn	SF	SF	SF
Size	From	То	Size	(lbs)			Collapse	Burst	Tension
8.75"	0	14,787'	5.5"	17	P-110	BTC	1.54	2.19	3.18
BLM Minimum Safety Factor					1.125	1.00	1.6 Dry 1.8 Wet		

All casing strings will be tested in accordance with Onshore Oil and Gas Order #2 III.B.1.h

## **Cement Program**

Casing	# Sks	Wt. lb/ gal	H₂0 gal/sk	Yld ft3/ sack	500# Comp. Strengt h (hours)	Slurry Description			
5-1/2"	583	11	20.22	3.26	28	Lead #1 : NeoCem™			
Prod Single Stage	1147	13.2	6.89	1.4	6	Tail: NeoCem <sup>™</sup>			
	480	11	19.8	3.19	48	Lead: NeoCem <sup>TM</sup>			
5-1/2"	1157	13.2	7.18	1.43	6	Tail: NeoCem <sup>™</sup>			
Prod	DV Tool = 4,700ft								
Two	40	11	19.8	3.19	48	Lead: NeoCem <sup>™</sup>			
Stage	30	14.8	6.32	1.33	6	2 <sup>nd</sup> Stage Tail: Class C Cement + 0.125 lbs/sack Poly- E-Flake			

If a DV tool is ran, depth(s) will be adjusted based on hole conditions and cement volumes will be adjusted proportionally. DV tool will be set a minimum of 50 feet below previous casing and a minimum of 200 feet above current shoe. Lab reports with the 500 psi compressive strength time for the cement will be onsite for review.

Casing String	TOC	% Excess
5-1/2" Production Casing	4,100'	10%
5-1/2" Production Casing Two Stage Option	1 <sup>St</sup> Stage = 4700' / 2 <sup>nd</sup> Stage = 4180'	10%

Nios

# PECOS DISTRICT CONDITIONS OF APPROVAL

**OPERATOR'S NAME:** Devon Energy Production Company, L.P.

**LEASE NO.: NMNM-046525** 

WELL NAME & NO.: Cotton Draw Unit 272H
SURFACE HOLE FOOTAGE: 0225' FNL & 1350' FEL
BOTTOM HOLE FOOTAGE 0330' FSL & 1450' FEL

LOCATION: Section 03, T. 25 S., R 31 E., NMPM

**COUNTY:** | **Eddy County, New Mexico** 

#### A. CASING

# All previous COAs still apply except the following:

1. The minimum required fill of cement behind the 5-1/2 inch production casing is:

# Option 1:

Cement should tie-back at least **200** feet into previous casing. Operator should provide method of verification.

# Option 2:

Operator has proposed DV tool at depth of 4700', but will adjust cement proportionately if moved. DV tool shall be set a minimum of 50' below previous shoe and a minimum of 200' above current shoe. Operator shall submit sundry if DV tool depth cannot be set in this range. If an ECP is used, it is to be set a minimum of 50' below the shoe to provide cement across the shoe. If it cannot be set below the shoe, a CBL shall be run to verify cement coverage.

- a. First stage to DV tool:
- Cement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with second stage cement job. Operator should have plans as to how they will achieve circulation on the next stage.
- b. Second stage above DV tool:
- Cement should tie-back at least 200 feet into previous casing. Operator should provide method of verification. Excess calculates to 9% additional cement might be required.

## MHH 06122017