Form 3160-5 (June 2015)

INITED STATES DEP BU

UNITED STATES	
PARTMENT OF THE INTERIOR	
REAU OF LAND MANAGEMENT	

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS OCD Artesia		5. Lease Serial No. NMNM85893							
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. CEDAR CANYON 21 FEDERAL COM 21H				
2. Name of Operator Contact: DAVID STEWART					9. API Well No.				
OXY USA INC. E-Mail: david_stewart@oxy.com					30-015-44181 10. Field and Pool or Exploratory Area				
3a. Address P.O. BOX 50250 MIDLAND, TX 79710 3b. Phone No. (include area code) Ph: 432-685-5717					CORRAL DRAW BONE SPRING				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State					
Sec 21 T24S R29E NENE 369FNL 368FEL 32.209271 N Lat, 103.982058 W Lon					EDDY COUNTY, NM				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent ■ Notice of Intent Notice of	☐ Acidize	□ Dee	oen	☐ Product	tion (Start/Resum	e) [Water Shut-Off		
-	☐ Alter Casing	🗖 Hyd	raulic Fracturing	Reclam	ation	0	☐ Well Integrity		
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	plete		Other Change to Original A		
☐ Final Abandonment Notice	☐ Change Plans		and Abandon	and Abandon			PD		
	☐ Convert to Injection	Plug	Back	ack					
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.									
OXY USA Inc. respectfully rec	quests approval for the follo	owing chang	es from the appr	oved permi	t:				
Change in Mud Program a. Replace MMH with water based Spud Mud in Surface Hole									
b. Replace Brine & MMH system with Direct Emulsion Water Based Mud in Intermediate Hole from 400 ARTESIA DISTRICT							SERVATION: ISTRICT		
c. Raise expected Mud Weight range from 8.6-9.2 ppg to 9.5-11.5 ppg due to weights seen in recent offsets.									
d. OXY will make the change contingent upon the vendor being ready to support the rig. If the									
14. I hereby certify that the foregoing is true and correct. Electronic Submission #378453 verified by the BLM Well Information System For OXY USA INC., sent to the Carlsbad									
Committed to AFMSS for processing by DEBORAH MCKINNEY on 06/13/2017 () Name (Printed/Typed) DAVID STEWART Title SR, REGULATORY ADVISOR									
Signature (Electronic Submission) Date 06/08/2017									
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved By Mallo			Title End]		· · · · · · · · · · · · · · · · · · ·	Date 6/13/17		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.									
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a c	crime for any pe	rson knowingly and	willfully to m	ake to any departme	ent or age	ncy of the United		

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

PuP 6.19-17

Additional data for EC transaction #378453 that would not fit on the form

32. Additional remarks, continued

vendor is not ready to support the rig, OXY will continue with the current MMH system that was permitted.

e. As discussed on 04/12/17, Oxy proposes to drill out the surface casing shoe with a Direct Emulsion Water Based Mud which will consist of an external saturated brine phase with pH above 10 at all times, from 400'?ICP. This will eliminate the need for two mud systems, to manage both the salt and losses circulation interval in the intermediate hole section.

Depth Mud Weight Funnel Vis Fluid Type 40-50 28-38 0-400' Spud Mud 8.4-8.6 N/C 9.0-10.0 9.5-11.5 400-ICP DEWBM N/C ICP-TD 28-34 OBM <15

2. OXY requests the option to contract a Surface Rig to drill, set surface casing, and cement for this well. If the timing between rigs is such that OXY would not be able to preset surface, the Primary Rig will MIRU and drill the well in its entirety per the APD. Please see the attached document for information on the spudder rig.

OXY USA Inc APD ATTACHMENT: SPUDDER RIG DATA

OPERATOR NAME / NUMBER: OXY USA Inc

1. SUMMARY OF REQUEST:

Oxy USA respectfully requests approval for the following operations for the surface hole in the drill plan:

1. Utilize a spudder rig to pre-set surface casing for time and cost savings.

2. Description of Operations

- 1. Spudder rig will move in to drill the surface hole and pre-set surface casing on the well.
 - **a.** After drilling the surface hole section, the spudder rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations).
 - **b.** The spudder rig will utilize fresh water-based mud to drill the surface hole to TD. Solids control will be handled entirely on a closed loop basis. No earth pits will be used.
- 2. The wellhead will be installed and tested as soon as the surface casing is cut off and the WOC time has been reached.
- 3. A blind flange at the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with needle valves installed on two wingvalves.
 - a. A means for intervention will be maintained while the drilling rig is not over the well.
- 4. Spudder rig operations are expected to take 2-3 days per well on the pad.
- 5. The BLM will be contacted and notified 24 hours prior to commencing spudder rig operations.
- **6.** Drilling operations will begin with a larger rig and a BOP stack equal to or greater than the pressure rating that was permitted will be nippled up and tested on the wellhead before drilling operations resume on each well.
 - **a.** The larger rig will move back onto the location within 90 days from the point at which the wells are secured and the spudder rig is moved off location.
 - **b.** The BLM will be contacted / notified 24 hours before the larger rig moves back on the pre-set locations.
- 7. Oxy will have supervision on the rig to ensure compliance with all BLM and NMOCD regulations and to oversee operations.
- **8.** Once the rig is removed, Oxy will secure the wellhead area by placing a guard rail around the cellar area.

Mud Mixing tank and Shaker echeration. Mud Pumps 1, & 2 Spudder Rig Layout Conex & Forklift Trailer Tool pusher