Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Reson	urces Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	ON GONGERMATION DIVIG	20 040 31637
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISI	5. Indicate Type of Lease
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		ETEI
	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK T	7. Lease Name or Unit Agreement Name
	CATION FOR PERMIT" (FORM C-101) FOR SUCH	OXY Bits State
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number
2. Name of Operator	Gas Well [2] Other	9. OGRID Number
OXY USA	WTP Limited Partnership	192463
3. Address of Operator	0350 Millard TV 70710	10. Pool name or Wildcat
	0250 Midland, TX 79710	Hackberry Morrow, W.
4. Well Location Unit Letter I: 1797 feet from the South line and 912 feet from the east line		
Section 36 Township LOS Range 30E NMPM County ELLY		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	3546'	
12. Check A	Appropriate Box to Indicate Nature of	Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK		IAL WORK ALTERING CASING
TEMPORARILY ABANDON	-	ENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING	G/CEMENT JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM OTHER:	☐ OTHER	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or rec	ompletion.	
		NM OIL CONSERVATION
		ARTESIA DISTRICT
	See Attached	JUN 1 6 2017
	Jee William Fee	0011 1 0 2017
		RECEIVED
		all bore only. receipt
		oluging of well pend pend plugging
<u>r</u>		Approved for plugging of well bore only. Approved for plugging of well plugging) Approved for plugging of well plugging) Approved for plugging of well plugging) Approved for plugging of well bore only. Approved for plugging of well plugging. Approved for plugging of well plugging of well plugging. Approved for plugging of well plugging of well plugging. Approved for plugging of well plugging of well plugging. Approved for plugging of well plugging of well plugging of well plugging. Approved for plugging of well plugging of we
Spud Date:	Rig Release Date:	Liability disubsequent at 0002 (se.nm.us/occ)
Space Bate.	Rig Release Date.	of Crisis may be mared the
		Aproved for plussing of well hore only. Aproved for plussing of well hore only receipt Liability under bond is retained pending receipt Liability under bond is retained for Well plussing of C.103 (Subsequent Report of Well Plussing under C.103 (Subsequent Report of Well plussing under Report of Well plussing under Report of C.103 (Subsequent Report of C.103)
I hereby certify that the information	above is true and complete to the best of my l	
SIGNATURE . S	TITLE Sr. Regulato	ry Advisor DATE 6/12/17
SIGNATURE 92-3	TILE Sr. Regulato	DATE CIACIT
Type or print name <u>David Stewa</u>	rt E-mail address: <u>david</u>	stewart@oxy.com PHONE: 432-685-5717
Factor II. O. I		
For State Use Only	0 1	
APPROVED BY: July 2	Syld TITLE COMPLIAN OF	OFFICER DATE 6/26/2017
Conditions of Approval (if any):		,

Attachment C-103 OXY Bits State #1 30-015-31937

2/16/17 - MIRU PU to P&A, ND tree, NU BOP. RIH & tag @ 3727', attempt to fish, mill, drill & work through 5-1/2" csg. 4/12/17 - POOH & LD approximately 3700' 5-1/2" csg, attempt to wash over, mill and work through 5-1/2" csg. RIH w/ 5-1/2" csg & latch on to csg collar # approximately 3700' 4/26/17. Continue to mill and work through csg to 5/11/17. Detail of work from 2/16-5/11/17 will be provided upon request.

- 5/12/2017 Csg-280# Tbg-0#. RU WL, RIH w/ 1.9" gauge ring, stack out @ 5200', POOH. RIH w/ 1-3/8" chisel to 9935', POOH. RIH & jet cut tbg @ 11410', tbg free, POOH w/ 1jt, circ hole.
- 5/15/2017 Csg/Tbg-340#. Continue to POOH w/ tbg. RIH w/ tbg to 11410'.
- 5/16/2017 Csq-250#. WO cementers. Circ hole w/ 10# MLF, M&P 75sx CL H cmt, PUH, WOC.
- 5/17/2016 Csg-250#. RIH & tag cmt @ 10572', PUH to 10274', circ w/ 10# MLF, M&P 25sx CL H cmt w/ 2% CaCl2, PUH, WOC. RIH w/ tbg & tag cmt @ 10088'. PUH to 9901', tbg plugged, POOH w/ tbg, LD 6 jts. RIH w/ tbg to 4500'.
- 5/18/2017 Csg-250#. RIH w/ tbg to 9901', circ w/ 10# MLF, M&P 25sx CL H cmt, PUH, WOC.
- 5/22/2017 CSG-260#. RIH & tag cmt @ 9437', POOH. RU WL, RIH w/ CBL from 7800-4500'. Rec appr-Robert Byrd-NMOCD to perf but no pkr. RIH & perf @ 7720', POOH. RIH w/ tbg to 7770'.
- 5/23/2017 Csg-200#. Circ w/ 10# MLF, M&P 40sx CL H cmt, PUH, WOC. RIH & tag cmt @ 7355', PUH to 5742', circ w/ 10# MLF, M&P 30sx Cl C cmt, PUH, WOC.
- 5/24/2017 Csg-250#, RIH & tag cmt @ 5450'. RIH w/ WL & cut 5-1/2" csg @ 3850'. CO BOP, POOH w/ 5-1/2" csg.
- 5/25/2017 Csg-200#, RIH w/ tbg to 3911', Circ w/ 10# MLF, M&P 250sx CL C cmt w/ 2% CaCl2, PUH, WOC. RIH & tag cmt @ 3335', M&P 150sx CI C cmt w/ 2% CaCl2, PUH, WOC.
- 5/26/2017 Csg/tbg-300#. RIH w/ tbg & tag cmt @ 3025', SI monitor csg, 100# in 1hr. RIH w/ pkr & set @ 2795'.
- 5/30/2017 Csg-0#, Tbg-350#. Pressure test plug @ 3025' to 100#, no rate, rel pkr, POOH.
- 5/31/2017 Csg-100#. RIH w/ WL & set CIBP @ 3025', POOH. RIH w/ tbg & tag CIBP @ 3025'. Circ w/ 10# MLF, M&P 40sx CL C cmt, Calc TOC-2904'. PUH to 1990', M&P 50sx CL C cmt w/ 2% CaCl2, PUH, WOC. RIH & tag cmt @ 1840', POOH.
- 6/1/2017 Csg-0#. RIH & perf @ 705', pressure test perfs to 600#, w/ no loss or rate. RIH w/ tbg to 775', M&P 275sx CL C cmt, circ to surface. POOH w/ tbg. ND BOP, top off csg w/ cmt, RDPU.