Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 2018							
5.	Lease Serial No. NMNM13413A						
6.	If Indian, Allottee or Tribe Name						

SUNDRY	NMNM13413A								
Do not use thi abandoned wel	6. If Indian, Allottee or Tribe Name								
SUBMIT IN 1	7. If Unit or CA/Agreement, Name and/or No.								
Type of Well	8. Well Name and No. SAM FEDERAL 2								
2. Name of Operator OXY USA INC.	9. API Well No. 30-015-24364								
3a. Address P.O. BOX 50250 MIDLAND, TX 79710	3b. Phone No. (include area code) Ph: 432-685-5717 Fx: 432-685-5742			10. Field and Pool or Exploratory Area ROCK SPUR MORROW (GAS)					
4. Location of Well (Footage, Sec., T.	11. County or Parish, State								
Sec 26 T25S R28E SWNE 19 32.102745 N Lat, 104.055611		EDDY COUNTY, NM							
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION	ACTION								
Notice of Intent	☐ Acidize	☐ Deepen		Producti	Production (Start/Resume)		Water Shut-Off		
Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing		Reclama	mation		Well Integrity		
	Casing Repair	☐ New Construction		☐ Recomp		⊠ Sh	Other outIn Notice		
Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection			☐ Tempora	rarily Abandon				
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. OXY USA Inc. ("OXY") operates the Sam Federal #2 (API 30-015-24364) well, being the only well holding Federal lease NMNM 13413A. OXY utilizes Enterprise Products Partners L.P.'s ("Enterprise") pipeline to transport gas produced from the Sam Federal #2, which is located in very close proximity to a dry creek bed that drains into the Pecos River. Due to the potential environmental impacts of leaks on this 300-foot lateral that connects the Sam Federal #2 to Enterprise's potash gathering system, Enterprise will be clamping this line and not putting it back into service until further discussions and evaluations can be made. OXY respectfully request a Shut-In Status for the Sam Federal #2, last production was 10/14/2016. RECEIVED Accepted for Record until 11/25/2017. See attached DAO.									
14. I hereby certify that the foregoing is Name(Printed/Typed) DAVID ST	Electronic Submission #3 For OX Committed to AFMSS for p	(Y USA INC., 🕏	ent to the Carlsb DEBORAH MCKI	ad	17/2017 ()		MOCD F 6/20/17		
Signature (Electronic S		Date ACCA	PTED F	OR RECOR	OS				
THIS SPACE FOR FEDERAL OF STATE OFFICE USE									
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the second of the sec	uitable title to those rights in the act operations thereon. U.S.C. Section 1212, make it a	subject lease crime for any per	son krowingly and	FAU OF LAN	5 2017 D MAN GEMENT	or agen	Date		
States any false, fictitious or fraudulent	statements or representations as	to any matter wi	nın its jurisdiction.		·				

OXY USA Inc. - Current Sam Federal #2 API No. 30-015-24364

26" hole @ 602' 20" csg @ 602' w/ 1800sx-TOC-Surf-Circ 17-1/2" hole @ 2637' 13-3/8" csg @ 2637' w/ 2600sx-TOC-Surf-Circ 12-1/4" hole @ 9765' 9-5/8" csg @ 9765' w/ 2600sx-TOC-2230'-TS DVT @ 5004' 8-1/2" hole @ 13460' 5" liner @ 9368-13460' w/ 1475sx-TOC-9368'-Circ Perfs @ 12632-13200' TD-13460'

2-3/8" tbg @ 11865' w/ DB Pkr @ 11850'

PB-13418'

Shut-In Status of a Producing Gas Well

Oxy USA Inc. Sam - 02, API 3001524364 T25S-R28E, Sec 26, 1980FNL & 1980FEL

05/25/2017 - Beginning 11/2016 until 11/25/2017 (the BLM designated renewal date) SI status accepted for record with this attached order of authorized officer. pswartz

- 1) This gas well accepted for a Shut-In Status of one year beginning the first report month of no production.
- 2) On or before the expiration of the BLM designated renewal date, submit a subsequent sundry for continued SI status acceptance or a notice of intent sundry for recompletion, or abandonment (temporary or permanent) for BLM approval.
- 3) For continued SI status, submit a subsequent sundry with a current 24hr production test, a BLM witnessed Mechanical Integrity Test chart record, and justification (wells capable of current production and not being produced due to location, facility, marketing, economic restrictions, or are BLM approved for a workover or recompletion may be accepted for continued Shut-In Status).
 - i) The minimum MIT pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with a minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need reduction).
 - ii) Verify that all annular casing vents are open to the surface atmosphere during this pressure test and record any reaction.
 - iii) Document the pressure test on a one hour full rotation chart recorder (calibrated within the last 6 months) registering within 35 to 75 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict status approval.
 - iv) Maintaining the annulus full of packer fluid at atmospheric pressure will suffice for the MIT pressure test requirement. Equipment that will display on site, continuous open to the air fluid level above the casing vent is necessary.
 - v) Excessive (+5 bbls/month) gain or loss of annular fluid volume requires BLM notification.
- 4) Upon production resumption submit a subsequent sundry of notification.
- 5) Federal Oil & Gas leases are held by well production or actively drilling for production during the end of the primary term of the lease. A Shut-In status will not hold the lease.
- 6) If you do not comply as noted, you shall be issued an Incident of Noncompliance (INC) in accordance with 43 CFR 3163.1(a). Failure to comply with the INC may result in assessments as outline in 43 CFR 3163.1, and may also incur civil penalties (43CFR 3163.2). All self-certified corrections must be postmark no later than the next business day after the prescribed time frame for correction.
- 7) Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.

8) A person contesting a decision shall request a State Director review of the Written Order. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4).