| Office | State of New Mexico | Form C-103 |
|--|--|---|
| <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 | Energy, Minerals and Natural Resources | Revised July 18, 2013 WELL API NO. |
| District II - (575) 748-1283 | OIL CONSERVATION DIVISION | 30-015-43828 |
| 811 S. First St., Artesia, NM 88210 <u>District III</u> - (505) 334-6178 | 1220 South St. Francis Dr. | 5. Indicate Type of Lease STATE FEE X |
| 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 | Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM | | |
| 87505 SUNDRY NOT | ICES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name |
| (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLI | OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH | WARREN FEDERAL COM |
| PROPOSALS.) 1. Type of Well: Oil Well | Gas Well 🛛 Other | 8. Well Number 206H |
| 2. Name of Operator MATADOR PRODUCTION | N COMPANY | 9. OGRID Number 228937 |
| 3. Address of Operator | | 10. Pool name or Wildcat |
| | STE 1500, DALLAS, TX 75240 | PURPLE SAGE;WOLFCAMP (GAS) |
| 4. Well Location Unit Letter O: | 246 feet from the S line and | 2322 feet from the E line |
| Section 25 | Township 23S Range 27E | NMPM County EDDY |
| 77 - 77E | 11. Elevation (Show whether DR, RKB, RT, GR, et | |
| | 3115' GR | |
| 10 01 1 | A | D (Od D) |
| 12. Check | Appropriate Box to Indicate Nature of Notice | e, Report or Other Data |
| | The state of the s | BSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK TEMPORARILY ABANDON | | RK ☐ ALTERING CASING ☐ ☐ RILLING OPNS.☐ P AND A ☐ |
| PULL OR ALTER CASING | | |
| DOWNHOLE COMMINGLE | | |
| CLOSED-LOOP SYSTEM | | _ |
| | | |
| OTHER: | OTHER: | and give pertinent dates including estimated date |
| 13. Describe proposed or com | pleted operations. (Clearly state all pertinent details, | and give pertinent dates, including estimated date |
| 13. Describe proposed or com | pleted operations. (Clearly state all pertinent details, a ork). SEE RULE 19.15.7.14 NMAC. For Multiple C | and give pertinent dates, including estimated date |
| 13. Describe proposed or com of starting any proposed w proposed completion or re | pleted operations. (Clearly state all pertinent details, a ork). SEE RULE 19.15.7.14 NMAC. For Multiple C | and give pertinent dates, including estimated date completions: Attach wellbore diagram of |
| 13. Describe proposed or composed of starting any proposed we proposed completion or re | pleted operations. (Clearly state all pertinent details, a ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. | and give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT @ 8454'. Well on gas lift. |
| 13. Describe proposed or composed of starting any proposed we proposed completion or re | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 | und give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT @ 8454'. Well on gas lift. o production. |
| 13. Describe proposed or composed of starting any proposed we proposed completion or re | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 | und give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT @ 8454'. Well on gas lift. |
| 13. Describe proposed or composed of starting any proposed we proposed completion or re | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 | und give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT @ 8454'. Well on gas lift. o production. |
| 13. Describe proposed or composed of starting any proposed we proposed completion or re | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 | und give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 07 2017 |
| 13. Describe proposed or composed of starting any proposed we proposed completion or re | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 | und give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT @ 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT |
| 13. Describe proposed or composed of starting any proposed we proposed completion or re | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 | und give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 07 2017 |
| 13. Describe proposed or composed was proposed completion or re 7/15/17 Install & NU product | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 tion tree, test to 8000 psi. Turn well over the state of the sta | und give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 07 2017 |
| 13. Describe proposed or composed starting any proposed we proposed completion or re 7/15/17 Install & NU produc | pleted operations. (Clearly state all pertinent details, a tork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 tion tree, test to 8000 psi. Turn well over t | und give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 0 7 2017 RECEIVED |
| 13. Describe proposed or composed with proposed completion or responsed comple | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 tion tree, test to 8000 psi. Turn well over to Rig Release Date: | and give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 0 7 2017 RECEIVED |
| 13. Describe proposed or composed with proposed completion or responsed comple | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 tion tree, test to 8000 psi. Turn well over the state of the sta | and give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 0 7 2017 RECEIVED |
| 13. Describe proposed or composed starting any proposed we proposed completion or re 7/15/17 Install & NU production of production of the NU production of | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 tion tree, test to 8000 psi. Turn well over to Rig Release Date: Rig Release Date: 04 | and give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 0 7 2017 RECEIVED |
| 13. Describe proposed or composed with proposed completion or responsed comple | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 tion tree, test to 8000 psi. Turn well over to Rig Release Date: Rig Release Date: Output TITLE Sr. Engineeri | and give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 0 7 2017 RECEIVED 1/04/17 dge and belief. |
| 13. Describe proposed or composed starting any proposed we proposed completion or re 7/15/17 Install & NU product Spud Date: 03/03/17 I hereby certify that the information SIGNATURE | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 tion tree, test to 8000 psi. Turn well over to above is true and complete to the best of my knowled the complete to the best of my knowled amonroe@matadorre | and give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 0 7 2017 RECEIVED 1/04/17 dge and belief. ng Tech DATE 08/03/17 sources.com |
| 13. Describe proposed or composed starting any proposed we proposed completion or re 7/15/17 Install & NU production of production of the NU production of | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 tion tree, test to 8000 psi. Turn well over to above is true and complete to the best of my knowled the complete to the best of my knowled amonroe@matadorre | and give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. o production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 0 7 2017 RECEIVED 1/04/17 dge and belief. |
| 13. Describe proposed or compost of starting any proposed we proposed completion or re 7/15/17 Install & NU product Spud Date: 03/03/17 I hereby certify that the information SIGNATURE Quality Type or print name Ava Monr For State Use Only | pleted operations. (Clearly state all pertinent details, a fork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. land tubing hanger. Install 2.875" 6/5# L80 tion tree, test to 8000 psi. Turn well over to above is true and complete to the best of my knowled the complete to the best of my knowled amonroe@matadorre | and give pertinent dates, including estimated date completions: Attach wellbore diagram of tubing w/ EOT • 8454'. Well on gas lift. tubing w/ EOT • 8454'. Well on gas lift. tubing w/ EOT • 8454'. Well on gas lift. to production. NM OIL CONSERVATION ARTESIA DISTRICT AUG 0 7 2017 RECEIVED MO4/17 dge and belief. ng Tech DATE 08/03/17 sources.com PHONE:972-271-5218 |