Form 3160-5 (June 2015) DF B	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.						
SUNDRY Do not use th	MultipleSee Attached						
Do not use th abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN	7. If Unit or CA/Agree MultipleSee At	ement, Name and/or No. ttached					
1. Type of Well	8. Well Name and No. MultipleSee Attached						
2. Name of Operator	9. API Well No. MultipleSee Attached						
	COG OPERATING LLC E-Mail: sballard@concho.com						
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701		Ph: 432-6		10. Field and Pool or Exploratory Area EMPIRE-ABO UNKNOWN			
4. Location of Well (Footage, Sec., 7		11. County or Parish, State					
MultipleSee Attached		EDDY COUNTY, NM					
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	Acidize	Dec	epen	Product	tion (Start/Resume)	□ Water Shut-Off	
_	Alter Casing		traulic Fracturing	🗖 Reclam		U Well Integrity	
	Subsequent Report Casing Repair		w Construction	Recomplete		Other Venting and/or Flari	
Final Abandonment Notice	 Change Plans Convert to Injection 	_	g and Abandon g Back			ng	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zone Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed one testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Parliament 1 Federal Com #4H Battery (Permit approval: Electronic Submission# 352099) Actual gas flared for this battery for 9/17/16 to 12/16/16 is as follows: Sept Total for Battery = 340 mcf Oct Total for Battery = 0 mcf Nov Total for Battery = 0 mcf							
Nov Total for Battery = 0 mcf							
Dec Total for Battery = 270 mcf							
		30-015	5-42 6 47				
14. I hereby certify that the foregoing is true and correct. Electronic Submission #382486 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 08/03/2017 (17PP0812SE)							
Name (Printed/Typed) SANDY BALLARD Title ADMINISTRATIVE ASSISTANT							
Signature (Electronic Submission)			Date 07/25/2017				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By ACCEPTED			OMAR ALOMAR TitlePETROLEUM ENGINEER Date 08/07/2017				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsbad				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISE	D ** BLM R	EVISED ** BLN		D ** BLM REVISE	D **	

с 1

Additional data for EC transaction #382486 that would not fit on the form

5. Lease Serial No., continued

NMLC064222 NMNM7752

4*

¢

7. If Unit or CA/Agreement, Name and No., continued

NMNM135473 NMNM135732

Wells/Facilities, continued

Agreement	Lease	Well/Fac Name, Number	APINumber	Location
NMNM135473	NMNM7752	PARLIAMENT 1 FEDERAL COM	UBBB-041-15-42647-00-S1	Sec 1 T17S R29E SENE 2310FNL 150FEL
NMNM135732	NMLC064222	MUNDS 1 FEDERAL COM 12H	30-015-41565-00-S1	32.864316 N Lat, 104.019625 W Lon Sec 1 T17S R29E Lot 1 890FNL 295FEL 32.868220 N Lat, 104.020082 W Lon

32. Additional remarks, continued

Number of wells to flare: (2) MUNDS 1 FEDERAL COM #12H 30-015-41565 PARLIAMENT 1 FED COM #4H UBB 30-015-42647 Reason for flare: unplanned midstream curtailment