Form 3160-5 (June 2015)

### **UNITED STATES** DEPARTMENT OF THE INTERIOR

OCD Artesi	•
------------	---

FORM APPROVED OMB NO. 1004-0137

BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.  SUBMIT IN TRIPLICATE - Other instructions on page 2					Expires: January 31, 2018  5. Lease Serial No. NMNM85893  6. If Indian, Allottee or Tribe Name				
								7. If Unit or CA/Agreement, Name and/or No.	
								Type of Well	8.
					2. Name of Operator OXY USA INC	Contact: DAVID STEWART E-Mail: david_stewart@oxy.com			
3a. Address	3b. Phone No. (include area code) Ph: 432.685.5717				10. Field and Pool or Exploratory Area CORRAL DRAW-BONE SPRING				
MIDLAND, TX 79710  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State				
Sec 21 T24S R29E SWNW 1 32.205410 N Lat, 103.99755			EDDY COUNTY, NM						
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE, RE	EPORT, OR OTI	IER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION								
■ N. CI	☐ Acidize	☐ Dee	pen	☐ Production	(Start/Resume)	☐ Water Shut-Off			
➤ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing		☐ Reclamation		■ Well Integrity			
☐ Subsequent Report	☐ Casing Repair		■ New Construction		e	<b>⊠</b> Other			
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon				Change to Original A PD			
	☐ Convert to Injection	Plug	Back		osal				
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for	nally or recomplete horizontally, ork will be performed or provide d operations. If the operation re- bandonment Notices must be file final inspection.	give subsurface the Bond No. or sults in a multipl ed only after all	locations and measu if file with BLM/BIA e completion or reco requirements, includ	red and true vertic Required subsection in a new ing reclamation, has	al depths of all pertir juent reports must be interval, a Form 316	nent markers and zones.  filed within 30 days  60-4 must be filed once			
OXY USA Inc. respectfully re	quests approval for the foll	lowing chang	es from the appr	oved permit:					
1. OXY requests the option to contract a Surface Rig to drill, set surface casing, and cement for this well. If the timing between rigs is such that OXY would not be able to preset surface, the Primary Rig will MIRU and drill the well in its entirety per the APD. Please see the attached document for information on the spudder rig.					NM OIL CONSERVATION ARTESIA DISTRICT				
					0	CT. 16 2017			
OXY proposes to drill out to will consist of an external sate. This will eliminate the need for interval in the intermediate/pressure.	urated brine phase with pl- or two mud systems, to ma	I above 10 at	all times, from 4 e salt and losses	00' to PCP.	h <del>I</del>	RECEIVED			
14. I hereby certify that the foregoing i	Electronic Submission #3	383513 verifie	d by the BLM Wel	I Information S	/stem	<del></del>			
C	For O) ommitted to AFMSS for pro		sent to the Carlsb NILLE ORTIZ on		O0031SE)				
Name (Printed/Typed) DAVID STEWART			Title SR REGULATORY ADVISOR						
Signature (Electronic	Submission)		Date 08/02/2	017					
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE USE					
		· · · · · · · · · · · · · · · · · · ·							
_Approved By ZOTA STEVENS _	Approved By_ZOTA STEVENS			<u>UM ENGINEEI</u>	R	Date 09/29/2017			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent that the appl									
certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsbad						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

# Additional data for EC transaction #383513 that would not fit on the form

### 32. Additional remarks, continued

Fluid Type Mud Weight
Spud Mud 8.4-8.6
DEWBM 9.0-9.5
DEWBM (Brine/OBM-Contingency) 9.5-10.0 Depth 0-400' 400-PCP PCP-TD

## OXY USA Inc APD ATTACHMENT: SPUDDER RIG DATA

**OPERATOR NAME / NUMBER: OXY USA Inc** 

### 1. SUMMARY OF REQUEST:

Oxy USA respectfully requests approval for the following operations for the surface hole in the drill plan:

1. Utilize a spudder rig to pre-set surface casing for time and cost savings.

#### 2. Description of Operations

- 1. Spudder rig will move in to drill the surface hole and pre-set surface casing on the well.
  - a. After drilling the surface hole section, the spudder rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations).
  - **b.** The spudder rig will utilize fresh water-based mud to drill the surface hole to TD. Solids control will be handled entirely on a closed loop basis. No earth pits will be used.
- 2. The wellhead will be installed and tested as soon as the surface casing is cut off and the WOC time has been reached.
- 3. A blind flange at the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with needle valves installed on two wingvalves.
  - **a.** A means for intervention will be maintained while the drilling rig is not over the well.
- **4.** Spudder rig operations are expected to take 2-3 days per well on the pad.
- 5. The BLM will be contacted and notified 24 hours prior to commencing spudder rig operations.
- **6.** Drilling operations will begin with a larger rig and a BOP stack equal to or greater than the pressure rating that was permitted will be nippled up and tested on the wellhead before drilling operations resume on each well.
  - **a.** The larger rig will move back onto the location within 90 days from the point at which the wells are secured and the spudder rig is moved off location.
  - **b.** The BLM will be contacted / notified 24 hours before the larger rig moves back on the pre-set locations.
- 7. Oxy will have supervision on the rig to ensure compliance with all BLM and NMOCD regulations and to oversee operations.
- **8.** Once the rig is removed, Oxy will secure the wellhead area by placing a guard rail around the cellar area.

