Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

## 5. Lease Serial No. NMLC029395B

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian Allottee or Tribe Name

abandoned wel	6. If Indian, Allottee	6. If Indian, Allottee or Tribe Name			
SUBMIT IN T	7. If Unit or CA/Agre	7. If Unit or CA/Agreement, Name and/or No.			
Type of Well     Gas Well ☐ Oth	8. Well Name and No TURNER B 37				
Name of Operator Contact: DEBI GORDON LINN OPERATING INCORPORATED E-Mail: DGORDON@LINNENERGY.COM			9. API Well No. 30-015-05193-	 00-\$1	
3a. Address         3b. Phone No.           600 TRAVIS STREET SUITE 5100         Ph: 281-84		o. Phone No. (include area code) h: 281-840-4010 x: 832-209-4340	10. Field and Pool or GRAYBURG	10. Field and Pool or Exploratory Area GRAYBURG	
4. Location of Well (Footage, Sec., T.		11. County or Parish,	11. County or Parish, State		
Sec 17 T17S R31E SWSW 33		EDDY COUNT	EDDY COUNTY, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	INDICATE NATURE O	F NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize	Deepen	☐ Production (Start/Resume)	■ Water Shut-Off	
	Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
Subsequent Report	Casing Repair	■ New Construction	□ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon		
	Convert to Injection	☐ Plug Back	■ Water Disposal		
testing has been completed. Final Abdetermined that the site is ready for final Abdetermined that the site is ready for final Abdetermined that the site is ready for final OPERATING, LLC IS RIPERED WELL LOCATED TO BE CO	andonment Notices must be filed of inal inspection.  ESPECTFULLY SUBMITTIN FED IN EDDY COUNTY, NM MPLETED BY 12/25/2017.  RY AND FINAL WELLBORE IMENT OPERATIONS WER	only after all requirements, includ IG A FINAL PLUG AND AB I. THIS WELL WAS IN AN E DIAGRAMS ARE ATTAC	BANDONMENT REPORT FOR EXPIRED TA STATUS. CORF	and the operator has THE RECTIVE	
	Electronic Submission #398 For LINN OPERATIN nmitted to AFMSS for process	G INCORPORATED, sent to sing by PRISCILLA PEREZ or	the Carlsbad n 12/21/2017 (18JA0042SE)		
Name (Printed/Typed) DEBI GOI	Title REGUL	ATORY MANAGER			
Signature (Electronic S	Submission)	Date 12/21/20	017		
Accepted for Record	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE		
Approved By	a. amos	Title	pu. PET	12-27-17 Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive the applicant to conduct the second conductive th	itable title to those rights in the sul		140 140		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent			willfully to make to any department of	or agency of the United	

## TURNER B #37 API#: 30-015-05193 FINAL PLUG & ABANDONMENT OPERATIONS

12/14/2017	Moved rig and equipment to location. Dig out well head. Spot rig, MIRU. Rigged up all equipment. Well head was about 4' deep in cellar, waited on 2 spools to
	NUBOP. Spools here, NUBOP. S/I well, SDFN.
12/15/2017	Crew to location. Held daily safety meeting, go over JSA. Open well up, 0 press on well. RIH W/ 54 jnts and packer to 1750' and tag CIBP. Set packer, test CIBP
	to 500 psi, held good. Circ. Hole with 74 bbls 9.5 ppg. MLF. POOH W/ packer RU
	wireline, RIH to 1314' and perf. POOH W/ wireline. RIH W/ packer to 1364', tried
	to establish injection rate but unable to. Notified BLM. Got ok to spot 30 sxs. Mix
	up and pump 30 sxs. @ 14.8 ppg. Displace with 5 bbls. Calc'd, TOC 1189"
	Release packer, POOH with tubing and packer. S/I well, SDFN. Will tag plug
	Monday morning.
12/18/2017	Crew to location. Held safety meeting, go over JSA. Open up well, 0 press on
	well. RIH and tag cement @ 1180'. Notified BLM. POOH, RU wireline, RIH and
	perf @ 583'. POOH W/ wireline RIH W/ tubing and packer to 260', break circ. Set
	packer, Establish injection rate @ 2 bpm @ 500 psi. Squeeze 50 sxs. Class c @
	14.8ppg / 2% Cacl. Displace W/ 8 bbls F/W. Calc. TOC.445', WOC. Bled of
	press, release packer, POOH. LD packer, RIH open ended and tag TOC @ 453'.
	Notified BLM. POOH, RU wireline, RIH and perf @ 100'. RD wireline. NDBOP,
	RIH W/ 1 joint and packer and set @ 20'. Establish injection rate @ 2bpm 300
	psi. Pump 50 sxs. Class c @ 14.8 ppg. Cement to surface. Release packer,
	POOH and lay down. Top off well with cement. RD plugging rig and all
	equipment, prep to move to Skelly Unit 21 today.
12/20/2017	Cut wellhead and weld on below ground level dry hole marker as required.

FINAL PLUG AND ABANDONMENT OPERATIONS WERE COMPLETED 12/20/2017

