Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR OIL CONSERVATION BUREAU OF LAND MANAGEMENT ARTESIA DISTRICT

	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018
5.	Lease Serial No. NMNM118108

SUNDRY NOTICES AND REPORTS ON WELLS no Do not use this form for proposals to drill or to re-order and	2018
Do not use this form for proposals to drill or to re-writer ah J	2010
handened well. Hee form 2460 2 (ABD) for such proposals	

	s form for proposals to C II. Use form 3160-3 (APD			6.	If Indian, Allottee or	Tribe Name
SUBMIT IN 1	7.	7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well			Well Name and No. MultipleSee Attac	ched		
2. Name of Operator	Contact: [OORIAN K F	JENTES	9.	API Well No.	anhad
CHEVRÓN USA INCORPORA	ATED E-Mail: DJVO@CH				MultipleSee Att	
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706 3b. Phone N Ph: 432-6			(include area code) 7-7631	10	10. Field and Pool or Exploratory Area WILDCAT	
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			13	. County or Parish, S	tate
MultipleSee Attached					EDDY COUNTY	, NM
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE, RI	EPORT, OR OTH	ER DATA
TYPE OF SUBMISSION			TYPE OF	ACTION		
Notice of Intent ■	☐ Acidize ☐ Dec		epen		(Start/Resume)	☐ Water Shut-Off
	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclamation	on	■ Well Integrity
☐ Subsequent Report	Casing Repair	□ Nev	Construction	☐ Recomplet	e	⊠ Other
☐ Final Abandonment Notice	☐ Change Plans	Plug	☐ Plug and Abandon		ly Abandon	Change to Original A
	☐ Convert to Injection	Injection		■ Water Disposal		
determined that the site is ready for for CHEVRON RESPECTFULLY HH SO 8 P2 5H 30 -015 -4 HH SO 8 P2 6H 30 -015 -4 HH SO 8 P2 13H 30 -015 -4 HH SO 8 P2 14H 30 -015 -4 HH SO 8 P2 21H 30 -015 HH SO 8 P2 22H -70 -6 THE SUMMARY ATTACHED CASING OF THE 6 WELLS L	REQUEST THE ABILITY 139351 / - 9 13933 13931 13931 13931 13931 13931 13931 13931	-18 - moop SEE AT CONDI	Carlsbac TAC O O TIONS OF	d Field Xrte APPRO	Office sia VAL	
14. I hereby certify that the foregoing is	Electronic Submission #3	SA INCORPO	RATED. sent to t	he Carlsbad		
	K FUENTES			ATORY SPEC	•	
		:				
Signature (Electronic	Submission)		Date 07/27/2	017		
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE USE		
_Approved_By_ZOTA_STEVENS			TitlePETROLE	UM ENGINEE	R	Date 01/02/2018
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of th	uitable title to those rights in the		Office Carlsbac	d		
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a	crime for any pe	rson knowingly and	willfully to make	to any department or	agency of the United

Additional data for EC transaction #382905 that would not fit on the form

Wells/Facilities, continued

Agreement	Lease	Well/Fac Name, Number	API Number	Location
NMNM118108	NMNM118108	HH SO 8 P2 5H	30-015-43935-00-X1	Sec 17 T26S R27E SESW 255FNL 960FWL
NMNM118108	NMNM118108	HH SO 8 P2 13H	30-015-43933-00-X1	Sec 17 T26S R27E NWNW 305FNL 960FWL
NMNM118108	NMNM118108	HH SO 8 P2 14H	30-015-43931-00-X1	Sec 17 T26S R27E NWNW 330FNL 960FWL
NMNM118108	NMNM118108	HH SO 8 P2 21H	30-015-43927-00-X1	Sec 17 T26S R27E NWNW 205FNL 960FWL
NMNM118108	NMNM118108	HH SO 8 P2 22H	30-015-43928-00-X1	Sec 17 T26S R27E NWNW 230FNL 960FWL
NMNM118108	NMNM118108	HH SO 8 P2 6H	30-015-43934-00-X1	Sec 17 T26S R27E NWNW 280FNL 960FWL

32. Additional remarks, continued

SHOULD YOU HAVE ANY QUESTIONS, PLEASE GIVE ME A CALL @ 432-687-7631.

Delaware Basin in Eddy County


Changes to APD for Federal Wells

HH SO 8 P2	5H	30-015-43935
HH SO 8 P2	6H	30-015-43934
HH SO 8 P2	13H	30-015-43933
HH SO 8 P2	14H	30-015-43931
HH SO 8 P2	21H	30-015-43927
HH SO 8 P2	22H	30-015-43928

Rig Patterson 270

CVX Contact: Rod Milligan Drilling Engineer 281-413-9794

CVX Contatct: Dorian K. Fuentes Regulatory Specialist 432-687-7631



Surface Hole:

- 1. Drill 17-1/2" surface hole with fresh water to planned casing set depth with 10' rat hole.
- 2. Run casing as stated by approved APD, land out wellhead, and cement.
- 3. Dress out 13-5/8" 5M SH-2 wellhead and install/secure with temporary abandonment cap, and a pressure gauge will be installed. Reference image below *Part U 399984*
- 4. Skid to next well according to below "Drill Order" Repeat 1 through 3 until all six surface holes are drilled, cased and cemented

Intermediate Hole:


- 1. N/U, using an API approved Quick-Connect, and test 13-5/8" 10M Class IV BOP to 250 psi/ 5,000 psi.
- 2. Test casing to required pressure. Drill out shoe track and 10' of new formation. Perform FIT. Drill 12-1/4" intermediate hole to planned casing set depth with ~10' of rat hole.
- 3. Run casing as stated by approved APD, land out hanger and cement.

Production Hole:

- 1. Test casing to required pressure. Drill out shoe track and 10' of new formation. Perform FIT. Drill 8-3/4" vertical section, curve, and lateral as stated by approved APD.
- 2. Run casing as stated by approved APD, cement, land out hanger and cement.
- 3. Install back pressure valve and temporary abandonment cap. Repeat steps in intermediate hole and production hole until all Six wells are drilled, cased, and cemented.

Summary: Variance to batch drill the HH SO 10 P3 not requested in the MDP nor original submittal.

Chevron respectfully request the ability to batch drill in the HH SO 8 P2 13H, 14H, 21H, 22H, 5H, 6H. The summary provided is a brief description of the main operational sequences for drilling and casing the six wells referenced.



PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: | Chevron USA Inc.

LEASE NO.: | NMNM-118108

WELL NAME & NO.: | HH SO 8 P2 22H

SURFACE HOLE FOOTAGE: | 0230' FNL & 0960' FWL

BOTTOM HOLE FOOTAGE | 0180' FNL & 0996' FWL Sec. 05, T. 26 S., R 27 E.

LOCATION: Section 17, T. 26 S., R 27 E., NMPM

COUNTY: | **Eddy County, New Mexico**

All COAs still apply expect the following:

1. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.

- a. In the event the operator has proposed to drill multiple wells utilizing a skid/walking rig. Operator shall secure the wellbore on the current well, after installing and testing the wellhead, by installing a blind flange of like pressure rating to the wellhead and a pressure gauge that can be monitored while drilling is performed on the other well(s).
- b. When the operator proposes to set surface casing with Spudder Rig
 - Notify the BLM when moving in and removing the Spudder Rig.
 - Notify the BLM when moving in the 2nd Rig. Rig to be moved in within 90 days of notification that Spudder Rig has left the location.
 - BOP/BOPE test to be conducted per Onshore Oil and Gas Order No. 2 as soon as 2nd Rig is rigged up on well.

ZS 010218