Submit 1 Copy To Appropriate District	State of New Me	xico	Form C-103			
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013			
<u>District I</u> – (575) 555-6161 1625 N. French Dr., Hobbs, NM 882 N <u>District II</u> – (575) 748-1283	W 30	WELL API NO. 30-015-24805				
811 S. First St., Artesia, NM 88210 <u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	ARTE OID: CONSERVATION JAN 2 6 ¹ 220 South St. Fran Santa Fe, NM 87		5. Indicate Type of Lease STATE STATE			
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	RECEIVED		6. State Oil & Gas Lease No. E-135			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Cockatoo State			
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well 🗌 Other	8. 8.	Well Number 1			
2. Name of Operator COG Operating, LLC			OGRID Number 9137			
3. Address of Operator 600 W. Illinois Ave, Midland, TX		10. Pool name or Wildcat Red Lake; Queen-GRBG-SA				
4. Well Location		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
Unit Letter <u>N</u> :	330 feet from the S	line and1716_	feet from theW	line		
Section 27	Township 17S Rang	ge 28E NM	PM County EDDY			
	11. Elevation (Show whether DR, 3677" gr	RKB, RT, GR, etc.)				

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK 🛛 ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS. P AND A	\boxtimes
PULL OR ALTER CASING		MULTIPLE COMPL		CASING/CEMENT JOB	
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM					
OTHER:				OTHER:	

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1/08/18 Moved rig to location. 01/09/18 Rigged up plugging equipment. POH w/ 110 ¼" rods & pump. Dug out cellar, ND well head, NU BOP. POH w/ 85 jts 2 3/8" J55 4.6# 8rd tbg. Set 5 ½" CIBP @ 2327'. Circulated hole w/ MLF. Pressure tested csg. Tried to pressure test csg, isolated holes in 5 ½" csg @ surface. 01/10/18 Spotted 25 sx class C cmt w/ 2% CACL @ 2327-2082'. WOC. Tagged plug @ 2115'. Spotted 25 sx class C cmt @ 850-606'. WOC. 01/11/18 Tagged plug @ 635'. Perf'd csg @ 568'. Pressured up on perfs to 500 psi. Perf'd csg @ 100'. Pressure tested perfs @ 2 bbls per minute @ 500 psi, no circulation. Spotted 25 sx class C cmt w/ 2% CACL @ 618-377'. WOC. Tagged plug @ 385'. ND BOP. Sqz'd 40 sx class C cmt through perfs @ 100' & displaced to 10'. WOC. 01/12/18 Tagged plug @ 20'. Spotted 2 sx class C cmt @ 20' & circulated to surface. Rigged down & moved off. 01/16/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.

Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and c SIGNATURE Kanicia Custillo For State Use Only		date 24 18 phone: 432-685-4332
APPROVED BY: Conditions of Approval (if any):	TITLE STATE Mgr	DATE /-26-18