Form 3160-5 (June 2015)

#### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY I	5. Lease Serial No. NMNM05039A						
Do not use thi abandoned wel	6. If Indian, Allottee or Tribe Name						
SUBMIT IN 7	RIPLICATE - Other me	หนังที่จกร จิก เ	age 2	ice	7. If Unit or CA/Agree	ment, l	Name and/or No.
		A	rtesia				<del>" </del>
<ol> <li>Type of Well</li> <li>Gas Well</li> <li>Oth</li> </ol>	ner 👢				8. Well Name and No. POKER LAKE UN	IT 474	H
Name of Operator     BOPCO LP		9. API Well No. 30-015-43425-00-X1					
3a. Address 6401 HOLIDAY HILL RD BLDG 5 SUITE 200 MIDLAND, TX 79707  3b. Phone No. (include area code) Ph: 432-620-6714					10. Field and Pool or Exploratory Area CORRAL CANYON		
4. Location of Well (Footage, Sec., T.		11. County or Parish, State					
Sec 27 T25S R30E NESE 1980FSL 980FEL					EDDY COUNTY, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICAT	TE NATURE O	F NOTICE,	REPORT, OR OTH	ŒR I	DATA
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent     ■	☐ Acidize	☐ Deep	en	☐ Producti	on (Start/Resume)	<b>0</b> /	Water Shut-Off
	☐ Alter Casing	☐ Hydi	☐ Hydraulic Fracturing		tion	<i>a</i> /	Well Integrity
☐ Subsequent Report	□ Casing Repair	□ New	Construction	□ Recomp	plete		Other
☐ Final Abandonment Notice	Change Plans	🗖 Plug	and Abandon	☐ Tempora	arily Abandon	Dri	lling Operations
	☐ Convert to Injection	Plug	☐ Plug Back ☐ W		Water Disposal		
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for final BOPCO, L.P. respectfully requestuck while drilling and losing procedure for the original oper After TOOH, the BHA stuck at was left in the hole. TOF: 687	operations. If the operation re- pandonment Notices must be fil- inal inspection.  Lests to deviate the interre- the hole. Details of the si- in hole is included along v	results in a multiple led only after all in mediate portion tuation are not vith a wellbore the BHA free.	e completion or rece equirements, include n of the well after led below. A plu diagram.	ompletion in a n ling reclamation er the BHA gr gging	ew interval, a Form 3166, have been completed a y-y-lot cepted for record	0-4 mu ind the 8 NN	st be filed once operator has  FOR
assembly. RIH to C/O well. His circulation.	t tight spot @ 3983? and	were able to v	vash/ream to 51	196?. Los <b>C (</b>	DNDITIONS	S OI	F APPROV.
In lieu of going further and pot hole from 5196-1012?. At this the surface csg shoe, and slid	point, BOPCO would D/0	D a portion of	cement, perform	ı a shallow K	/O at - १६/६	けたつれ	NSERVATIO.
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #	Angsos verifie	hy the BIM We	ll Information	System	4PR	0 3 2018
	For I	BOPCO LP. se	nt to the Carlsba	ıd	-,		
	mmitted to AFMSS for pro	cessing by 24		03/29/2018 (1 ATORY ANA		段價	CEIVED
Name (17theartypea) STEFFIAN	NE NABADUL		THE NEGOL	ATONT ANA	101		
Signature (Electronic S	Submission)		Date 03/28/2	018			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	SE		
_Approved By_ZOTA STEVENS			TitlePETROLE	UM ENGINE	ER	l	Date 03/29/2018
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of t	Office Carlsbad						
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a statements or representations as	crime for any pe s to any matter wi	rson knowingly and thin its jurisdiction.	willfully to ma	ke to any department or	agency	of the United

## Additional data for EC transaction #409595 that would not fit on the form

### 32. Additional remarks, continued

the original hole, following the same drilling plan design as approved.

Proposed Plug Back Procedure: 1.Dump Cl C cmt fr/5196?-3983?. WOC. Tag TOC. 2.Set OH Cl C cmt plug fr/3945?-3895?. WOC. Tag TOC. 3. Set OH Cl C cmt plug fr/1150-1050?. WOC. Tag.

Once plugs are set, the cmt fr/the uppermost plug will be used to create a KOP for hole deviation and continued drilling.

	Poker Lake Unit 474H - Current Wellbore Schematic  Wolfcamp A, 3 Mile Lateral									
	County: SHL:	<b>Eddy</b> 980' FEL, 1980' FSL Sec 27, T25S, R30E	<b>%то</b>	AFE # XTO ID #	1702460 996794					
	BHL:	990' FEL, 2440' FNL Sec 10, T26S, R30E	ENERGY	API# Elevation	30-015-43425 GL 3290', KB 3313' (23' AGL)					
	Area:	Water Basin		Rig:	Frontier 17 (23' RKB)					
	Geology	Casing & Cement	<u>Wellhead</u> 10k	Hole Size	General Notes					
TVD	Formation	<u>Lead (100% OH excess)</u> 600 sx 13.6ppg class C Top of Lead @ 0'	(Tech Data Sheet)	17-1/2"	Notify BLM prior to spud, running casing, cementing, and BOP testing  Drill out with 8.4-8.7 ppg FW mud					
865'	Rustler	Tail (100% OH excess) 345 sx 14.8ppg class C Top of Tail @ 712'			RU Mud Loggers on Surface Inc/Az survey every stand					
		13-3/8" 68# J-55 BTC > 25' into Rustler Per BLM	1012' MD	12-1/4"	Isolation/Kick-Off Plug from ~1700' - 950'					
1,317'	Top of Salt				Kick off ~1200'					
3,720'	Base of Salt				Isolation Plug from Top of Delaware - 100' above Base of Salt					
3,920'	Delaware		* 40		Tight hole/spot at ~3983' that we have gotten stuck at before; cannot go back through without further issue					
4,841'	Cherry Canyon				Could not wash/ream past 5196'					
6,420'	Brushy Canyon				Top of Fish 6871'					
7,469'	Basa! Brushy Canyon		7993' MD		Bottom of Fish 7908'					

,3

# POKER LAKE UNIT 474H 30-015-43425 BOPCO, LP Conditions of Approval

Notify BLM at 575-361-2822 (Eddy County) or 575-393-3612 (Lea County) a minimum of 24 hours prior to commencing work.

### Work to be completed by June 30, 2018.

- 1. Operator shall spot 722 sks Class C cement from 5196 ft to 3983ft. WOC & Tag required.
- 2. Spot 32 sks Class C cement from 3945 ft to 3895ft. WOC and Tag.
- 3. Spot 196 sks Class C cement from 1367ft to 1050 ft. WOC and Tag.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 10. See attached for General Plugback Guidelines

ZS 032918

### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plug back operations shall commence within <u>ninety (90)</u> days from this approval. If you are unable to plug back the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u> If plugging back to a new zone submit a Completion Report, form 3160-4 with the Subsequent Report.
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.