

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMNM20965

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
RDX FEDERAL COM 17 037H9. API Well No.
30-015-4354410. Field and Pool or Exploratory Area
PURPLE SAGE; WOLFCAMP (GAS)11. County or Parish, State
EDDY COUNTY, NM**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

RKI EXPLORATION & PRODUCTION E-Mail: caitlin.ohair@wpenergy.com

Contact: CAITLIN O'HAIR

3a. Address

3500 ONE WILLIAMS CENTER MD 35
TULSA, OK 74172

3b. Phone No. (include area code)

Ph: 539-573-3527

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 17 T26S R30E 200FNL 760FWL

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Hydraulic Fracturing☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☒ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleteness horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleteness in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

RKI EXPLORATION AND PRODUCTION, LLC PROPOSES TO DISPOSE WATER TO THE FOLLOWING FACILITIES LOCATED IN LOVING, TX:

DAM SITE UNIT #1, API 42-301-30047, UIC 000102256 ✓
STATELINE SWD 2 #1, API 42-301-31961, UIC 000107340 ✓
STATELINE SWD 2 #2, API 42-301-31958, UIC 000107045 ✓
STATELINE SWD 2 #3, API 42-301-31959, UIC 000107341 ✓
STATELINE SWD 2 #4, API 42-301-31960, UIC 000107342 ✓
RED BLUFF 8 #1, API 42-301-30294, UIC 000100957 ✓
RED BLUFF 8 #2D, API 42-301-30333, UIC 000101482 ✓
RED BLUFF DEEP #1D, API 42-301-30225, UIC 000102257 ✓

RECEIVED

MAY 31 2018

APPROVED

MAY - 9 2018

McKinney, L.E.
BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICECc 6-4-18
Accepted for record - NMOC

DISTRICT # ARTESIA O.C.D.

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #412800 verified by the BLM Well Information System
For RKI EXPLORATION & PRODUCTION, sent to the Carlsbad
Committed to AFMSS for processing by DEBORAH MCKINNEY on 05/01/2018 ()

Name (Printed/Typed) CAITLIN O'HAIR

Title SUBMITTER

Signature (Electronic Submission)

Date 04/30/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Date


Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)


**** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ****



SURFACE FLOW
DIRECTION

SURFACE FLOW
DIRECTION

LEGEND



PLAN LOCATED AT: WPX ENERGY PRODUCTION, INC. 5315 Buena Vista Carlsbad NM, 88220

FACILITY SITE DIAGRAM

RKI Exploration & Production, LLC - Permian Basin
RDX 17-36H, 37H

Latitude: 32.025740° Longitude: -103.543510°
UNIT K, SEC. 17, T26S, R30E
API: 30-015-43636 (43544)
EDDY COUNTY, NM

DRAWN BY: Kevin Fox

DATE: 3.8.2018

PREPARED BY: HRI COMPLIANCE SOLUTIONS, INC.
Environmental Consultants

Equipment: Volume & Dimensions

Oil Tank #1: 500 Bbl oil, 12.0' diameter
Oil Tank #2: 500 Bbl oil, 12.0' diameter
Oil Tank #3: 500 Bbl oil, 12.0' diameter
Oil Tank #4: 500 Bbl oil, 12.0' diameter
Oil Tank #5: 500 Bbl oil, 12.0' diameter
Oil Tank #6: 500 Bbl oil, 12.0' diameter
Oil Tank #7: 500 Bbl oil, 12.0' diameter
Oil Tank #8: 500 Bbl oil, 12.0' diameter

Water Tank #1: 500 Bbl produced water, 12.0' diameter
Water Tank #2: 500 Bbl produced water, 12.0' diameter
Water Tank #3: 500 Bbl produced water, 12.0' diameter
Water Tank #4: 500 Bbl produced water, 12.0' diameter

Heater Treater #44: 100.72 Bbl, 6.0' diameter
Heater Treater #45: 100.72 Bbl, 6.0' diameter
Production Separator #46: 179.10 Bbl, 8.0' diameter
Scrubber Unit #1: 0.42 Bbl, 1.0' diameter
Scrubber Unit #2: 0.42 Bbl, 1.0' diameter
Scrubber Unit #3: 0.42 Bbl, 1.0' diameter
Scrubber Unit #4: 0.42 Bbl, 1.0' diameter

Production Phase: Sales valves S1 through S8 sealed closed. Fill valve (F) to tank that is in production will be open. Equalizer valve (E) in tank that is in production will be open. Circulating valves (C) will be open as necessary, then released.

Sales Phase: The tank from which sales are being made will be isolated by sealing closed the fill valve, circulating valve, and the equalizer valve during sales and opening the sales valve. Upon completion of the sale the sales valve will be released. Sales by truck will be by tank gauge.

Valve	Production Phase	Sales Phase	Consolidating
S1	Closed	Open	Closed
S2	Closed	Open	Closed
S3	Closed	Open	Closed
S4	Closed	Open	Closed
S5	Closed	Open	Closed
S6	Closed	Open	Closed
S7	Closed	Open	Closed
S8	Closed	Open	Closed
E1	Closed	Open	Closed
E2	Closed	Open	Closed
E3	Closed	Open	Closed
E4	Closed	Open	Closed
E5	Closed	Open	Closed
E6	Closed	Open	Closed
E7	Closed	Open	Closed
E8	Closed	Open	Closed
C1	Closed or Open	Closed	Closed
C2	Closed or Open	Closed	Closed
C3	Closed or Open	Closed	Closed
C4	Closed or Open	Closed	Closed
C5	Closed or Open	Closed	Closed
C6	Closed or Open	Closed	Closed
C7	Closed or Open	Closed	Closed
C8	Closed or Open	Closed	Closed
F1	Closed or Open	Closed	Closed or Open
F2	Closed or Open	Closed	Closed or Open
F3	Closed or Open	Closed	Closed or Open
F4	Closed or Open	Closed	Closed or Open
F5	Closed or Open	Closed	Closed or Open
F6	Closed or Open	Closed	Closed or Open
F7	Closed or Open	Closed	Closed or Open
F8	Closed or Open	Closed	Closed or Open
F9	Closed or Open	Closed	Closed or Open
F10	Closed or Open	Closed	Closed or Open
F11	Closed or Open	Closed	Closed or Open
F12	Closed or Open	Closed	Closed or Open
F13	Closed or Open	Closed	Closed or Open
F14	Closed or Open	Closed	Closed or Open
F15	Closed or Open	Closed	Closed or Open
F16	Closed or Open	Closed	Closed or Open
F17	Closed or Open	Closed	Closed or Open
F18	Closed or Open	Closed	Closed or Open
F19	Closed or Open	Closed	Closed or Open

