NMOCD

Form 3160-5

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137

JUN 2 0 2018 (June 2015) Expires: January 31, 2018 5. Lease Serial No. 00017280 **BUREAU OF LAND MANAGEMENT** Do not use this form for proposals to drill or to re-entended TESIA Of 17 Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for subiPproposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well 8. Well Name and No. South Lucky Lake QN UT #4 Other Oil Well Gas Well 2. Name of Operator Bar V Barb, LLC 9. API Well No. 30-005-60381 10. Field and Pool or Exploratory Area 3a. Address PO BOX 4435 3b. Phone No. (include area code) Roswell, NM 88202 (575) 973-1346 Queen Formation 11. Country or Parish, State 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) N-22-15S-29E 990 FSL 14 TI FWL United States, NM, Chaves County 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Reclamation Well Integrity Alter Casing Hydraulic Fracturing New Construction Other Casing Repair Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Water Disposal Final Abandonment Notice Convert to Injection Plug Back 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.) This is notification that Bar V Barb, LLC is taking over operations of this plugged well in the South Lucky Lake Queen Unit and is submitting for change of Bar V Barb, LLC., as new operator, acceptst all applicable terms, conditions, stipulations and restrictions concerning operations conducted ont his lease, or portion o flease described. Bond Coverage: BLM Bond File No.: NMB001321 Change of Operator Effective: December 15, 2015 SEE ATTACHED FOR Former Opertator: Tandem Energy Corporation (236183) CONDITIONS OF APPROVAL 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Owner/Operator Steve Oldfield Title Signature THE SPACE FOR FEDERAL OR STATE OFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office

(Instructions on page 2)

which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfull

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

## Change of Operator of Wells on Federal Lands Conditions of Approval

- 1. Tank battery must be bermed/diked (must be able to contain 1-1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Bob Hoskinson at (575) 627-0218 for inspection and to resolve environmental issues.
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with the New Mexico State BLM office in Santa Fe, NM.