

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
DISTRICT II-ARTESIA O.C.D.

Form C-103
Revised July 18, 2013

WELL API NO. 30-015-24477	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. B-2071	
7. Lease Name or Unit Agreement Name NG Phillips State	
8. Well Number 32	
9. OGRID Number 229137	
10. Pool name or Wildcat Artesia;Qn-Grbg-SA	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator COG Operating, LLC	
3. Address of Operator 600 W. Illinois Ave, Midland, TX 79701	
4. Well Location Unit Letter P : 440 feet from the S line and 979 feet from the E line Section 27 Township 17S Range 28E NMPM County Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3666' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

06/19/18 MIRU Plugging equipment. ND well head, POH w/ 111 3/4 rods & pump. 06/20/18 Bled down well, Dug out cellar, NU BOP. Tagged 5 1/2" CIBP @ 2840'. Set 5 1/2" CIBP @ 2000'. Circulated hole w/ MLF. Pressure tested csg, held 500 psi. Spotted 25 sx class C cmt @ 2000-1750'. Spotted 25 sx class C cmt @ 850-600'. WOC. 06/21/18 Tagged plug @ 610'. Perf'd csg @ 600'. Pressured up on perfs to 800 psi. Spotted 25 sx class C cmt @ 600-350'. WOC. Tagged plug @ 350'. Perf'd csg @ 300'. Sqz'd 130 sx class C cmt @ 300' & displaced to 100'. WOC. 06/22/18 Tagged plug @ 100'. Perf'd csg @ 75'. Sqz'd 25 sx class C cmt @ 75' & circulated to surface. Rigged down & moved off. 06/26/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Verified cmt to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

Type or print name

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):