Form 3160-5 (June 2015)

#### **UNITED STATES** DEPARTMENT OF THE INTERIOR OCD Artesia **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

# 5. Lease Serial No. NMNM02862

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

-				
6.	If Indian.	Allottee	or Tribe	Name

abandoned wei	II. Use form 3160-3 (AP	D) for such p	roposals.		o. Il fidiali, Allouce of	THOC Name	
SUBMIT IN T	TRIPLICATE - Other ins	tructions on	page 2		7. If Unit or CA/Agree	ment, Name and/or No.	
Type of Well     Gas Well □ Oth		8. Well Name and No. POKER LAKE UNIT 486H					
2. Name of Operator BOPCO LP		STEPHANIE rabadue@xtoe			9. API Well No. 30-015-43639-00-X1		
3a. Address 6401 HOLIDAY HILL RD BLD MIDLAND, TX 79707	G 5 SUITE 200	3b. Phone No Ph: 432-62	. (include area code) 0-6714		10. Field and Pool or Exploratory Area CORRAL CANYON		
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description	)			11. County or Parish, S	State	
Sec 26 T24S R30E SWSW 15	50FSL 950FWL				EDDY COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF						
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Producti	on (Start/Resume)	☐ Water Shut-Off	
Notice of Intent	☐ Alter Casing	☐ Hyd	raulic Fracturing	Reclamation		■ Well Integrity	
☐ Subsequent Report	Casing Repair	□ New	Construction	☐ Recomp	lete	Other	
☐ Final Abandonment Notice	□ Change Plans	🛭 Plug	and Abandon	☐ Tempora	arily Abandon		
	☐ Convert to Injection	Plug	g Back	■ Water Disposal			
following completion of the involved testing has been completed. Final At determined that the site is ready for fit BOPCO, L.P. respectfully require the rig for a redrill.  After making connection while pick up additional drill collars a attempted to fish the BHA with	pandonment Notices must be filinal inspection.  uests to drill and abandor  drilling the 24? surface hand the hole became tigh	led only after all the Poker Landon Tole at 245?, we tat 211?. We	requirements, includ ake Unit 486H pri we racked backe had full returns a	ing reclamation for to skiddin d drill pipe to and	n, have been completed a	nd the operator has	
Top of Fish (BHA): 207? TD of Surface Hole: 245?  Accept			Accepted for r	septed for record - NMOCD AUG 0 7 2018			
This is an open hole. Conduct during drilling.	or csg was set at 90? and	d cemented. N	No water has bee	en encounter	ed DISTRICT II-	ARTESIA O.C.D.	
Contact SIM C	On Call Co	575.	341- 2	822		Acioc PHA.	
14. I hereby certify that the foregoing is	Electronic Submission #		d by the BLM Wel ent to the Carlsba		/		
	itted to AFMSS for proces	sing by DEBO			•		
Name (Printed/Typed) STEPHAN	IIE RABADUE		Title REGUL	ATORY ANA	ALYST		
Signature (Electronic S	Submission)		Date 07/25/20	018			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	SE		
Approved By	a. lines	2	Title Su	ev. Ac	ST	7.26-18 Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would enable the applicant to condu	itable title to those rights in the		Office (2	rlsha	$\mathcal{L}$		
Rule 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to ma	ke to any department or	agency of the United	

### Additional data for EC transaction #428785 that would not fit on the form

#### 32. Additional remarks, continued

Proposed Plug and Abandon Procedure:
1. Tag TOF at 207?
2. Circulate 700sx Class C 14.8ppg cement fr/207-0?.
3. Install dry hole marker, cut off WH.
4. Skid Rig.

Current WBD is attached.

## Poker Lake Unit 486H

Wolfcamp E, 2.5 Mile Lateral

County: SHL:

**Eddy** 950' FWL, 150' FSL

Sec 26, T24S, R30E

BHL:

200' FWL, 330' FSL

Sec 28, T24S, R30E



AFE# XTO ID#

1702459 996794

API # 30-015-43639 Elevation GL 3339', KB 3365' (26' AGL)

Rig:

Patterson 225 (26' KB)

Area: NM Delaw	are Water Basin	Tug. T	diologices (ea.im)
Summary	are search pasm	· · · · · · · · · · · · · · · · · · ·	T
After making a connection of drilling 24" surface hole at 2 we racked backed drill pipe pick up additional drill colla	245 ft to		8.8-8.9 FW Mud
hole became tight at 211 ft had full returns and attempt	ì		Top of Fish at 207 ft rKB
fish the BHA with no succes days. TD of surface hole is rKB and top of fish is 207 ft	ss for 5 245 ft		TD @ 245 ft rKB